





### Cement Report

Customer <i>L.D. Drilling</i>		Lease No.		Date <i>10-24-15</i>	
Lease <i>Casey</i>		Well # <i>2-7</i>		Service Receipt <i>1717 06562 4</i>	
Casing <i>8 5/8"</i>	Depth <i>3230' 2439' 400' 40'</i>	County <i>Cheyenne</i>		State <i>Ks.</i>	
Job Type <i>242 Plug</i>		Formation	Legal Description <i>7 2 37</i>		
Pipe Data			Perforating Data		Cement Data
Casing size <i>8 5/8"</i>	Tubing Size <i>4 1/2" 16.6"</i>	Shots/Ft		Lead <i>60/40 Poz 240sk</i>	
Depth <i>3230' 2439' 400' 40'</i>	Depth	From	To		
Volume	Volume	From	To	<i>1.43 3/8k 6.92 3/8k</i>	
Max Press <i>2000</i>	Max Press	From	To	Tail in	
Well Connection	Annulus Vol.	From	To		
Plug Depth <i>354'</i>	Packer Depth	From	To		
Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<i>15:00</i>					<i>On Location</i>
<i>15:10</i>					<i>Safety Meeting w/ B.E.S. employees</i>
<i>15:25</i>					<i>Rig Up</i>
<i>16:10</i>		<i>150</i>	<i>12.7 bbl slurry</i>	<i>4.5</i>	<i>Pump 1st Plug @ 3230' 50sk</i>
<i>16:25</i>			<i>42.6</i>		<i>Displace + wait on rig</i>
<i>16:50</i>		<i>150</i>	<i>25.4 bbl slurry</i>	<i>5.0</i>	<i>Pump 2nd Plug @ 2439' 100sk</i>
<i>17:05</i>			<i>28.0</i>		<i>Displace + wait on rig</i>
<i>18:45</i>					<i>Pump 3rd Plug @ 400' 50sk</i>
<i>18:50</i>					<i>Displace + wait on rig</i>
<i>20:05</i>		<i>0</i>	<i>7.6 bbl slurry</i>	<i>1.9</i>	<i>Cement Bar Hole</i>
<i>20:15</i>		<i>0</i>	<i>2.5 bbl slurry</i>	<i>1.9</i>	<i>Pump 4th Plug @ 40' 10sk</i>
<i>20:30</i>					<i>(cement to surface)</i>
					<i>Job Complete</i>
Service Units <i>78938</i>		<i>3817/1991 927808/19883</i>			
Driver Names <i>Daniel</i>		<i>Rogelio</i>		<i>Santiago</i>	

*L.D. Davis*  
Customer Representative

*Tyce Davis*  
Station Manager

*Daniel Beck*  
Cementer