

TREATMENT REPORT



HURRICANE SERVICES INC

Customer: MURFIN	Date: 6/17/2017	Ticket No.: 50994
Field Rep: DUKE		
Address:		
City, State:		
County, Zip:		

Field Order No.:		Open Hole:	7 7/8	Perf Depths (ft)	Perfs
Well Name:	YOUNGMAYER A 1-11	Casing Depth:	474		
Location:	BEAUMONT, KS	Casing Size:	8 5/8		
Formation:		Tubing Depth:			
Type of Service:	RTA	Tubing Size:			
Well Type:	OIL	Liner Depth:			
Age of Well:	NEW	Liner Size:			
Packer Type:		Liner Top:			
Packer Depth:		Liner Bottom:			
Treatment Via:	DRILL PIPE	Total Depth:			
				Total Perfs	0

TIME	INJECTION RATE		PRESSURE		REMARKS	PROP (lbs)	HCL (gls)	FLUID (bbls)
	FLUID	N2/CO2	STP	ANNULUS				
6:30 PM					ON LOACTION SAFETY MEETING SPOT IN AND RIG UP			
					BREAK CIRCULATION WITH RIG PIPE AT 3220'			
	4.0		300.0		PUMP WATER			8.50
	4.0		300.0		MIX AND PUMP CEMENT			5.00
	4.0		300.0		PUMP WATER			3.00
	10.0				PUMP MUD			37.00
					BREAK CIRCULATION WITH RIG PIPE AT 2200'			
	4.0		300.0		PUMP WATER			8.50
	4.0		300.0		MIX AND PUMP CEMENT			5.00
	4.0		300.0		PUMP WATER			3.00
	10.0				PUMP MUD			27.00
					BREAK CIRCULATION WITH RIG PIPE AT 1810			
	4.0		250.0		PUMP WATER			8.50
	4.0		250.0		MIX AND PUMP CEMENT			5.00
	4.0		250.0		PUMP WATER			3.00
	10.0				PUMP MUD			21.00
TOTAL:						-	-	181.70

SUMMARY

Max Fl. Rate	Avg Fl. Rate	Max PSI	Avg PSI
10.0	5.0	300.0	245.8

PRODUCTS USED

250 SACKS 60:40:4% GEL

Treater: JAKE HEARD

Customer: DUKE

