Geological Report

American Warrior, Inc.

Wray #1-8

1076' FNL & 1122' FWL Sec 8, T14s, R35w Logan County, Kansas



American Warrior, Inc.

General Data

Well Data:	American Warrior, Inc. Wray #1-8 1076' FNL & 1122' FWL Sec. 8, T14s, R35w Logan County, Kansas API # 15-109-21512-00-00			
Drilling Contractor:	Discovery Drilling Rig #1			
Geologist:	Luke Thompson			
Spud Date:	September 11, 2017			
Completion Date:	September 20, 2017			
Elevation	3245' G.L. 3253' K.B.			
Directions:	From the West side of Russell Springs, KS at the intersection of Hwy 25 & Broadway Ave. – Now go 0.8 miles South on Hwy 25 Rd then 2 miles West on Hwy 25 - Now go about 4 miles South on 240 Rd to Kiowa Rd – Now go West 1 mile to 230 Rd – Now go North 0.5 miles – East into			
Casing:	210' 8 5/8" #23 Surface Casing			
Samples:	3750' to RTD 10' Wet & Dry			
Drilling Time:	3700' to RTD			
Electric Logs:	Pioneer Energy Services "D. Schmidt" Full Sweep			
Drillstem Tests:	Two-Trilobite Testing "Mike Roberts"			
Problems:	Pulled Tight on all trips			

Formation Tops

Wray #1-8 Sec. 8, T14s, R35w 1076' FNL & 1122' FWL

Anhydrite	2622' +631
Base	2643' +610
Heebner	4038' -785
Lansing	4091' -838
Stark	4345' -1092
ВКС	4417' -1164
Marmaton	4461' -1208
Pawnee	4554' -1301
Fort Scott	4614' -1361
Cherokee	4642' -1389
Johnson	4689' -1436
Morrow	4762' -1509
Miss	4836' -1583
RTD	4900' -1647
LTD	4900' -1647

Sample Zone Descriptions

Marmaton (4490' -1237): Covered in DST #1

Limestone, cream, sub-crystalline, slightly chalky, occasionally oolitic, scattered poor pinpoint vuggy and oolicastic porosity, very slight fleeting odor, poor stain and saturation in 1 piece, very poor show of free oil, no fluorescence slow string cut. No Gas Kick.

Lansing K (4380' -1127): Covered in DST #2

Limestone, cream, oolitic packstone, slightly chalky, poor to fair oolicastic porosity, very faint odor, fair stain, fair to good saturation, fair show of free oil, no fluorescence, fair to good stream cut. No Gas Kick.

Drill Stem Tests

Trilobite Testing "Mike Roberts"

DST #1 Marmaton

Interval (4435' – 4510') Anchor Length 75'

IHP - 2243 #

- 30" – built to 2" IFP 48-60#

- 30" – No return ISI 1146#


FFP - 30" – WSB 62-68#

FSIP - 30" - No return 1126#

- 2214# FHP

BHT - 114° F

Recovery: 20' M



DST #2 Lansing K (straddle test)

Interval (4374' - 4384') Anchor Length 10'; Tail Pipe 126'

1267#

IHP - 2212 #

- 30" – Built to $1\frac{1}{2}$ " IFP 16-33#

- 30" – No Return ISI 1290#


- 30" – built to $1\frac{1}{2}$ " FFP

FSIP - 30" - No Return

FHP - 2124 #

BHT - 120° F

Recovery: 90' WCM



Structural Comparison

	American Warrior, Inc.	American Warrior, Inc.			American Warrior, Inc.		
	Wray #1-8		Fairchild #1-17	Ausmus Unit #1-7			
	Sec. 8, T14s, R35w		Sec. 17, T14s, R35w	Sec. 7, T14s, R35w			
Formation	1076' FNL & 1122' FWL		1506' FNL 1036' FEL		160' FSL & 792' FEL		
Heebner	4038 -785	-8	4004 -777	-12	3995	-773	
Lansing	4091 -838	-7	4058 -831	-10	4050	-828	
Stark	4345 -1092	-5	4314 -1087	-6	4308	-1086	
BKC	4417 -1164	-1	4390 -1163	4	4390	-1168	
Marmaton	4461 -1208	-3	4432 -1205	5	4435	-1213	
Pawnee	4554 -1301	-7	4521 -1294	1	4524	-1302	
Fort Scott	4614 -1361	-6	4582 -1355	3	4586	-1364	
Cherokee	4642 -1389	-6	4610 -1383	3	4614	-1392	
Johnson	4689 -1436	-6	4657 -1430	4	4662	-1440	
Morrow	4762 -1509	-8	4728 -1501	9	4740	-1518	
Miss	4836 -1583	-18	4792 -1565	9	4814	-1592	

Summary

The location for the Wray #1-8 well was found via 3-D seismic survey. The new well ran structurally as expected. Two drill stem test were conducted, none of which recovered commercial quantities of oil. After all the gathered data had been examined, the decision was made to plug and abandon the Wray #1-8 well.

Respectfully Submitted,

Lukas Thompson

American Warrior, Inc.