Customer Name SUEMAUR EXPLORATION
Well Name GODFREY 1-32
Job Type Plug & Abandon






Seq No.	Start Date/Time 11/4/2017 14:00 230PM 245PM	Mobilization Operational Operational	Arrive on Location Rig Up Safety Meeting	Equipment Cement Pump Truck Cement Pump Truck	48 50 53	Density (ib/gal)	(bpm)	(bbls)	Pipe Pressure (psi)	Comments ON LOCATION, SPOT TRUCKS RIG UP SAFETY MEETING 1ST PLUG @ 2550FT 50 SK, 10 BBL WATER, 12.7 BBL
4	255PM		1ST PLUG			13.8	w	52.7	100	15T PLUG @ 2550FT 50 SK, 10 BBL WATER , 12.7 BBL SLURRY @ 13.8# FALLOWED BY 2 BBL WATER, AND 28 BBL MUD
s	312PM									RIG CREW LAY DOWN PIPE
6										
 - 		}					'			2ND PLUG @ 1700 FT 100 SK, 25.4 BBL SLURRY AND
7	340PM		2ND PLUG			13.8	w	42.9	90	17.5 BBL DISPLACEMENT
8	355PM									RIG CREW LAY DOWN PIPE
9										
5	433844		38D MILE			100	υ	*	5	3RD PLUG @ 350 FT, 50SK, 12.7 BBL SLURRY @ 13.8#
11										LAY DOWN PIPE
12										
12	MADES	i	ATH DILIG		-	13.8	J	2.51	Š	4TH PLUG FROM 40 FT TO SURFACE, 10 SK, 2.5 BBL
14										
										RAT & MOUSE HOLES, 45 SK, 11.4 BBL SLURRY @
15	S40PM		RAT & MOUSE PLUG			13.8		11.4	c	13.8#
17	550PM		WASH							WASH PIMPING LINES TO PIT
18	600PM		RIG DOWN		73					RIG DOWN
19	700PM									LEAVE LOCATION
20										THANKS
21										
22										
23					STATE OF THE PARTY					



Customer:	SUEMAUR EXPLORATION		
Date:	Saturday, November 04, 2017		
Well Name:	GODFREY # 1-32		
Well Location:	HOXIE		
Supervisor:	Aldo Espinosa		
Equipment Operators:	ALDO ESPINOZA - CRISTIAN CAMACHO - GERARDO BURCIAGA		
	Performance		Customer
Was the appearance of	the personnel and equipment satisfactory?	Yes	No
Was the job performed	in a professional manner?	Yes	No No
Were the calculations p	repared and explained properly?	Yes	No
Were the correct servic	es dispatched to the job site?	Ye	No
Were the services perfo	ormed as requested?	Yes	No
Did the job site environ	ment remain unchanged?	Yes	s) No
Did the equipment perf	orm in the manner expected?	Yes	No
Did the materials meet	your expectations?	Yes	No
Was the crew prepared	for the job?	Yes	No
Was the crew prompt in	n the rig-up and actual job?	Yes	No
Were reasonable recon	nmendations given, as requested?	Yes	No No
Did the crew perform sa	afely?	Yes	No
Was the job performed	to your satisfaction?	Yes	No No
Customer Signature:		Date:	·· · · •
Additional Comments:		<u> </u>	
			
			-
	6		





CEMENT MIXING WATER GUIDELINES

Company Name:	SUEN	AUR EXPLO	DRATION
Lease Name:		GODFREY # 1-	32
County	SHERIDAN	State	KS
Water Source:		TANK	
Submitted By:		Date:	11/4/2017
pH Level	7	·	Must be less than 8.5
Sulfates	400		Must be less than 1,000 PPM
Chlorides	0		Must be less than 3,000 PPM
Temperature	64		
COMMENTS			

Customer Signature B

Thank You