

<b>Operator License #:</b> 35122	<b>API #:</b> 15-205-28399-00-00
<b>Operator:</b> Lakeshore Operating, LLC	<b>Lease:</b> Bacon
<b>Address:</b> 23 ½ E Madison Ste A Iola, KS 66749	<b>Well #:</b> LO-16
<b>Phone:</b> (844) 557-4673	<b>Spud Date:</b> 08/14/17 <b>Completed:</b> 08/16/17
<b>Contractor License:</b> 34036	<b>Location:</b> NE-NW-SW-NE of 7-30S-16E
<b>T.D. :</b> 935 <b>T.D. of Pipe:</b> 930	3749 <b>Feet From</b> South
<b>Surface Pipe Size:</b> 7" <b>Depth:</b> 32'	2014 <b>Feet From</b> East
<b>Kind of Well:</b> Oil	<b>County:</b> Wilson

# LOG

Thickness	Strata	From	To	Thickness	Strata	From	To
17	Soil/Clay	0	17	7	Broken Oil Sand	823	830
8	Sand/Gravel	17	25	6	Oil Sand	830	836
50	White Sand	25	75	29	Shale	836	865
3	Coal Streaks	75	78	9	Broken Oil Sand	865	874
43	Shale	78	121	20	Shale	874	894
16	Lime	121	137	8	Oil Sand	894	902
8	Shale	137	145	4	Very Broken Oil	902	906
68	Shale	145	213	29	Shale	906	935
36	Sandy Shale	213	249				
19	Shale	249	268				
17	Lime	268	285				
42	Shale	285	327				
14	Lime	327	341				
69	Shale	341	410				
8	Lime	410	418				
5	Shale	418	423				
14	Lime	423	437				
104	Shale	437	541				
40	Lime	541	581				
43	Shale	581	624				
21	Lime	624	645				
11	Shale/Black Shale	645	656				
8	Lime	656	664				
6	Shale/Black Shale	664	670				
4	Lime	670	674				
143	Shale	674	817				
3	Broken Oil Sand	817	820				
3	Oil Sand	820	823				

