

TREATMENT REPORT



HURRICANE SERVICES INC

Customer:	McCoy Pet.	Date:	3/28/2018	Ticket No.:	100898
Field Rep:	Lanny Saloga				
Address:					
City, State:					
County, Zip:					

Field Order No.:	100898	Open Hole:		Perf Depths (ft)	Perfs
Well Name:	Mack A 1-1	Casing Depth:			
Location:	Montezuma	Casing Size:			
Formation:		Tubing Depth:	6312'		
Type of Service:	Plug Job	Tubing Size:	4.5 16>6 LB		
Well Type:	Oi	Liner Depth:			
Age of Well:	New	Liner Size:			
Packer Type:		Liner Top:			
Packer Depth:		Liner Bottom:			
Treatment Via:	Drill Pipe	Total Depth:			
				Total Perfs	0

TIME	INJECTION RATE		PRESSURE		REMARKS	PROP (lbs)	HCL (gls)	FLUID (bbls)
	FLUID	N2/CO2	STP	ANNULUS				
3:00 PM					Called Out			
7:00 PM					On Location W/Trucks			
					Hold Safety Meeting Spot & Set Up Trucks			
					1 St Plug @ 6312' 50 Sk 60/40 4% Gel			
11:10 PM	6.0		620.0		Start Pumping H2O			20.00
11:16 PM	5.0		670.0		Start Mix & Pump 50 sk			12.65
11:20 PM	5.0		400.0		Start Displacement H2O			7.00
11:23 PM	8.7		800.0		Start Displacement Mud W/Rig			79.50
11:31 PM					Shut Down PDPOOH			
					2 nd Plug @ 1800' 50 Sk 60/40 4% Gel			
2:15 AM	5.0		250.0		Start Pumping H2O			20.00
2:19 AM	4.4		220.0		Start Mix & Pump 50 sk			12.65
2:20 AM	4.4		110.0		Start Displacement			6.50
2:27 AM	8.7		220.0		Start Displacement Mud W/Rig			16.00
2:29 AM					Shut Down PDPOOH			
					3 Rd Plug @ 730' 40 Sk 60/40 4% Gel			
3:00 AM	5.0		190.0		Start Pumping H2O			20.00
3:03 AM	4.5		190.0		Start Mix & Pump 40 sk			10.12
TOTAL:						-	-	229.83

SUMMARY

Max Fl. Rate	Avg Fl. Rate	Max PSI	Avg PSI
8.7	4.9	800.0	288.6

PRODUCTS USED

210 Sacks 60/40 4% Gel

Treater: Todd Seba

Customer: Lanny Saloga

