Quality Well Service, Inc.

PO Box 468 Pratt, KS 67124

Invoice

Date	Invoice #
12/10/2018	2078

Bill To	
Trek AEC, LLC 4925 Greenville Ave, Ste.915 Dallas, TX 75206	

	P.O. No.	Terms	1	ease Name
·			Z-B:	ar Ranch #17-1A
Description		Qty	Rate	Amount
Rig Time		24	180.00	4,320.001 250.007
Floor Rental		1	250.00	
Rip Casing		2	600.00	1,200.007
Welding		4	75.00	300.007
Water Truck		6	90.00	540.007
Phone Calls	İ	1	20.00	20.007
Clerical		1	25.00	25.007
Fresh Water	1	2	30.00	60.007
Wiping Rubber	i	1	20.00	20.001
Wood lay down	İ	1	30.00	30.007
Z-Bar Ranch #17-1A				
Barber Co.		, i		
11/27/18:		1		
Drove to location, raised pole, changed over to pull rods, drove home.				
11/28/18:				
Drove to location, pulled rods, changed over for tubing, moved pumping home.	unit, drove			
11/29/18:				
Drove to location, pulled tubing, dug cellar and pit, unpacked casing hea	d, set floor, drove		•	
home.				
12/3/18:		1		
				•
Thank You for your business & Happy Holidays!		Subtotal		
	·	Jubiotal	····	
		Sales Ta	x (7.5%)	
		Total	***************************************	

Quality Well Service, Inc.

PO Box 468 Pratt, KS 67124

Invoice

Date	Invoice #
12/10/2018	2078

Bill To	-
Trek AEC, LLC 4925 Greenville Ave, Ste.915 Dallas, TX 75206	

	P.O. No.	Terms	Le	ase Name
			Z-Bar	Ranch #17-1A
Description		Qty	Rate	Amount
Drove to location, pumped 25 sacks cement, 100# hulls, displaced to 4 1000 psi, couldn't get slips out of casing head, had to split casing head casing at 2640' and 2440', came free, swedged in, drove home. 12/4/18: Drove to location, pulled casing to 930', pumped 10 sacks gel, 50 sack casing to 360', pumped 40 sacks cement, circulated to surface, tore do emptied pit, back filled cellar and pit.	in two, ripped			
Thank You for your business & Happy Holidays!	.	Subtotal	__	\$6,765.
		Sales Ta	x (7.5%)	\$507.
		Total		\$7,272.

Quality Well Service, Inc.

PO Box 468 Pratt, KS 67124

Invoice

Date	Invoice #
12/10/2018	C-1915

Bill To	· ,
Trek AEC, LLC 4925 Greenville Ave, Ste.915 Dallas, TX 75206	

	P.O. No.	Terms	Lea	se Name
			Z-Bar l	Ranch #17-1A
Description		Qty	Rate	Amount
Common		105	15.50	1,627.50
Poz		50	9.50	475.00
Gel		15	22.00	330.00
Calcium		2	60.00	120.00
Hulls .		1	45.00	45.00
Plug/Pumped Bottom	1	1	950.00	950.00
2nd day Pump Truck		1	500.00	500.00
Handling		174	2,10	365.40
.08 * sacks * miles		8,700	0.08	696.00
Service Supervisor		1	150.00	150.00
LMV		50	3.75	187.50
		100	8.00	800.00
Heavy Equipment Mileage		100	-1,873.92	-1,873.92
Customer Discount			0.00	0.00
Discount Expires after 30 days from the date of the invoice			0.00	0.00
Z-Bar Ranch 17-1A				
Barber Co.				
• •				
· ·				
•				
			1	
5 A A			1	
Thank You for your business & Happy Holidays!		<u> </u>		
		Subtotal		\$4,372.48
		Sales Tax	(7.5%)	\$327.94
	-	Total		\$4,700.42

QUALITY WELL SERVICE, INC. Federal Tax I.D. # 481187368

Home Office 30060 N. Hwy 281, Pratt, KS 67124

Mailing Address P.O. Box 468

Office 620-727-3410 Fax 620-672-3663

Rich's Cell 620-727-3409 Brady's Cell 620-727-6964

12-3-18	Sec.	Twp.	Range	4	County	State	On Location	Finish		
Date 12 - 4-18	17	34	14	Bo	uber	KS				
Lease Z-Box Ranch	W	ell No.	17-1-A.	Locati	on					
Contractor Quality	W.	e ll	Service		Owner		•			
Type Job PT/A.	Pmod	<u>ි</u> යිං	itton		To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish					
Hole Size		T.D.			cementer and helper to assist owner or contractor to do work as listed.					
csg. 4,5		Depth			Charge T	rek AEC				
Tbg. Size		Depth			Street					
Tool	Depth			City State						
Cement Left in Csg.	Shoe Jo	int		The above was done to satisfaction and supervision of owner agent or cont						
Meas Line	Ī	Displace	3		Cement Amount Ordered 19654 60140 - 255K					
E	QUIPM	ENT			1	rel on side				
Pumptrk & No.					Common IC					
Bulktrk 10 No.					Poz. Mix 50	5	i			
Bulktrk No.					Gel./ ₅ 5					
Pickup No.					Calcium 2					
JOB SERVICES & REMARKS					Hulls 100	#				
Rat Hole					Salt					
Mouse Hole					Flowseal					
Centralizers			······································		Kol-Seal					
Baskets	·				Mud CLR 48					
D/V or Port Collar	L-3-I	8 .			CFL-117 or CD110 CAF 38					
1st Hooked up	to	4.5	CS9 DUMA	ره	Sand					
	_ നേര	2	mt hu		Handling 174					
	302+			D'asi	Mileage 50					
T. 1a	-4-1			,	FLOAT EQUIPMENT					
Ist Pumper) 10sx	ı Ge	1 50	Sx 60/4	-Q-	Guide Shoe					
fr 601 20 9	330				Centralizer					
•					Baskets					
no. Pundier) -40	ンこく	601	40 4°6	Gel	AFU Inserts					
£ 360'					Float Shoe					
· · · · · · · · · · · · · · · · · · ·					Latch Down					
12 Auped 40sx 60/40 426					LMV 5	Ò				
Gol 60'	40	_	face		Service	Supervisies				
					Pumptrk Char	/	imped Botter	M. 2nd Day Augo		
					Mileage ()(•			
						****	Tax			
							Discount			
X Signature		······································					Total Charge			
-				<u>_</u>				Taylor Printing, Inc.		



Daily Workover Report

Well:	Z Bar Ran	ich #1-17		_	Report #:	1	_	Date:	28-Nov-18
Location:				-	AFE:		•	Daily \$:	0
Rig:	Quality W	ell Service		_	KB:	1,623	•	Cum \$:	0
Supv:	Tanner Ne	elson			GL:	1,610		AFE \$:	0
Next Pla	inned					Swab_	Wellbore		Material
Operation						Report	Diagram	Pipe Tally	Transfer
								<u></u> _	<u>Transion</u>
From	То	Hrs:Min				Operations	Report		
	ļ	ļ			rvice. Plug	well.			
	<u></u>	-	POOH as 1						· -··
		<u> </u>			rod. 1 1/2" b	ronze liner.			
		<u> </u>		2',2',4',4',4',6 x 25' sucke					
		-	1 - 3/4" x 2		100	 			
	 	ļ	1 - 3/4 X 2	/2" x 12' ins	sort numn				
			RUET TO	OH as follo	ws: (11/29/1	8)			
				3/8" 8RD tu		<u> </u>			
· · · ·			1 - 2" seati		ibirig				
					d cement in	cellar. No	records of r	revious sa	leeze.
	 			casing jack			000,000,00	,, o 1, o a a a q	
	"			<u> </u>				-	
			SDFN.						
									•
					. <u>.</u>				
		ļ							
		-							
To	tal	0:00							
		<u> </u>							
	ost Estim	ate	Daily \$	Cum \$	AFE \$		Com	ments	
9561 Pulling			0	0				····	
9579 Superv	rision		0	0					
			0	0	1				
			0	0					
			0	0				····.	
			0	0	-				
			0	0				······································	
	•		0	0					
			0	0					
	-		0	0					
		3	0	0					
		1	0	0					
			0	0		· · · · · · · · · · · · · · · · · · ·			•
			0	0					
			0	0					
Total			0	0	0 1				



Daily Workover Report

Well:	Z Bar Ran	ich #1-17			Report #:	2	Date:	3-Dec-18
Location:				-	AFE:		Daily \$:	0
Rig:	Quality We		· · · · · ·	M	KB:	1,623	Cum \$:	0
Supv:	Tanner Ne			-	GL:	1,610	AFE \$:	0
Next Pla								_ , , ,
							Pipe Tally	<u>Material</u>
Operation	วท:	l						<u>Transfer</u>
From	. To	Hrs:Min			Detail	Operations Repor	t	
				ocation. Sta	arted rig.			
		<u></u>		4 1/2" casin				
		ļ				s A cement. 100# I	nulls.	
					psi. Shut ir			
	<u> </u>	<u> </u>			it. Bled pres			
		<u> </u>			igged cemei		44	
	 	<u> </u>				casing free. Could	n't.	
	 	 		casing supp		00' of fron ping		
	 	 				00' of free pipe. Ripped casing @ 24	450'	
	 	 	SDFN.	Mulli le casi	ng culter. r	Alphen casing @ 2.	450	
		 	SDEW.					
	 	 	 					
	 	 	 					
			<u> </u>					
	 	1	 					<u>, </u>
		†				•		
				M. 1_ 1-2-2-2			-	
	!							
	<u> </u>		<u> </u>					
	<u> </u>							
	<u> </u>	1	<u> </u>					
	otal	0:00						
	ost Estim	ıate	Daily \$	Cum \$	AFE \$	С	omments	
9561 Pulling				0	0			
9579 Super	<u>rision</u>			0	0			
0			<u> </u>	0	0	 		
<u> </u>			<u> </u>	0	0			
)			<u> </u>	0	0			
) -			-	0	0			
<u>, </u>			 	0	0			
<u>, </u>			<u> </u>	0	0			
<u>, </u>			-	0	0			
) h			+	0	0			
) 1			1	0	0			
, 1				0	0			
<u>, </u>				0	0			
<u> </u>				0	0			
)			-	0	0			
Total			1 0	O	0			



Daily Workover Report

AEC,LLC								
Well:	Z Bar Rar	nch #1-17			Report #:	3	Date: 4-Dec-18	
Location:		,		_	AFE:	Daily \$: 0		
Rig:		'ell Service		-	KB:	1,623	Cum \$: 0	
Supv:	Tanner N			-	GL:	1,610	AFE \$: 0	
Next Pla	anned						Ding Tally Material	
Operation	on:						Pipe Tally Transfer	
		1 11 12						
From	То	Hrs:Min						
		 	Drove to location. Started rig. KCC rep Eric on location.					
	 	-	TOOH with 4 1/2" 10.5# casing.					
	 		Pulled to 930'					
	 	 	Tied on to	ed on to casing. Pumped gel spacer and 40 sx 60/40 cement.				
	Circulated fluid to surface.							
	 	 	Pulled to 360'					
	+	<u> </u>	Tied on to casing. Pumped 40 sx 60/40 cement.					
	 		Circulated cement to surface.					
	+	 	Pulled all 4 1/2" casing out of hole.					
	1		Capped well off with 40 sx 60/40 cement					
	 		<u> </u>				(2) to 2442 (2) (2	
	 	1	RDMO Quality Well Service					
		 	RDMO Quality Well Service					
		1	Recovered 71 jts 4 1/2" 10.5# casing (good/fair condition)					
	 	Trecovered 71 jts 4 1/2 10.5# casing (good/fair condition)						
		 	· · · · · · · · · · · · · · · · · · ·					
		 						
		1					· · · · · · · · · · · · · · · · · · ·	
		+						
			1			-		
···		<u></u>	-					
	 					· · · · · · · · · · · · · · · · · · ·		
T	otal	0:00						
				1 .				
Cost Estimate			Daily \$	Cum \$	AFE \$		Comments	
9561 Pulling Unit / Rig				0	0			
9579 Supervision				0	0			
0				0	0			
0				0	0			
0				0	0			
0				0	0			
0				0	0			
0				0	0			
0				0	0			
0				0	0		(8) 80 90 11	
0				0	0			
0				0	0			
0				0	0			
0				0	0			
0			0	0	0			
0				0	0			
Total			0	0	0			