

Operation:

Test Complete

Company: Raydon Exploration, SEC: 27 TWN: 338

Inc

Lease: Rock #2-27

SEC: 27 TWN: 33S RNG: 31W

State: Kansas

Drilling Contractor: Quest Drilling

Services, LLC - Rig 102 Elevation: 2733 GL Field Name: Kismet Pool: WILDCAT Job Number: 386

API#: 15-175-22271-00-00

DATE September

30 2019 **DST #1**

Formation: Morrow/Chester Test Interval: 5702 -


Total Depth: 5730'

5730'

Time On: 05:44 09/30

Time Off: 13:21 09/30

Time On Bottom: 00:00 01/01 Time Off Bottom: 00:00 01/01





Operation: **Test Complete**

Company: Raydon Exploration, County: SEWARD

Inc

Lease: Rock #2-27

SEC: 27 TWN: 33S RNG: 31W

State: Kansas

Drilling Contractor: Quest Drilling Services, LLC - Rig 102

Elevation: 2733 GL Field Name: Kismet Pool: WILDCAT Job Number: 386

API#: 15-175-22271-00-00

DATE September

> 30 2019

DST #1

Formation: Morrow/Chester Test Interval: 5702 -

Total Depth: 5730'

5730'

Time On: 05:44 09/30

Time Off: 13:21 09/30

Time On Bottom: 00:00 01/01 Time Off Bottom: 00:00 01/01

Recovered

Foot 1635

BBLS 19.974034 Description of Fluid M

Gas %

0

Oil % Water % 0


Mud % 100

Total Recovered: 1635 ft

Total Barrels Recovered: 19.974034

Reversed Out

Recovery at a glance





Operation: Test Complete

Company: Raydon Exploration, SEC: 27 TWN: 338 County: SEWARD

Inc

Lease: Rock #2-27

SEC: 27 TWN: 33S RNG: 31W

State: Kansas

Drilling Contractor: Quest Drilling

Services, LLC - Rig 102 Elevation: 2733 GL Field Name: Kismet Pool: WILDCAT Job Number: 386

API#: 15-175-22271-00-00

DATE

September

30 2019 **DST #1**

Formation: Morrow/Chester Test Interval: 5702 -

Total Depth: 5730'

5730'

Time On: 05:44 09/30

Time Off: 13:21 09/30

Time On Bottom: 00:00 01/01 Time Off Bottom: 00:00 01/01

BUCKET MEASUREMENT:

1st Open: N/A 1st Close: N/A 2nd Open: N/A 2nd Close: N/A

REMARKS:

PACKER FAILURE!

Tool Sample: 0% Gas 0% Oil 0% Water 100% Mud



Operation: **Test Complete**

Company: Raydon Exploration, SEC: 27 TWN: 338 County: SEWARD

Inc

Lease: Rock #2-27

SEC: 27 TWN: 33S RNG: 31W

State: Kansas

Drilling Contractor: Quest Drilling

Services, LLC - Rig 102 Elevation: 2733 GL Field Name: Kismet

Pool: WILDCAT Job Number: 386

API#: 15-175-22271-00-00

DATE

September 30

2019

DST #1

Formation: Morrow/Chester Test Interval: 5702 -

Total Depth: 5730'

5730'

Time On: 05:44 09/30

Time Off: 13:21 09/30

Time On Bottom: 00:00 01/01 Time Off Bottom: 00:00 01/01

Down Hole Makeup

Heads Up:

9.5300000000003 FT

Packer 1:

5696.5 FT

Drill Pipe:

Packer 2:

5702 FT

ID-3 1/2

5324.86 FT

Top Recorder:

5685.92 FT

Weight Pipe:

0 FT

ID-2 7/8

Bottom Recorder:

5704 FT

Well Bore Size:

7 7/8

Collars: ID-2 1/4

Surface Choke:

1"

Test Tool:

34.07 FT

353.60 FT

Bottom Choke:

5/8"

ID-3 1/2-FH

Jars

Safety Joint

Total Anchor:

28

Anchor Makeup

Packer Sub:

1FT

Perforations: (top):

0 FT

4 1/2-FH

Change Over:

0 FT

Drill Pipe: (in anchor):

0 FT

ID-3 1/2

Change Over:

0 FT

Perforations: (below):

27 FT

4 1/2-FH



Operation:

Test Complete

Company: Raydon Exploration, SEC: 27 TWN: 338 County: SEWARD

Inc

Lease: Rock #2-27

SEC: 27 TWN: 33S RNG: 31W

State: Kansas

Drilling Contractor: Quest Drilling

Services, LLC - Rig 102 Elevation: 2733 GL Field Name: Kismet Pool: WILDCAT Job Number: 386

API#: 15-175-22271-00-00

DATE

September 30 2019

DST #1

Formation: Morrow/Chester Test Interval: 5702 -

Total Depth: 5730'

5730'

Time On: 05:44 09/30

Time Off: 13:21 09/30

Time On Bottom: 00:00 01/01 Time Off Bottom: 00:00 01/01

Mud Properties

Mud Type: Chemical

Weight: 8.9

Viscosity: 50

Filtrate: 6.0

Chlorides: 2,000 ppm