KOLAR Document ID: 1511280

Kansas Corporation Commission Oil & Gas Conservation Division

Form U-7 August 2019

CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recovery: KCC District No.:	API No.:	Permit No.:
Operator License No.: Name:	s	ec Twp S. R
Address 1:		Feet from North / South Line of Section
Address 2:		Feet from East / West Line of Section
City: State: Zip: +	Lease:	Well No.:
Contact Person: Phone: ()		
Well Construction Details: New well Existing well with chang	es to construction Fyisting w	rell with no changes to construcion
	imum Injection Rate:	
,	nediate Production	Liner Tubing
	rioduction rioduction	•
Size:		Size:
Set at:		Set at:
Sacks of Cement:		Type:
Cement Top:		
Cement Bottom:		
Packer Type:		Set at:
DV Tool Port Collar Depth of: feet with	sacks of cement TD (and	plug back): feet de
Zone of Injection Formation: Top Fee	t: Bottom Fe	eet: Perf. or Open Hole:
Is there a Chemical Sealant or a Mechanical Casing patch in the annula	r space? Yes No	
GPS Location: Datum: NAD27 NAD83 WGS84 L	FIELD DATA _at: Long:	Date Acquired:
MIT Type:	MIT Rea	ason:
Time in Minute(s):		
Pressures: Set up 1		
Set up 2		
Set up 3		
Tested: Casing or Casing - Tubing Annulus System F	Pressure during test:	Bbls. to load annulus:
Test Date: Using:		Company's Equipme
The zone tested for this well is between feet and	feet.	
The test results were verified by operator's representative:		
Name:	Title:	Phone: ()
		, , , , , , , , , , , , , , , , , , ,
KCC Office Use Only State Agent:	Title:	Witness: Yes N
The results were: Remarks:		
Satisfactory		
Not Satisfactory		
Next MIT:		
I VEAL IVII I.		

Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720



Phone: 620-902-6450 http://kcc.ks.gov/

Laura Kelly, Governor

Susan K. Duffy, Chair Shari Feist Albrecht, Commissioner Dwight D. Keen, Commissioner

FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

04/08/2020

LICENSE 34350 Altavista Energy, Inc. 4595 K-33 HIGHWAY PO BOX 128 WELLSVILLE, KS 66092-0128

Re: API No. 15-207-26682-00-00 Permit No. E12706.114 RILEY PW-5 35-23S-16E Woodson County, KS

Operator:

On 03/27/2020, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

- 1) repair and retest the well to show mechanical integrity,
- 2) plug the well, or
- 3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

Failure to comply with K.A.R. 82-3-407(c) by 06/25/2020 shall be punishable by a \$1,000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerly,

Duane Sims KCC District #3