## KOLAR Document ID: 1536874

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recovery: KCC District No.: \_\_\_\_ API No.: Permit No.: \_\_\_\_\_ - \_\_\_\_ Sec. \_\_\_\_ Twp. \_\_\_\_ S. R. \_\_\_\_ East West Operator License No.: \_\_\_\_\_ Name: \_\_\_ \_\_\_ Feet from North / South Line of Section Address 1: \_\_ \_\_\_\_\_Feet from East / West Line of Section Address 2: State: Zip: + Lease: Well No.: City: Contact Person: \_\_\_\_ \_\_\_\_\_ Phone: ( \_\_\_\_\_ ) \_\_\_\_\_ County: \_\_\_\_ Well Construction Details: New well Existing well with changes to construction Existing well with no changes to construction Maximum Authorized Injection Pressure: \_ \_\_\_ psi Maximum Injection Rate: \_ bbl/d Conductor Surface Intermediate Production Liner Tubing Size: Size: Set at: Set at: Sacks of Cement: Type: Cement Top: Cement Bottom: Packer Type: Set at: \_\_\_ DV Tool Port Collar Depth of: \_\_\_\_\_ feet with \_\_\_\_\_ sacks of cement TD (and plug back): \_\_\_\_ \_\_\_\_\_ feet depth Zone of Injection Formation: \_\_\_\_\_ Top Feet: \_\_\_\_ \_ Bottom Feet: \_\_\_\_\_ Perf. or Open Hole: \_\_\_ Is there a Chemical Sealant or a Mechanical Casing patch in the annular space? Yes No If Dual Completion - Injection is: Above Production Below Production FIELD DATA Date Acquired: GPS Location: Datum: NAD27 NAD83 WGS84 Lat: Long: MIT Reason: MIT Type: \_ Time in Minute(s): Pressures: Set up 1 Set up 2 Set up 3 or Casing - Tubing Annulus System Pressure during test: \_\_\_\_\_ Bbls. to load annulus: \_\_ Tested: Casing Using: \_\_\_\_\_ Test Date: Company's Equipment The zone tested for this well is between \_\_\_\_\_\_ feet and \_\_\_\_\_\_ feet. The test results were verified by operator's representative: \_\_\_\_ Title: \_\_\_\_\_ Phone: (\_\_\_\_) \_\_\_\_\_ Name: \_ Witness: Yes No \_\_\_\_\_ Title: \_\_\_\_\_ **KCC Office Use Only** State Agent: \_\_\_\_ The results were: Remarks: Satisfactory Not Satisfactory Next MIT:

Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720

Susan K. Duffy, Chair Dwight D. Keen, Commissioner Andrew J. French, Commissioner



Phone: 620-902-6450 http://kcc.ks.gov/

Laura Kelly, Governor

## FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

12/23/2020

LICENSE 33640 Haas Petroleum, LLC PO BOX 8396 PRAIRIE VILLAGE, KS 66208-1936

Re: API No. 15-073-01742-00-00 Permit No. D16079.0 GRIBLIN B 10 21-23S-13E Greenwood County, KS

Operator:

On 11/20/2020, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

1) repair and retest the well to show mechanical integrity,

2) plug the well, or

3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

## Failure to comply with K.A.R. 82-3-407(c) by 02/18/2021 shall be punishable by a \$1, 000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Duane Sims KCC District #3