KOLAR Document ID: 1540620

Kansas Corporation Commission Oil & Gas Conservation Division

Form U-7 August 2019

CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recovery: KCC District No.:			API No.: Permit No.:			
Operator License No.:	 Name:		Se	c Twp	S. R	East West
Address 1:				Feet from	North / Sout	h Line of Section
Address 2:				Feet from	East / Wes	t Line of Section
City:	State: Zip:	+	Lease:		Wel	No.:
Contact Person:	·		County:			
Well Construction Details:	New well Fxistin	g well with changes to cons	struction	Il with no change	es to construcion	
Maximum Authorized Injecti				· ·		
Condi		Intermediate	Production	Liner		Tubing
Size:					Size:	
Set at:					Set at:	
Sacks of Cement:					Type:	
Cement Top:						
Cement Bottom:						
DV Tool Port Coll	ar Depth of:	feet with sac	ks of cement TD (and p	lug back):		feet depth
Zone of Injection Formation	on:	Top Feet:	Bottom Fee	t:	Perf. or Open Hol	e:
s there a Chemical Sealant	or a Mechanical Casing pa	atch in the annular space?	Yes No			
	NAD27 NAD83		Long: MIT Reas	200:	Date Acquired:	
MIT Type:			Will Reas	SOII		
Time in Minute(s):						
Pressures: Set up 1						
Set up 2						
Set up 3						
Tested: Casing	or Casing - Tubing Annu	ulus System Pressure o	luring test:	Bbl	s. to load annulus:	
Test Date:	Using: _				Con	npany's Equipment
The zone tested for this well	is between fe	eet and feet.				
The test results were verified	l by operator's representativ	/e:				
Name:		Title:		Phone:	()	
KCC Office Use Only	State Agent:	•	Title:		Witness:	Yes No
The results were:	Remarks:					
Satisfactory						
Not Satisfactory						
Next MIT:						
·						
l						
	1					

Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720



Phone: 620-902-6450 http://kcc.ks.gov/

Laura Kelly, Governor

Andrew J. French, Chairman Dwight D. Keen, Commissioner Susan K. Duffy, Commissioner

FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

02/01/2021

LICENSE 30944 Thyer, Joe dba D & T Oil Company 7040 KS HIGHWAY 7 MOUND CITY, KS 66056-5330

Re: API No. 15-011-20923-00-01 Permit No. E20542.12 MARGRAVE 3 81 2-24S-21E Bourbon County, KS

Operator:

On 01/11/2021, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

- 1) repair and retest the well to show mechanical integrity,
- 2) plug the well, or
- 3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

Failure to comply with K.A.R. 82-3-407(c) by 04/11/2021 shall be punishable by a \$1,000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Duane Sims KCC District #3