KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
May 2011
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: Landmark Resources, Inc.
License Number: 6113
Operator Address: 4900 WOODWAY DRIVE SUITE 880 Houston TX 77056 1881
Contact Person: Bill Schmidt
Phone Number: (316) 772 - 0921
Permit Number *(API No. if applicable)*: 15-171-21004-00-00
Lease Name: KREBS
Well Number: 1-5

Source of Waste:

- [ ] Emergency Pit
- [ ] Settling Pit
- [x] Workover Pit
- [ ] Drilling Pit
- [ ] Burn Pit
- [ ] Haul-off Pit
- [ ] Steel Pit
- [ ] Spill / Escape
- [ ] Dike

Source Location (QQQQ): SW - SW - SE - SW
Sec. 5 Twp. 17 R. 33 [ ] East [x] West
156 Feet from [ ] North / [x] South Line of Section
3858 Feet from [x] East / [ ] West Line of Section
GPS Location: Lat: _____ *(e.g. xx.xxxxx)*, Long: _____ *(e.g. -xxx.xxxxx)*
Datum: [ ] NAD27 [ ] NAD83 [ ] WGS84
County: Scott

No Waste to be Hauled: [x] *(If checked, provide an explanation as to why no waste was hauled in the Comments area.)*

Type of waste to be disposed: [ ] Fluid [ ] Soil [ ] Mud / Cuttings [ ] Other: _____

Amount of waste: _____ No. of loads _____ Barrels _____ Tons _____ YDS

Destination of waste: [ ] Reserve Pit [ ] Haul Off Pit [ ] Disposal Well [ ] Lease Road [ ] Dike / Berm [ ] Other: _____

If waste is transferred to another reserve pit, is the lease active? [ ] Yes [ ] No

Location of Waste Disposal:

Destination Out of State: [ ] *(If checked, provide the location of where the waste was hauled in the Comments area.)*

Date of Waste Transfer: _____

Operator Name: _____ License No.: _____

Lease Name: _____ Sec. _____ Twp. _____ R. _____ [ ] East [ ] West

Docket No./API No.: _____ County: _____

Comments:

Approximately 1/2 bbl cement was hauled to pit during cementing, and approximately 20 bbl clean up water from pump truck was taken to pit. Fluid was approximately 90% absorbed over night, and only wet dirt remained in pit after 48 hrs.

Submitted Electronically