## KOLAR Document ID: 1669833

Form U-7 August 2019

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Re	ecovery: KCC Distric	et No.:	API No.:		Permit No.:
Operator License No.: Name:					
Address 1:				·	North / South Line of Section
Address 2:					
City: State: Zip:+				Well No.:	
Contact Person: Phone: ( )					
Well Construction Details:	New well Existing	g well with changes to con	struction Existing w	vell with no change	s to construcion
Maximum Authorized Injection	on Pressure:	psi Maximum Inje	ection Rate:	bbl/d	
Condu	ictor Surface	Intermediate	Production	Liner	Tubing
Size:					Size:
Set at:					Set at:
Sacks of Cement:					Туре:
Cement Top:					
Cement Bottom:					
Packer Type:				Set at:	
	ar Depth of:	feet with sad	cks of cement TD (and	plug back):	feet dept
Zone of Injection Formatio			Υ.	,	_ Perf. or Open Hole:
Is there a Chemical Sealant					_ · ···· · · · · · · · · · · · · · · ·
GPS Location: Datum:	NAD27 NAD83		-		Date Acquired:
МІТ Туре:			MIT Re	ason:	
Time in Minute(s):					
Pressures: Set up 1					
Set up 2					
Set up 3					
Tested: Casing	or Casing - Tubing Annu	Ilus System Pressure	during test:	Bbls	. to load annulus:
Test Date:	Using:				Company's Equipmen
The zone tested for this well	is between fe	et and feet			
The test results were verified	by operator's representative	e:			
Name:		Title:		Phone: (	)
KCC Office Use Only	State Agent:	•	Title:		Witness: Yes No
The results were:	Remarks:				
Satisfactory					
Not Satisfactory					
Next MIT:					
	1				

Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720

Dwight D. Keen, Chair Susan K. Duffy, Commissioner Andrew J. French, Commissioner



Phone: 620-902-6450 http://kcc.ks.gov/

Laura Kelly, Governor

## FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

10/27/2022

LICENSE 31473 BG-5, Inc. 3939 ELLIS RD RANTOUL, KS 66079-9090

Re: API No. 15-059-26170-00-00 Permit No. E31342.11 THOELE SOUTH BSI-TS16 29-18S-21E Franklin County, KS

Operator:

On 10/21/2022, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

1) repair and retest the well to show mechanical integrity,

2) plug the well, or

3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

## Failure to comply with K.A.R. 82-3-407(c) by 10/31/2022 shall be punishable by a \$1, 000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Duane Sims KCC District #3