KOLAR Document ID: 1694775

Kansas Corporation Commission Oil & Gas Conservation Division

Form U-7 August 2019

CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recovery: KCC District No.:	API No.:	Permit	No.:
Operator License No.: Name:		ec Twp S. R	East West
Address 1:		Feet from North /	South Line of Section
Address 2:		Feet from East /	West Line of Section
City: State: Zip:+_	Lease:		Well No.:
Contact Person: Phone: ()	County:		
, , , ,	·		
Well Construction Details: New well Existing well with chan	ges to construction Existing w	ell with no changes to construci	on
Maximum Authorized Injection Pressure:		· ·	OH
•	mediate Production	Liner	Tubing
Size:	Troduction		Size:
Set at:	<u> </u>		Set at:
			Туре:
Cement Top:			
Cement Bottom:		Cat at:	
Packer Type:		Set at:	
DV Tool Port Collar Depth of: feet with			
Zone of Injection Formation: Top Fe Is there a Chemical Sealant or a Mechanical Casing patch in the annul		et: Perf. or O	pen Hole:
GPS Location: Datum: NAD27 NAD83 WGS84	Lat: Long:	Date Acquire	ed:
MIT Type:	MIT Rea	ason:	
Time in Minute(s):			
Pressures: Set up 1			
Set up 2			
Set up 3			
Tested: Casing or Casing - Tubing Annulus System	Pressure during test:	Bbls. to load annu	lus:
Test Date: Using:			Company's Equipment
The zone tested for this well is between feet and	feet.		
The test results were verified by operator's representative:			
Name:	Title:	Phone: ()	
KCC Office Use Only State Agent:	Title:	W	itness: Yes No
The results were: Remarks:			
Satisfactory			
Not Satisfactory			
Next MIT:			
·			

Conservation Division District Office No. 2 3450 N. Rock Road Building 600, Suite 601 Wichita, KS 67226



Phone: 316-337-7400 http://kcc.ks.gov/

Laura Kelly, Governor

Susan K. Duffy, Chair Dwight D. Keen, Commissioner Andrew J. French, Commissioner

FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

03/02/2023

LICENSE 30582 MWK Petroleum, LLC 508 STONE LAKE CT AUGUSTA, KS 67010-2399

Re: API No. 15-015-21471-00-01 Permit No. D20327.0 BROOMFIELD 3 17-28S-4E Butler County, KS

Operator:

On 03/01/2023, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

- 1) repair and retest the well to show mechanical integrity,
- 2) plug the well, or
- 3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

Failure to comply with K.A.R. 82-3-407(c) by 05/30/2023 shall be punishable by a \$1,000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Virgil Clothier KCC District #2