KOLAR Document ID: 1704955

Confidentiality Requested:

Yes No

Kansas Corporation Commission Oil & Gas Conservation Division

Form ACO-1
January 2018
Form must be Typed
Form must be Signed
All blanks must be Filled

WELL COMPLETION FORM WELL HISTORY - DESCRIPTION OF WELL & LEASE

OPERATOR: License #	API No.:
Name:	Spot Description:
Address 1:	
Address 2:	Feet from North / South Line of Section
City:	Feet from East / West Line of Section
Contact Person:	Footages Calculated from Nearest Outside Section Corner:
Phone: ()	□NE □NW □SE □SW
CONTRACTOR: License #	GPS Location: Lat:, Long:
Name:	(e.g. xx.xxxxxx) (e.gxxx.xxxxxx)
Wellsite Geologist:	Datum: NAD27 NAD83 WGS84
Purchaser:	County:
Designate Type of Completion:	Lease Name: Well #:
New Well Re-Entry Workover	Field Name:
	Producing Formation:
☐ Oil ☐ WSW ☐ SWD	Elevation: Ground: Kelly Bushing:
☐ Gas ☐ DH ☐ EOR	Total Vertical Depth: Plug Back Total Depth:
☐ OG ☐ GSW	Amount of Surface Pipe Set and Cemented at: Feet
CM (Coal Bed Methane)	Multiple Stage Cementing Collar Used? Yes No
Cathodic Other (Core, Expl., etc.):	
If Workover/Re-entry: Old Well Info as follows:	If yes, show depth set: Feet
Operator:	If Alternate II completion, cement circulated from:
Well Name:	feet depth to: sx cmt.
Original Comp. Date: Original Total Depth:	
☐ Deepening ☐ Re-perf. ☐ Conv. to EOR ☐ Conv. to SWD	Drilling Fluid Management Plan
☐ Plug Back ☐ Liner ☐ Conv. to GSW ☐ Conv. to Producer	(Data must be collected from the Reserve Pit)
Commingled Permit #:	Chloride content:ppm Fluid volume:bbls
Dual Completion Permit #:	Dewatering method used:
SWD Permit #:	Location of fluid disposal if hauled offsite:
EOR Permit #:	Location of fluid disposal if fladica offsite.
GSW Permit #:	Operator Name:
_	Lease Name: License #:
Spud Date or Date Reached TD Completion Date or	QuarterSecTwpS. R East West
Recompletion Date Recompletion Date	County: Permit #:

AFFIDAVIT

I am the affiant and I hereby certify that all requirements of the statutes, rules and regulations promulgated to regulate the oil and gas industry have been fully complied with and the statements herein are complete and correct to the best of my knowledge.

Submitted Electronically

KCC Office Use ONLY						
Confidentiality Requested						
Date:						
Confidential Release Date:						
Wireline Log Received Drill Stem Tests Received						
Geologist Report / Mud Logs Received						
UIC Distribution						
ALT I II Approved by: Date:						

KOLAR Document ID: 1704955

Page Two

Operator Name:					Lease Nam	ne:			Well #:	
Sec Tw	pS. F	R [East	West	County:					
open and closed and flow rates if	, flowing and sh gas to surface t ty Log, Final Lo	nut-in pressurest, along wit	es, whe h final c ain Geo	ther shut-in pre hart(s). Attach physical Data a	essure reached extra sheet if r and Final Electr	station more : ric Loc	level, hydrosta space is needed	tic pressures, d.	bottom hole tempe	val tested, time tool erature, fluid recovery, Digital electronic log
Drill Stem Tests (Attach Addit			Ye	es No		Lo	og Formatio	n (Top), Deptl	n and Datum	Sample
Samples Sent to	Geological Sur	vey	Ye	es 🗌 No		Name)		Тор	Datum
Cores Taken Electric Log Run Geologist Repor List All E. Logs F	t / Mud Logs		Y€ Y€	es No						
			Repo		RECORD [Nev	w Used rmediate, producti	on. etc.		
Purpose of St		ze Hole Orilled	Siz	e Casing (In O.D.)	Weight Lbs. / Ft.		Setting Depth	Type of Cement	# Sacks Used	Type and Percent Additives
				ADDITIONAL	OF MENTING /					
Purpose:	[Depth	Typo	of Cement	# Sacks Use		EEZE RECORD	Typo a	nd Percent Additives	
Perforate Protect Ca Plug Back	Top	Bottom	туре	or cement	# Sacks Use	,u		туре а	ia reicent Additives	
Plug Off Z										
Did you perform Does the volum Was the hydraul	e of the total base	fluid of the hyd	draulic fra	cturing treatmen		•	Yes ns? Yes	No (If No	, skip questions 2 an , skip question 3) , fill out Page Three o	,
Date of first Produ	ction/Injection or	Resumed Produ	uction/	Producing Meth			Coolift 0	thor (Fundain)		
Estimated Produc	otion	Oil Bb	le.	Flowing Gas	Pumping	Wate		ther <i>(Explain)</i> bls.	Gas-Oil Ratio	Gravity
Per 24 Hours		Oli Bb	15.	Gas	IVICI	vvale	ı Di	JIS.	Gas-Oil Hallo	Gravity
DISPO	OSITION OF GAS	S:		N	METHOD OF CO	MPLE.	TION:		PRODUCTIO	N INTERVAL:
Vented	Sold Use	d on Lease		Open Hole		Dually		nmingled	Тор	Bottom
(If vente	ed, Submit ACO-18	.)			(5	SUDITIIL I	ACO-5) (Subi	mit ACO-4)		
Shots Per Foot	Perforation Top	Perforation Bottom	on	Bridge Plug Type	Bridge Plug Set At		Acid,		Cementing Squeeze Kind of Material Used)	Record
TUBING RECOR	D: Size:		Set At:		Packer At:					

Form	ACO1 - Well Completion
Operator	Shelby Resources LLC
Well Name	L & M UNIT 1-33
Doc ID	1704955

All Electric Logs Run

Neutron/Density	
Sonic	
Dual Induction	
Micro	

Form	ACO1 - Well Completion
Operator	Shelby Resources LLC
Well Name	L & M UNIT 1-33
Doc ID	1704955

Casing

Purpose Of String	Size Hole Drilled	Size Casing Set	Weight		Type Of Cement		Type and Percent Additives
Surface	12.25	8.625	23	910	Class A		2% gel 3% cc
Production	7.875	5.5	14	4743	Class A	1	2%gel 3% cc



Scale 1:240 Imperial

Well Name: LM Unit #1-33

Surface Location: 184' FSL _1775' FWL, Sec. 33-T28s-R14w

Bottom Location:

API: 15-151-22555-00-00

License Number: 31725

Spud Date: 10/14/2022 Time: 11:00 AM

Region: **Pratt County**

Drilling Completed: 10/27/2022 5:30 AM Time:

Surface Coordinates:

Bottom Hole Coordinates:

Ground Elevation: 2021.00ft K.B. Elevation: 2033.00ft

Logged Interval: 3200.00ft 4914.00ft To:

Total Depth: 4914.00ft

Formation:

Chemical/Fresh Water Gel Drilling Fluid Type:

OPERATOR

Shelby Resources, LLC Company:

3700 Quebec St. Unit 100 PMB 376 Address:

Denver, CO 80207

Contact Geologist: Jeremy Schwartz Contact Phone Nbr: 203-671-6034

Well Name: LM Unit #1-33

Location: 184' FSL _1775' FWL, Sec. 33-T28s-R14w

API: 15-151-22555-00-00

Pool: Field:

State: Kansas Country: USA

LOGGED BY



Mile High Exploration, LLC Company: 14645 Sterling Road Address:

Colorado Springs, CO 80921

Phone Nbr: 203-671-6034

Logged By: Geologist Name: Jeremy Schwartz

NOTES

10 DST's were conducted during the drilling of this well, 1 of which was a misrun due to a hole in the drill pipe.

Due to drill stem test results, sample shows, gas kicks, and log analysis it was determined by all parties involved to further test the well through production casing. The dry samples were saved and will be available for furthur review at the Kansas Geological Society Well Sample Library, located in Wichita, KS.

Respectfully Submitted, Jeremy Schwartz Geologist

CONTRACTOR

Contractor: Fossil Drilling

Rig #:

Rig Type: mud rotary Spud Date: 10/14/2022 Time: 11:00 AM TD Date: 10/27/2022 Time: 5:30 AM


Rig Release: Time:

ELEVATIONS

K.B. Elevation: 2033.00ft Ground Elevation: 2021.00ft

K.B. to Ground: 12.00ft

						D	8 .8									
						Flyni	n Oil C	ο.				Shelby R	esour	es, LLC		_
						Lut	her#1	l				Shriver	Trust	#1-32		
		L&M Un	it #1-33		N/	V-NW-NW	Sec. 4	T29s-F	14w	9	NE-	-SW-SE-SE	Sec. 3:	2-T 2 8s-	R14w	í
	KB		2033		KB		2	022			KB		2	2042		
	LOG	TOPS	SAMPL	E TOPS	COME	. CARD	L	OG	SN	IPL.	COME	. CARD	L	OG	SN	VIPI
Formation	DEPTH	DATUM	DEPTH	DATUM	DEPTH	DATUM	CC	RR.	CO	RR.	DEPTH	DATUM	CO	RR.	CC	ORF
Anhydrite	86 9	1164	872	1161	875	1147	+	17	+	14	880	1162	+	2	-2	
Topeka	3472	-1439	3476	-1443	3465	-1443	+	4	+	0	3476	-1434	1	5	-	
Heebner	3842	-1809	3842	-1809	3830	-1808	+	1	4	1	3840	-1798	+	11	-	8
Douglas	3883	-1850	3888	-1855	3875	-1853	+	3	a	2	3880	-1838	2	12	-	
Brown Lime	4008	-1975	4012	-1979	3998	-1976	+	1	70	3	4003	-1961	71	14	7	8
Lansing	4024	-1 99 1	4027	-1 99 4	4018	-19 9 6	+	5	+	2	4019	-1977	1	14	+	
Lansing B	4050	-2017	4058	-2025	4044	-2022	+	5	4	3	4047	-2005	-	12	1	
Muncie Creek	4184	-2151	4188	-2155	4176	-2154	+	3	a	1	4179	-2137	2	14	1	
Lansing H	4187	-2154	4192	-2159	4184	-2162	+	8	+	3	4183	-2141	5 3	13	<u>,,≅,,</u>	
5tark	4319	-2286	4324	-2291	4318	-2296	+	10	+	5	4310	-2268	7	18	1	
BKC	4394	-2361	4398	-2365	4390	-2368	+	7	+	3	4388	-2346	+	15	¥	
Marmaton	4409	-2376	4410	-2377	4406	-2384	+	8	+	7	4403	-2361	1	15	-	
Viola	4514	-2481	4514	-2481	4523	-2501	+	20	+	20	4507	-2465	-	16	7	
Simpson Shale	4624	-2591	4623	-2590	4612	-2590	1 7 2	1	+	0	4638	-2596	+	5	+	
Simpson Sand								50								
Arbuckle	4683	-2650	4684	-2651	4681	-2659	+	9	+	8	4695	-2653	+	3	+	
RTD	4914	-2881			4710	-2688	7	193			4775	-2733	7:	148		
LTD			4915	-2882	4707	-2685		0	-	197	4774	-2732			-	



ACCESSORIES

FOSSIL ○ Bioclastic or Fragmental

F Fossils < 20%

^^~ Chert Dolomite Oolites Limestone ··· Sandstone Siltstone --- Shale green shale red shale

TEXTURE


C Chalky


OTHER SYMBOLS


MISC


DST


STRINGER




















Shelby LM Unit 1-33 dst 1.jpg
Shelby LM Unit 1-33 dst 2.jpg

Shelby LM Unit 1-33 dst 3.jpg

Shelby LM Unit 1-33 dst 4.jpg

Shelby LM Unit 1-33 dst 5.jpg
Shelby LM Unit 1-33 dst 6.jpg

Shelby LM Unit 1-33 dst 6.jpg

Shelby LM Unit 1-33 dst 7.jpg

Shelby LM Unit 1-33 dst 8.jpg

Shelby LM Unit 1-33 dst 9.jpg


Shelby LM Unit 1-33 dst 10.jpg


Logged By Jeremy Schwartz


Mostly gray shale with some very scattered red, also with scattered LS, cream to white, micro-xln, lithographic and dense with no vis porosity to fossiliferous with mostly poor inter-fossil porosity, no show or odor


Shale with scattered LS as above, poor to no vis porosity, no show or odor


As above, slight influx white lithographic to fossiliferous LS as above, poor to no vis porosity, no show or odor



















C2 (unit C3 (uni -80u gas kick ale Change after DST #8 C2 (units) 200 100u gas kick



Total Gas (units) Lighter Test





Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69607

ATTN: Jeremy Schwartz Test Start: 2022.10.19 @ 05:49:08

DST#: 1

GENERAL INFORMATION:

Formation: Douglas

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Initial)

Time Tool Opened: 09:00:08 Tester: Bric Burgess

Time Test Ended: 12:31:47 Unit No: 80

Interval: 3932.00 ft (KB) To 4017.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4017.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 951.26 psig @ 3933.00 ft (KB) Capacity: 8000.00 psig


 Start Date:
 2022.10.19
 End Date:
 2022.10.19
 Last Calib.:
 1899.12.30

 Start Time:
 05:49:09
 End Time:
 12:31:48
 Time On Btm:
 2022.10.19 @ 08:59:28

 Time Off Btm:
 2022.10.19 @ 10:23:08

TEST COMMENT: IF:Weak Building Blow Built 1.00" (15)

ISI:No Blow Back (45) FF:Pulled tool to reset.



Trilobite Testing, Inc	Ref. No: 69607	Printed: 2022.10.19 @ 21:22:13



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69608

ATTN: Jeremy Schwartz Test Start: 2022.10.19 @ 12:55:01

DST#: 2

GENERAL INFORMATION:

Formation: Douglas

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 14:50:31 Tester: Eric Burgess

Time Test Ended: 20:30:40 Unit No: 80

Interval: 3932.00 ft (KB) To 4017.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4017.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 127.25 psig @ 3933.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.19
 End Date:
 2022.10.19
 Last Calib.:
 2022.10.19

 Start Time:
 12:55:02
 End Time:
 20:30:41
 Time On Btm:
 2022.10.19 @ 14:49:31


 Time Off Btm:
 2022.10.19 @ 18:21:31

TEST COMMENT: IF:Weak Building Blow built 1.50" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built 1.50" in bucket. (60)

FSI:No Blow Back. (90)



Trilobite Testing, Inc Ref. No: 69608 Printed: 2022.10.19 @ 21:11:55



Shelby Resources

33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM

L M Unit 1-33

Denver, Co 80207

Job Ticket: 69609

DST#: 3

ATTN: Jeremy Schwartz

Test Start: 2022.10.20 @ 05:41:38

GENERAL INFORMATION:

Formation: Lansing A-B

ft (KB) Deviated: No Whipstock:

> Tester: Eric Burgess

Time Tool Opened: 07:46:38 Time Test Ended: 13:27:08

Interval:

Unit No: 80

Test Type:

4027.00 ft (KB) To 4082.00 ft (KB) (TVD)

Reference Bevations: 2033.00 ft (KB)

Total Depth: 4082.00 ft (KB) (TVD) 2021.00 ft (CF)

Conventional Bottom Hole (Reset)

Hole Diameter: 7.88 inches Hole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 99.61 psig @ 4036.00 ft (KB) Capacity:

8000.00 psig

Start Date: Start Time:

2022.10.20 05:41:39

End Date: End Time: 2022.10.20 13:27:08

Last Calib .:

1899.12.30

Time On Btm: Time Off Btm:


2022.10.20 @ 07:44:58 2022.10.20 @ 11:21:58

TEST COMMENT: IF:Strong Building Blow built 375.29" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 689.94" (60)

FSI:No Blow Back. (90)



PRESSURE SUMMARY

Time	Pressure	Temp	Annotation
(Min.)	(psig)	(deg F)	
0	2013.45	105.45	Initial Hydro-static
2	45.01	108.50	Open To Flow (1)
16	64.16	109.56	Shut-In(1)
62	1266.45	110.65	End Shut-In(1)
63	47.55	111.27	Open To Flow (2)
123	99.61	113.20	Shut-ln(2)
217	1177.12	114.48	End Shut-In(2)
217	1934.57	114.78	Final Hydro-static

Recovery

58.50 GVSOWCM 5%G 5%O 5%W 85%M (Volume (bbl)
	0.29
40.00 OSM100%M	0.29
	0.58

Gas Rates

	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)
First Gas Rate	0.13	15.81	11.31
Last Gas Rate	0.13	23.13	14.05
Max. Gas Rate	0.13	23.13	14.05

Printed: 2022.10.20 @ 14:16:29 Ref. No: 69609 Trilobite Testing, Inc



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69610

ATTN: Jeremy Schwartz Test Start: 2022.10.21 @ 00:46:39

GENERAL INFORMATION:

Formation: Lansing D-F

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 03:03:29 Tester: Bric Burgess

Time Test Ended: 09:12:18 Unit No: 80

Interval: 4083.00 ft (KB) To 4140.00 ft (KB) (TVD) Reference Bevations: 2033.00 ft (KB)

Total Depth: 4140.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 207.00 psig @ 4095.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.21
 End Date:
 2022.10.21
 Last Calib.:
 2022.10.21

 Start Time:
 00:46:40
 End Time:
 09:12:19
 Time On Btm:
 2022.10.21 @ 03:02:09


 Time Off Btm:
 2022.10.21 @ 06:38:59

TEST COMMENT: IF:Fair Building Blow built 9.61" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 32.42" (60)

FSI:No Blow Back. (90)



Recovery

Length (ft)	Description	Volume (bbl)			
58.50	WCM 50%M 50%W	0.29			
121.50	MCW 80%W 20%M	1.21			
63.00	GOSWCM 15%G 45%W 40%M	0.92			
126.00	GOSWCM 5%G 20%W 75%M	1.84			
0.00	495' GIP	0.00			

Gas R	ates
-------	------

Choke (Inches)	Pressure (psig)	Gas Rate (Miciro)

DST#: 4

Trilobite Testing, Inc Ref. No: 69610 Printed: 2022.10.21 @ 10:33:15



Shelby Resources 33-28S-14W Pratt Co

L M Unit 1-33 3700 Quebec St Ste 100 PM

Job Ticket: 69611 DST#: 5

ATTN: Jeremy Schwartz Test Start: 2022.10.21 @ 21:46:36

GENERAL INFORMATION:

Formation: Lansing H-I

ft (KB) Conventional Bottom Hole (Reset) Deviated: No Whipstock: Test Type:

Time Tool Opened: 00:16:56 Tester: Eric Burgess

Time Test Ended: 04:53:26 Unit No: 80

Denver, Co 80207

2033.00 ft (KB) 4185.00 ft (KB) To 4220.00 ft (KB) (TVD) Reference Bevations: Interval:

Total Depth: 420.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inches Hole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 40.12 psig @ 4186.00 ft (KB) Capacity: 8000.00 psig


Start Date: 2022.10.21 End Date: 2022.10.22 Last Calib .: 1899.12.30 Start Time: 21:46:37 End Time: 04:53:26 Time On Btm: 2022.10.22 @ 00:15:56 Time Off Btm: 2022.10.22 @ 02:38:46

TEST COMMENT: IF:Weak Building Blow built 2.50" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built .50" in bucket. (60)

FSI:No Blow Back. (20)



Ref. No: 69611 Printed: 2022.10.22 @ 07:25:29 Trilobite Testing, Inc.



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69612 **DST#:6**

Test Start: 2022.10.22 @ 15:54:37

ATTN: Jeremy Schwartz

GENERAL INFORMATION:

Formation: Lansing J

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 18:30:07 Tester: Eric Burgess

Time Test Ended: 02:02:37 Unit No: 80

Interval: 4235.00 ft (KB) To 4293.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4293.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 1066.25 psig @ 4247.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.22
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 15:54:38
 End Time:
 02:02:37
 Time On Btm:
 2022.10.22 @ 18:28:57


 Time Off Btm:
 2022.10.22 @ 22:00:07

TEST COMMENT: IF:STrong Building Blow built 106.60" (15)

ISI:3.75" Blow Back. (45)

FF:Strong Building Blow built 176.59" (60)

FSI: 1.75" Blow Back. (90)



Recovery

Length (ft)	Length (ft) Description				
0.00	00 2520' GIP				
1188.00	W 100%W	16.24			
126.00	GOSMCW 10%G 75%W 15%M	1.84			
315.00	GVSOMCW 15%G 5%O 65%W 15%M	4.61			
315.00					

Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69612 Printed: 2022.10.23 @ 07:46:42



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69612 **DST#:6**

Test Start: 2022.10.22 @ 15:54:37

ATTN: Jeremy Schwartz

GENERAL INFORMATION:

Formation: Lansing J

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 18:30:07 Tester: Eric Burgess

Time Test Ended: 02:02:37 Unit No: 80

Interval: 4235.00 ft (KB) To 4293.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4293.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 1066.25 psig @ 4247.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.22
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 15:54:38
 End Time:
 02:02:37
 Time On Btm:
 2022.10.22 @ 18:28:57


 Time Off Btm:
 2022.10.22 @ 22:00:07

TEST COMMENT: IF:STrong Building Blow built 106.60" (15)

ISI:3.75" Blow Back. (45)

FF:Strong Building Blow built 176.59" (60)

FSI: 1.75" Blow Back. (90)



Recovery

Length (ft)	Length (ft) Description				
0.00	00 2520' GIP				
1188.00	W 100%W	16.24			
126.00	GOSMCW 10%G 75%W 15%M	1.84			
315.00	GVSOMCW 15%G 5%O 65%W 15%M	4.61			
315.00					

Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69612 Printed: 2022.10.23 @ 07:46:42



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69613

ATTN: Jeremy Schwartz Test Start: 2022.10.23 @ 12:02:40

GENERAL INFORMATION:

Formation: Lansing K

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 14:18:00 Tester: Eric Burgess

Time Test Ended: 20:30:00 Unit No: 80

Interval: 4320.00 ft (KB) To 4342.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4342.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Poor KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 84.04 psig @ 4321.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.23
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 12:02:41
 End Time:
 20:30:00
 Time On Btm:
 2022.10.23 @ 14:16:20


 Time Off Btm:
 2022.10.23 @ 17:47:10

TEST COMMENT: IF:Strong Building Blow built 75.16" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 163.16" (60)

FSI:No Blow Back. (90)



Time	Pressure	Temp	Annotation					
(Min.)	(psig)	(deg F)						
0	2091.86	112.38	Initial Hydro-static					
2	47.42	112.15	Open To Flow (1)					
14	56.73	112.24	Shut-ln(1)					
60	1233.26	114.88	End Shut-In(1)					
61	40.26	114.97	Open To Flow (2)					
120	84.04	118.24	Shut-In(2)					
210	1101.19	119.70	End Shut-In(2)					
211	2038.24	120.09	Final Hydro-static					

PRESSURE SUMMARY

DST#: 7

Recovery

Length (ft)	Description	Volume (bbl)			
58.50	8.50 OWCG 45%G 40%O 25%W3				
58.50	OMWCG 50%G 25%O 15%W 10%M	0.29			
63.00	GVSOCM 20%G 5%O 75%M	0.92			
40.00 GOCM 10%G 10%O 80%M		0.58			
0.00	0.00 1638' GIP				

Gas	Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69613 Printed: 2022.10.24 @ 06:59:40



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Job Ticket: 69614 **DST#:8**

ATTN: Jeremy Schwartz Test Start: 2022.10.24 @ 12:31:45

GENERAL INFORMATION:

Formation: Conglomerate

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 15:35:25 Tester: Eric Burgess

Time Test Ended: 19:34:15 Unit No: 80

Interval: 4469.00 ft (KB) To 4490.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4490.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 29.12 psig @ 4470.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.24
 End Date:
 2022.10.24
 Last Calib.:
 1899.12.30

 Start Time:
 12:31:46
 End Time:
 19:34:15
 Time On Btm:
 2022.10.24 @ 15:34:35


 Time Off Btm:
 2022.10.24 @ 17:16:35

TEST COMMENT: IF:Weak Building Blow built 2.25" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Blow built .41" but died. (20)

FSI:No Blow Back. (20)



Trilobite Testing, Inc Ref. No: 69614 Printed: 2022.10.24 @ 20:50:59



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69615

ATTN: Jeremy Schwartz Test Start: 2022.10.25 @ 05:08:36

DST#: 9

GENERAL INFORMATION:

Formation: Kinderhook

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 07:32:36 Tester: Eric Burgess

Time Test Ended: 10:45:36 Unit No: 80

Interval: 4495.00 ft (KB) To 4415.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4515.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 37.88 psig @ 4496.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.25
 End Date:
 2022.10.25
 Last Calib.:
 1899.12.30


 Start Time:
 05:08:37
 End Time:
 10:45:36
 Time On Btm:
 2022.10.25 @ 07:31:56

 Time Off Btm:
 2022.10.25 @ 08:51:16


TEST COMMENT: IF:Weak Building Blow built 1.00" in bucket. (15)

ISI:No Blow Back. (45)

FF:No Blow Advanced to pull tool per Jeremy. (12)



Trilobite Testing, Inc Ref. No: 69615 Printed: 2022.10.25 @ 11:16:46



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69616

ATTN: Jeremy Schwartz Test Start: 2022.10.25 @ 23:46:11

DST#: 10

GENERAL INFORMATION:

Formation: Viola

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 02:27:51 Tester: Eric Burgess

Time Test Ended: 07:08:20 Unit No: 80

Interval: 4520.00 ft (KB) To 4610.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4610.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 38.92 psig @ 4527.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.25
 End Date:
 2022.10.26
 Last Calib.:
 1899.12.30

 Start Time:
 23:46:12
 End Time:
 07:08:21
 Time On Btm:
 2022.10.26 @ 02:27:31


 Time Off Btm:
 2022.10.26 @ 05:07:31

TEST COMMENT: IF:Weak Building Blow built 1.25" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built .50" in bucket. (30)

FSI:No Blow Back. (60)



Trilobite Testing, Inc Ref. No: 69616 Printed: 2022.10.26 @ 07:26:01



Scale 1:240 Imperial

Well Name: LM Unit #1-33

Surface Location: 184' FSL _1775' FWL, Sec. 33-T28s-R14w

Bottom Location:

API: 15-151-22555-00-00

License Number: 31725

Spud Date: 10/14/2022 Time: 11:00 AM

Region: **Pratt County**

Drilling Completed: 10/27/2022 5:30 AM Time:

Surface Coordinates:

Bottom Hole Coordinates:

Ground Elevation: 2021.00ft K.B. Elevation: 2033.00ft

Logged Interval: 3200.00ft 4914.00ft To:

Total Depth: 4914.00ft

Formation:

Chemical/Fresh Water Gel Drilling Fluid Type:

OPERATOR

Shelby Resources, LLC Company:

3700 Quebec St. Unit 100 PMB 376 Address:

Denver, CO 80207

Contact Geologist: Jeremy Schwartz Contact Phone Nbr: 203-671-6034

Well Name: LM Unit #1-33

Location: 184' FSL _1775' FWL, Sec. 33-T28s-R14w

API: 15-151-22555-00-00

Pool: Field:

State: Kansas Country: USA

LOGGED BY



Mile High Exploration, LLC Company: 14645 Sterling Road Address:

Colorado Springs, CO 80921

Phone Nbr: 203-671-6034

Logged By: Geologist Name: Jeremy Schwartz

NOTES

10 DST's were conducted during the drilling of this well, 1 of which was a misrun due to a hole in the drill pipe.

Due to drill stem test results, sample shows, gas kicks, and log analysis it was determined by all parties involved to further test the well through production casing. The dry samples were saved and will be available for furthur review at the Kansas Geological Society Well Sample Library, located in Wichita, KS.

Respectfully Submitted, Jeremy Schwartz Geologist

CONTRACTOR

Contractor: Fossil Drilling

Rig #:

Rig Type: mud rotary Spud Date: 10/14/2022 Time: 11:00 AM TD Date: 10/27/2022 Time: 5:30 AM


Rig Release: Time:

ELEVATIONS

K.B. Elevation: 2033.00ft Ground Elevation: 2021.00ft

K.B. to Ground: 12.00ft

					D&A Flynn Oil Co.					Shelby Resources, LLC						
	04					Lut	her#1	l				Shriver	Trust	#1-32		
	9:	L&M Un	NW-NW-NW Sec. 4-T29s-R14w					NE-SW-SE-SE Sec. 32-T28s-R14w					í			
	KB		2033		KB		2	022			KB		2	042		
	LOG	TOPS	SAMPL	E TOPS	COME	. CARD	L	OG	SN	IPL.	COME	. CARD	L	OG	SN	VIPI
Formation	DEPTH	DATUM	DEPTH	DATUM	DEPTH	DATUM	CC	RR.	CO	RR.	DEPTH	DATUM	CO	RR.	CC	ORF
Anhydrite	86 9	1164	872	1161	875	1147	+	17	+	14	880	1162	+	2	-2	
Topeka	3472	-1439	3476	-1443	3465	-1443	+	4	+	0	3476	-1434	1	5	-	
Heebner	3842	-1809	3842	-1809	3830	-1808	+	1	4	1	3840	-1798	+	11	-	8
Douglas	3883	-1850	3888	-1855	3875	-1853	+	3	a	2	3880	-1838	2	12	-	
Brown Lime	4008	-1975	4012	-1979	3998	-1976	+	1	70	3	4003	-1961	71	14	7	8
Lansing	4024	-1 99 1	4027	-1 99 4	4018	-19 9 6	+	5	+	2	4019	-1977	1	14	+	
Lansing B	4050	-2017	4058	-2025	4044	-2022	+	5	4	3	4047	-2005	-	12	1	
Muncie Creek	4184	-2151	4188	-2155	4176	-2154	+	3	a	1	4179	-2137	2	14	1	
Lansing H	4187	-2154	4192	-2159	4184	-2162	+	8	+	3	4183	-2141	5 3	13	<u>,,≅,,</u>	
5tark	4319	-2286	4324	-2291	4318	-2296	+	10	+	5	4310	-2268	-	18	1	
BKC	4394	-2361	4398	-2365	4390	-2368	+	7	+	3	4388	-2346	+	15	¥	
Marmaton	4409	-2376	4410	-2377	4406	-2384	+	8	+	7	4403	-2361	1	15	-	
Viola	4514	-2481	4514	-2481	4523	-2501	+	20	+	20	4507	-2465	-	16	7	
Simpson Shale	4624	-2591	4623	-2590	4612	-2590	1 7 2	1	+	0	4638	-2596	+	5	+	
Simpson Sand								50								
Arbuckle	4683	-2650	4684	-2651	4681	-2659	+	9	+	8	4695	-2653	+	3	+	8
RTD	4914	-2881			4710	-2688	7	193			4775	-2733	7:	148		
LTD			4915	-2882	4707	-2685		0	-	197	4774	-2732			-	



ACCESSORIES

FOSSIL ○ Bioclastic or Fragmental

F Fossils < 20%

^^~ Chert Dolomite Oolites Limestone ··· Sandstone Siltstone --- Shale green shale red shale

TEXTURE


C Chalky


OTHER SYMBOLS


MISC


DST


STRINGER




















Shelby LM Unit 1-33 dst 1.jpg
Shelby LM Unit 1-33 dst 2.jpg

Shelby LM Unit 1-33 dst 3.jpg

Shelby LM Unit 1-33 dst 4.jpg

Shelby LM Unit 1-33 dst 5.jpg
Shelby LM Unit 1-33 dst 6.jpg

Shelby LM Unit 1-33 dst 6.jpg

Shelby LM Unit 1-33 dst 7.jpg

Shelby LM Unit 1-33 dst 8.jpg

Shelby LM Unit 1-33 dst 9.jpg


Shelby LM Unit 1-33 dst 10.jpg


Logged By Jeremy Schwartz


Mostly gray shale with some very scattered red, also with scattered LS, cream to white, micro-xln, lithographic and dense with no vis porosity to fossiliferous with mostly poor inter-fossil porosity, no show or odor


Shale with scattered LS as above, poor to no vis porosity, no show or odor


As above, slight influx white lithographic to fossiliferous LS as above, poor to no vis porosity, no show or odor



















C2 (unit C3 (uni -80u gas kick ale Change after DST #8 C2 (units) 200 100u gas kick



Total Gas (units) Lighter Test





Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69607

ATTN: Jeremy Schwartz Test Start: 2022.10.19 @ 05:49:08

DST#: 1

GENERAL INFORMATION:

Formation: Douglas

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Initial)

Time Tool Opened: 09:00:08 Tester: Bric Burgess

Time Test Ended: 12:31:47 Unit No: 80

Interval: 3932.00 ft (KB) To 4017.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4017.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 951.26 psig @ 3933.00 ft (KB) Capacity: 8000.00 psig


 Start Date:
 2022.10.19
 End Date:
 2022.10.19
 Last Calib.:
 1899.12.30

 Start Time:
 05:49:09
 End Time:
 12:31:48
 Time On Btm:
 2022.10.19 @ 08:59:28

 Time Off Btm:
 2022.10.19 @ 10:23:08

TEST COMMENT: IF:Weak Building Blow Built 1.00" (15)

ISI:No Blow Back (45) FF:Pulled tool to reset.



Trilobite Testing, Inc	Ref. No: 69607	Printed: 2022.10.19 @ 21:22:13



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69608

ATTN: Jeremy Schwartz Test Start: 2022.10.19 @ 12:55:01

DST#: 2

GENERAL INFORMATION:

Formation: Douglas

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 14:50:31 Tester: Eric Burgess

Time Test Ended: 20:30:40 Unit No: 80

Interval: 3932.00 ft (KB) To 4017.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4017.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 127.25 psig @ 3933.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.19
 End Date:
 2022.10.19
 Last Calib.:
 2022.10.19

 Start Time:
 12:55:02
 End Time:
 20:30:41
 Time On Btm:
 2022.10.19 @ 14:49:31


 Time Off Btm:
 2022.10.19 @ 18:21:31

TEST COMMENT: IF:Weak Building Blow built 1.50" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built 1.50" in bucket. (60)

FSI:No Blow Back. (90)



Trilobite Testing, Inc Ref. No: 69608 Printed: 2022.10.19 @ 21:11:55



Shelby Resources

33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM

L M Unit 1-33

Denver, Co 80207

Job Ticket: 69609

DST#: 3

ATTN: Jeremy Schwartz

Test Start: 2022.10.20 @ 05:41:38

GENERAL INFORMATION:

Formation: Lansing A-B

ft (KB) Deviated: No Whipstock:

> Tester: Eric Burgess

Time Tool Opened: 07:46:38 Time Test Ended: 13:27:08

Interval:

Unit No: 80

Test Type:

4027.00 ft (KB) To 4082.00 ft (KB) (TVD)

Reference Bevations: 2033.00 ft (KB)

Total Depth: 4082.00 ft (KB) (TVD) 2021.00 ft (CF)

Conventional Bottom Hole (Reset)

Hole Diameter: 7.88 inches Hole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 99.61 psig @ 4036.00 ft (KB) Capacity:

8000.00 psig

Start Date: Start Time:

2022.10.20 05:41:39

End Date: End Time: 2022.10.20 13:27:08

Last Calib .:

1899.12.30

Time On Btm: Time Off Btm:


2022.10.20 @ 07:44:58 2022.10.20 @ 11:21:58

TEST COMMENT: IF:Strong Building Blow built 375.29" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 689.94" (60)

FSI:No Blow Back. (90)



PRESSURE SUMMARY

Time	Pressure	Temp	Annotation
(Min.)	(psig)	(deg F)	
0	2013.45	105.45	Initial Hydro-static
2	45.01	108.50	Open To Flow (1)
16	64.16	109.56	Shut-In(1)
62	1266.45	110.65	End Shut-In(1)
63	47.55	111.27	Open To Flow (2)
123	99.61	113.20	Shut-ln(2)
217	1177.12	114.48	End Shut-In(2)
217	1934.57	114.78	Final Hydro-static

Recovery

58.50 GVSOWCM 5%G 5%O 5%W 85%M (Volume (bbl)
	0.29
40.00 OSM100%M	0.29
	0.58

Gas Rates

	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)
First Gas Rate	0.13	15.81	11.31
Last Gas Rate	0.13	23.13	14.05
Max. Gas Rate	0.13	23.13	14.05

Printed: 2022.10.20 @ 14:16:29 Ref. No: 69609 Trilobite Testing, Inc



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69610

ATTN: Jeremy Schwartz Test Start: 2022.10.21 @ 00:46:39

GENERAL INFORMATION:

Formation: Lansing D-F

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 03:03:29 Tester: Eric Burgess

Time Test Ended: 09:12:18 Unit No: 80

Interval: 4083.00 ft (KB) To 4140.00 ft (KB) (TVD) Reference Bevations: 2033.00 ft (KB)

Total Depth: 4140.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 207.00 psig @ 4095.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.21
 End Date:
 2022.10.21
 Last Calib.:
 2022.10.21

 Start Time:
 00:46:40
 End Time:
 09:12:19
 Time On Btm:
 2022.10.21 @ 03:02:09


 Time Off Btm:
 2022.10.21 @ 06:38:59

TEST COMMENT: IF:Fair Building Blow built 9.61" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 32.42" (60)

FSI:No Blow Back. (90)



Recovery

Length (ft)	Description	Volume (bbl)
58.50	WCM 50%M 50%W	0.29
121.50	MCW 80%W 20%M	1.21
63.00	GOSWCM 15%G 45%W 40%M	0.92
126.00	GOSWCM 5%G 20%W 75%M	1.84
0.00	495' GIP	0.00

Gas R	ates
-------	------

Choke (Inches)	Pressure (psig)	Gas Rate (Miciro)

DST#: 4

Trilobite Testing, Inc Ref. No: 69610 Printed: 2022.10.21 @ 10:33:15



Shelby Resources 33-28S-14W Pratt Co

L M Unit 1-33 3700 Quebec St Ste 100 PM

Job Ticket: 69611 DST#: 5

ATTN: Jeremy Schwartz Test Start: 2022.10.21 @ 21:46:36

GENERAL INFORMATION:

Formation: Lansing H-I

ft (KB) Conventional Bottom Hole (Reset) Deviated: No Whipstock: Test Type:

Time Tool Opened: 00:16:56 Tester: Eric Burgess

Time Test Ended: 04:53:26 Unit No: 80

Denver, Co 80207

2033.00 ft (KB) 4185.00 ft (KB) To 4220.00 ft (KB) (TVD) Reference Bevations: Interval:

Total Depth: 420.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inches Hole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 40.12 psig @ 4186.00 ft (KB) Capacity: 8000.00 psig


Start Date: 2022.10.21 End Date: 2022.10.22 Last Calib .: 1899.12.30 Start Time: 21:46:37 End Time: 04:53:26 Time On Btm: 2022.10.22 @ 00:15:56 Time Off Btm: 2022.10.22 @ 02:38:46

TEST COMMENT: IF:Weak Building Blow built 2.50" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built .50" in bucket. (60)

FSI:No Blow Back. (20)



Ref. No: 69611 Printed: 2022.10.22 @ 07:25:29 Trilobite Testing, Inc.



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69612 **DST#:6**

Test Start: 2022.10.22 @ 15:54:37

ATTN: Jeremy Schwartz

GENERAL INFORMATION:

Formation: Lansing J

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 18:30:07 Tester: Eric Burgess

Time Test Ended: 02:02:37 Unit No: 80

Interval: 4235.00 ft (KB) To 4293.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4293.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 1066.25 psig @ 4247.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.22
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 15:54:38
 End Time:
 02:02:37
 Time On Btm:
 2022.10.22 @ 18:28:57


 Time Off Btm:
 2022.10.22 @ 22:00:07

TEST COMMENT: IF:STrong Building Blow built 106.60" (15)

ISI:3.75" Blow Back. (45)

FF:Strong Building Blow built 176.59" (60)

FSI: 1.75" Blow Back. (90)



Recovery

Length (ft)	Description	Volume (bbl)
0.00	2520' GIP	0.00
1188.00	W 100%W	16.24
126.00	GOSMCW 10%G 75%W 15%M	1.84
315.00	GVSOMCW 15%G 5%O 65%W 15%M	4.61
315.00	GOMCW 10%G 10%O 40%W 40%M	4.61

Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69612 Printed: 2022.10.23 @ 07:46:42



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69612 **DST#:6**

Test Start: 2022.10.22 @ 15:54:37

ATTN: Jeremy Schwartz

GENERAL INFORMATION:

Formation: Lansing J

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 18:30:07 Tester: Eric Burgess

Time Test Ended: 02:02:37 Unit No: 80

Interval: 4235.00 ft (KB) To 4293.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4293.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 1066.25 psig @ 4247.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.22
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 15:54:38
 End Time:
 02:02:37
 Time On Btm:
 2022.10.22 @ 18:28:57


 Time Off Btm:
 2022.10.22 @ 22:00:07

TEST COMMENT: IF:STrong Building Blow built 106.60" (15)

ISI:3.75" Blow Back. (45)

FF:Strong Building Blow built 176.59" (60)

FSI: 1.75" Blow Back. (90)



Recovery

Length (ft)	Description	Volume (bbl)
0.00	2520' GIP	0.00
1188.00	W 100%W	16.24
126.00	GOSMCW 10%G 75%W 15%M	1.84
315.00	GVSOMCW 15%G 5%O 65%W 15%M	4.61
315.00	GOMCW 10%G 10%O 40%W 40%M	4.61

Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69612 Printed: 2022.10.23 @ 07:46:42



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69613

ATTN: Jeremy Schwartz Test Start: 2022.10.23 @ 12:02:40

GENERAL INFORMATION:

Formation: Lansing K

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 14:18:00 Tester: Eric Burgess

Time Test Ended: 20:30:00 Unit No: 80

Interval: 4320.00 ft (KB) To 4342.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4342.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Poor KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 84.04 psig @ 4321.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.23
 End Date:
 2022.10.23
 Last Calib.:
 1899.12.30

 Start Time:
 12:02:41
 End Time:
 20:30:00
 Time On Btm:
 2022.10.23 @ 14:16:20


 Time Off Btm:
 2022.10.23 @ 17:47:10

TEST COMMENT: IF:Strong Building Blow built 75.16" (15)

ISI:No Blow Back. (45)

FF:Strong Building Blow built 163.16" (60)

FSI:No Blow Back. (90)



Time	Pressure	Temp	Annotation	
(Min.)	(psig)	(deg F)		
0	2091.86	112.38	Initial Hydro-static	
2	47.42	112.15	Open To Flow (1)	
14	56.73	112.24	Shut-ln(1)	
60	1233.26	114.88	End Shut-In(1)	
61	40.26	114.97	Open To Flow (2)	
120	84.04	118.24	Shut-In(2)	
210	1101.19	119.70	End Shut-In(2)	
211	2038.24	120.09	Final Hydro-static	

PRESSURE SUMMARY

DST#: 7

Recovery

Length (ft)	Description	Volume (bbl)
58.50	OWCG 45%G 40%O 25%W3	0.29
58.50	OMWCG 50%G 25%O 15%W 10%M	0.29
63.00	GVSOCM 20%G 5%O 75%M	0.92
40.00	GOCM 10%G 10%O 80%M	0.58
0.00	1638' GIP	0.00

Gas	Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Trilobite Testing, Inc Ref. No: 69613 Printed: 2022.10.24 @ 06:59:40



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Job Ticket: 69614 **DST#:8**

ATTN: Jeremy Schwartz Test Start: 2022.10.24 @ 12:31:45

GENERAL INFORMATION:

Formation: Conglomerate

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 15:35:25 Tester: Eric Burgess

Time Test Ended: 19:34:15 Unit No: 80

Interval: 4469.00 ft (KB) To 4490.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4490.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 29.12 psig @ 4470.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.24
 End Date:
 2022.10.24
 Last Calib.:
 1899.12.30

 Start Time:
 12:31:46
 End Time:
 19:34:15
 Time On Btm:
 2022.10.24 @ 15:34:35


 Time Off Btm:
 2022.10.24 @ 17:16:35

TEST COMMENT: IF:Weak Building Blow built 2.25" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Blow built .41" but died. (20)

FSI:No Blow Back. (20)



Trilobite Testing, Inc Ref. No: 69614 Printed: 2022.10.24 @ 20:50:59



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69615

ATTN: Jeremy Schwartz Test Start: 2022.10.25 @ 05:08:36

DST#: 9

GENERAL INFORMATION:

Formation: Kinderhook

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 07:32:36 Tester: Eric Burgess

Time Test Ended: 10:45:36 Unit No: 80

Interval: 4495.00 ft (KB) To 4415.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4515.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 37.88 psig @ 4496.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.25
 End Date:
 2022.10.25
 Last Calib.:
 1899.12.30


 Start Time:
 05:08:37
 End Time:
 10:45:36
 Time On Btm:
 2022.10.25 @ 07:31:56

 Time Off Btm:
 2022.10.25 @ 08:51:16


TEST COMMENT: IF:Weak Building Blow built 1.00" in bucket. (15)

ISI:No Blow Back. (45)

FF:No Blow Advanced to pull tool per Jeremy. (12)



Trilobite Testing, Inc Ref. No: 69615 Printed: 2022.10.25 @ 11:16:46



Shelby Resources 33-28S-14W Pratt Co

3700 Quebec St Ste 100 PM L M Unit 1-33

Denver, Co 80207 Job Ticket: 69616

ATTN: Jeremy Schwartz Test Start: 2022.10.25 @ 23:46:11

DST#: 10

GENERAL INFORMATION:

Formation: Viola

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 02:27:51 Tester: Eric Burgess

Time Test Ended: 07:08:20 Unit No: 80

Interval: 4520.00 ft (KB) To 4610.00 ft (KB) (TVD) Reference Elevations: 2033.00 ft (KB)

Total Depth: 4610.00 ft (KB) (TVD) 2021.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 12.00 ft

Serial #: 8369 Outside

Press@RunDepth: 38.92 psig @ 4527.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.10.25
 End Date:
 2022.10.26
 Last Calib.:
 1899.12.30

 Start Time:
 23:46:12
 End Time:
 07:08:21
 Time On Btm:
 2022.10.26 @ 02:27:31


 Time Off Btm:
 2022.10.26 @ 05:07:31

TEST COMMENT: IF:Weak Building Blow built 1.25" in bucket. (15)

ISI:No Blow Back. (45)

FF:Weak Building Blow built .50" in bucket. (30)

FSI:No Blow Back. (60)



Trilobite Testing, Inc Ref. No: 69616 Printed: 2022.10.26 @ 07:26:01

Shelby Resources (JIB Account) Ledger Listing

01/01/2022 thru 12/31/2022 Only Accounts 9208, 9308

*** Only Sub-Accounts

2105 thru

2105 are Included. ***

Page

Reference | Jrnl | Description Amount Quantity Invoice# 9208-2105 Cementing & Services - L & M Unit # 1-33 0.00 15193 20 Hurricane Services Inc. 10/20/2022 0364022 16,543.00 Bd 10/31/2022 Deck: 2.0



Remit To: Hurricane Services, Inc. 250 N. Water, Suite 200 Wichita, KS 67202 316-303-9515

Customer:

SHELBY RESOURCES LLC 3700 QUEBEC STREET **SUITE 100 PMB 376** DENVER, CO 80207-1639

Invoice Date: 10/15/2022 0364022 Invoice # Lease Name: L-M Unit Well #: 1-33 (New) County: Pratt, Ks Job Number: WP3510 District: Pratt

Date/Description	HRS/QTY	Rate	Total
Surface	0.000	0.000	0.00
H-CON	275.000	25.000	6,875.00
Cement Class A	250.000	19.000	4,750.00
Calcium Chloride	470.000	0.750	352.50
Cello Flake	64.000	1.750	112.00
8 5/8" Flapper insert valve	1.000	375.000	375.00
8 5/8" Top rubber plug	1.000	175.000	175.00
8 5/8" Cementing basket	1.000	500.000	500.00
8 5/8" Centralizer x 12 1/4"	2.000	90.000	180.00
Light Eq Mileage	10.000	2.000	20.00
Heavy Eq Mileage	20.000	4.000	80.00
Ton Mileage	247.000	1.500	370.50
Cement Blending & Mixing	520.000	1.400	728.00
Depth Charge 501'-1000'	1.000	1,250.000	1,250.00
Cement Data Acquisition	1.000	250.000	250.00
Cement Plug Container	1.000	250.000	250.00
Service Supervisor	1.000	275.000	275.00

Total	16,543.00

TERMS: Net 30 days. Interest may be charged on past due invoice at rate of 1 1/2% per month or maximum allowed by applicable state or federal laws. HSI has right to revoke any discounts applied in arriving at net invoice price if invoice is past due. If revoked, full invoice price without discount plus additional sales tax, as applicable, is due immediately and subject to interest charges. Customer agrees to pay all collection costs directly or indirectly incurred by HSI in the event HSI engages a third party to pursue collection of past due invoice.

SALES TAX: Services performed on oil, gas and water wells in Kansas are subject to sales tax, with certain exceptions. HSI relies on the well information provided by the customer in identifying whether the services performed on wells qualify for exemption.

WE APPRECIATE YOUR BUSINESS!

Date	Reference	Jrnl	Description	Invoice#	Amount	Quantity

Hurricane Services, Inc. 250 N. Water St., Suite #200 Wichita, KS 67202



Customer	Shelby Resources	LLC	Lease & Well#	L-M Unit 1-33				Date		10/15/2022	
Service District	Pratt Kansas		County & State	Pratt Kansas	Legals S/T/R	33-26	Is-14w	Job#		071072022	
Job Type	surface	Ø PROD	₽ INJ	□ SWD	New Well?	9 YES	□ No	Ticket#		2540	
Equipment #	Driver			Job Safety Ar	alysis - A Discus	sion of Hazard			<u> </u>	wp 3510	
916	M Brungardt	☑ Hard hat		☑ Gloves		□ Lockout/Ta		D Warning Sign	o Or Flancis	_	
179/521	A Clifton	☐ H2S Monitor		☐ Eye Protection		□ Required Pe	-	□ Fall Protectio		1	
523/533	K Julian	☑ Safety Footwea	r	☐ Respiratory Prof	ection	☑ Slip/Trip/Fa		□ Specific Job S		actations	
		☐ FRC/Protective	Clothing	☐ Additional Chen	nical/Acid PPE	☑ Overhead H		Muster Point			
		☐ Hearing Protect	tion	☐ Fire Extinguisher	r			ues noted below	mearca coc	4110113	
					Cor	nments					
					· · · · · · · · · · · · · · · · · · ·						
Product/ Service											
Code		Descr	iption		Unit of Measure	Overatitus					
cp025	H-Con		· · · · · · · · · · · · · · · · · · ·		sack				7	Net Ar	
cp010	Class A Cement				sack	275.00	+	 	 		,875.00
cp100	Calcium Chloride				1b	470,80			 		,750.00
cp120	Cello-flake				lb	64.00			 		352.50
fe275	8 5/8" AFU Flapper I	insert Valve			ea	1.00		 	 		112.00
fe285	8 5/8" Rubber Plug				ea	1.00			 		375.00
e255	8 5/8" Cement Bask	et			ea	1.00			 		175.00
e250	8 5/8" Centralizer				ea	2.00			 		500.00
n015	Light Equipment Mile	eage			mi	10,00	 -		 		180.00
n010	Heavy Equipment M	leage			mi	20.00					\$20.00
11020	Ton Mileage				tm	247.00	-		 		\$80.00 370.50
:060	Cement Blending & f	Mixing Service			sack	520.00	—		 		728.00
1011	Depth Charge: 501'-	1000'			job	1.00			 		250.00
	Cement Data Acquis	ition			job	1.00					250.00
:050	Cement Plug Contain	er			job	1.00					250.00
061	Service Supervisor				day	1.00					275.00
											-70.00

	· · · · · · · · · · · · · · · · · · ·										
		· · · · · · · · · · · · · · · · · · ·									
Custon	ner Section: On the	following scale or	r munici vo vector	luvuu vaa S							
		Tomorring 3 . ale: 10.	a would you rate i	minicane Services II					Net:	\$16,	543.00
Bas	ed on this job, how	likely is it you wo	uld recommend l	HSI to a colleague?		Total Taxable	\$ -	Tax Rate:		\geq	\leq
					ļ	State tax laws der used on new wells	s to be sales tax	exempt.	Sale Tax:	\$	<u> </u>
					ľ	well information al	bove to make a	ustomer provided determination if			
Grea	any I Z 3	4 5	6 7 8	9 10 Extra	mely Likely	services and/or pr	oducts are tax e	xempl.	Total:	\$ 16.5	43.00
						HSI Represe	ntative '	Mark Brung	andt		
RMS: Cash in advance	e unless Humicane Se	rvices Inc. (HSI) has	annroyed credit prior	to sale. Credit terms				The order	arat		

TERMS: Cash in advance unless Hurricane Services Inc. (HSI) has approved credit prior to sale. Credit terms of sale for approved accounts are total invoice due on or before the 30th day from the date of invoice. Past due accounts shall pay interest on the balance past due at the rate of 1 ½% per month or the maximum allowable by applicable state or federal laws. In the event it is necessary to employ an agency and/or attorney to affect the collection, Customer hereby agrees to pay all fees directly or indirectly incurred for such collection. In the event that Customer's account with HSI becomes delinquent, HSI has the fight to revoke any discount is price and subject to collection. Prices quoted are estimates only and are good for 30 days from the services. Any discount is based on 30 days net payment terms or cash. DISCLAIMER NOTICE: Technical data is presented in good faith, but no warranty is stated or implied. HSI assumes no liability for advice or purposes and HSI makes no guarantee of future production performance. Customer represents and warrants that well and all associated equipment in acceptable condition to receive services by HSI. Likewise, the customer guarantees proper operational care of all customer owned equipment and property white HSI is on location performing services. The authorization below acknowledges the receipt and acceptance of all terms/conditions stated above, and Hurricane has been provided accurate well information in determining taxable services.

CUSTOMER AUTHORIZATION SIGNATURE


ftv: 15-2021/01/25 mplv: 339-2022/10/05

Shelby Resources (JIB Account) Ledger Listing

01/01/2022 thru 12/31/2022

Date	Reference	Jrnl	Description	Invoice#	Amount	Quantity






ftv: 15-2021/01/25 mplv: 339-2022/10/05

Shelby Resources (JIB Account) Ledger Listing

01/01/2022 thru 12/31/2022

Date	Reference	Jrnl	Description	Invoice#	Amount	Quantity



Date	Reference Jrnl Description	Invoice#	Amount	Quantity	
9208-2105	Cementing & Services - L & M Unit # 1-33 < Continued>				
9208-2105	16,543.00 YTD Total	_	16,543.00 *		
9308-2105	Cementing & Services - L & M Unit # 1-33	0.00			
11/06/2022	15298 20 Hurricane Services Inc.	0364364	17,249.00	Bd 11/30/2022	
		Deck: 2.0			



Remit To: Hurricane Services, Inc. 250 N. Water, Suite 200

Wichita, KS 67202 316-303-9515

Customer:

SHELBY RESOURCES LLC 3700 QUEBEC STREET SUITE 100 PMB 376 DENVER, CO 80207-1639 | Invoice Date: 10/28/2022 | Invoice #: 0364364 | Lease Name: L-M Unit | Well #: 1-33 (New) | County: Pratt, Ks | Job Number: WP3561 | District: Pratt

Date/Description	HRS/QTY	Rate	Total
Pipe Job	0.000	0.000	0.00
H-H Long	200.000	45.000	9,000.00
H-Plug	100.000	14.000	1,400.00
Type B basket shoe 5 1/2"	1.000	1,500.000	1,500.00
5 1/2" LD Plug & Baffle	1.000	350.000	350.00
5 1/2" Turbolizers	8.000	125.000	1,000.00
Light Eq Mileage	10.000	2.000	20.00
Heavy Eq Mileage	20.000	4.000	80.00
Ton Mileage	136.000	1.500	204.00
Cement Blending & Mixing	300.000	1.400	420.00
Depth Charge 4001'-5000'	1.000	2,500.000	2,500.00
Cement Data Acquisition	1.000	250.000	250.00
Cement Plug Container	1.000	250.000	250.00
Service Supervisor	1.000	275.000	275.00

Total	 17,249.00

TERMS: Net 30 days. Interest may be charged on past due invoice at rate of 1 ½% per month or maximum allowed by applicable state or federal laws. HSI has right to revoke any discounts applied in arriving at net invoice price if invoice is past due. If revoked, full invoice price without discount plus additional sales tax, as applicable, is due immediately and subject to interest charges. Customer agrees to pay all collection costs directly or indirectly incurred by HSI in the event HSI engages a third party to pursue collection of past due invoice.

SALES TAX: Services performed on oil, gas and water wells in Kansas are subject to sales tax, with certain exceptions. HSI relies on the well information provided by the customer in identifying whether the services performed on wells qualify for exemption.

WE APPRECIATE YOUR BUSINESS!

Date	Reference	Jrnl	Description	Invoice#	Amount	Quantity

Hurricane Services, Inc. 250 N. Water St., Suite #200 Wichita, KS 67202



Customer	Shelby Resour	ces		Lea	se & We	eil#	L & N	Unit 1-	33				Date	1	0/28/2022
Service District	Pratt Kansas			Col	unty & S	tate F	Pratt	Kansas		Legals S/T/R	33-28	s-14w	Job#		
Job Type	Pipe job	Ø PRC	OD	O IN	j	C	sw	D		New Well?	Ø YES	O No	Ticket#		wp 3561
Equipment #	Driver						J	b Safet	y Ana	llysis - A Discuss	ion of Hazards	& Safety Pro	ocedures		
916	M Brungardt	☑ Har	d hat			8	3 Glo	ves			□ Lockout/Tag	out	□ Warning Sign	s & Flagging	
179/521	A Clifton	□ H25	Monitor			6	2 Eye	Protect	ion		D Required Per	rmits	☐ Fall Protection		
182/534	K Julian	☑ Safe	ety Footw	ear			3 Res	piratory	Prote	ction	@ Slip/Trip/Fall	Hazards	□ Specific Job S	iequence/Exp	ectations
		☑ FRC	/Protectiv	ve Cloth	ing	r) Add	litional (Chemi	ical/Acid PPE	❷ Overhead Ha	szards	Muster Point	/Medical Loca	itions
		□ Hea	ring Prote	ection		£	3 Fire	Extingu	isher		D Additional co	oncems or iss	ues noted below		
										Con	nments				
				,											
Product/ Service Code			Des	cription	n					Unit of Measure	Quantity				Net Amoun
032	HH-Long									sack	200.00				\$9,000.
055	H-Plug A									sack	100.00			1	\$1,400.
160	5 1/2"Type B Ba	sket Shoe								ea	1.00			1	\$1,500.
170	5 1/2" Laich Dov	vn Plug & (3affle							ea	1.00				\$350.
135	5 1/2 Turbolizer									ea	8.00				\$1,000.
015	Light Equipment	Mileage								mi	10.00				\$20.
010	Heavy Equipmen	nt Mileage								mi	20.00				\$80.
020	Ton Mileage									tm	136.00			I	\$204.
160	Cement Blending	g & Mixing	Service						\perp	sack	300.00			1	\$420.
)15	Depth Charge: 4	001'-5000'							\perp	job	1.00				\$2,500.
	Cement Data Ac	quisition							_	job	1.00				\$250.0
	Cement Plug Co	ntainer							_	job	1.00	ļ			\$250.
61	Service Supervis	or							_	day	1.00			<u> </u>	\$275.
									_				·		
									_			_		<u> </u>	
									_			<u> </u>		ļ	
														<u> </u>	
									_			ļ		 	***************************************
												ļ		<u> </u>	
									\dashv			ļ			_
									-+			 	ļ	 	
	·								\dashv						
Custo	mer Section: Or	n the tollow	and scale	how we	add vour	at. Hi	.0.00	ne Sew	r ve te	nc ?		L			
			-1-2-000					Je V			Total Taxable	.	Tax Rate:	Net:	\$17,249.0
Ba	sed on this job,	how likely	is it you	would	recomm	end H	SI to	a colle	ague?)			lax Rate: lucts and services	Sale Tax:	
			0 0	6			9	10		mely Likely	used on กลพ wells	s to be sales ta s relies on the bove to make a	x exempt. customer provided determination if	Total:	\$ - \$ 17,249.0
					-						HSI Represe				·

TERMIS: Cash in advance unless Hurricane Services inc. (HSI) has approved credit prior to sate. Credit terms of sale for approved accounts are total invoice due on or before the 30th day from the date of invoice. Past due accounts shall pay interest on the belance past due at the rate of 1 ½% per month or the maximum allowable by applicable state or federal laws. In the event it is necessary to employ an agency and/or attorney to affect the collection, Oustomer hereby agrees to pay all fees directly or indirectly incurred for such collection. In the event that Customer's account with HSI becomes definiquent, HSI has the right to revoke any discounts previously applied in arriving at net invoice price. Upon revocation, the full invoice price without discount is immediately due and subject to collection. Prices quoted are estimates only and are good for 30 days from the date of issue. Pricing does not include federal, state, or total taxes, or royalties and stated price adjustments. Actual charges may vary depending upon time, equipment, and material ultimately required to perform these services. Any discount is based on 30 days not payment terms or cash. <u>DISCLAIMER NOTICE</u>: Technical data is presented in good faith, but no warranty is stated or implied. HSI assumes no liability for advice or recommendations made concerning the results from the use of any product or service. The information presented is a best estimate of the actual results that may be achieved and should be used for comparison purposes and HSI makes no guarantee of future production performance. Customer represents and warrents that well and all associated equipment in acceptable condition to receive services by HSI. Likewise, the customer guarantees proper operational care of all customer owned equipment and property while HSI is on location performing services. The authorization below acknowledges the receipt and acceptables services.

CUSTOMER AUTHORIZATION SIGNATURE

ftv: 15-2021/01/25 mplv: 339-2022/10/05

Date	Reference	Jrnl Description	Invoice#	Amount	Quantity




271211										
		ATMEN								
Customer: Shelby Resources			ces	Well:	L & M Unit 1-33		Ticket:	wp 3561		
City, State: Coats Kansas					County:	Pratt.Kansas		Date:	10/28/2022	
Field Rep: Chris Gottschalk			lk	S-T-R: 33-28s-14w		Service:	Pipe job			
Dow	nhole (nformati	on		Calculated Six	rry - Lead		Calcu	lated Slurry - Tail	
Hole Size: 7 7/8 in			Blend: H plug			Blend: H long				
Hole Depth: 4944 ft			Weight:	18.7 ppg		Weight:	15 ppg			
Casing Size: 5 1/2 in			Water / S		6.9 gal/sx		Water / Sx:	6.0 gal / sx		
			4743 ft		Yield:	1,43 ft ³ /sx		Yield:	1.42 ft ³ / sx	
Tubing / Liner		in			Annular Bbls / Ft.:	bbs / ft.		Annular Bbls / Ft.:	bbs / ft.	
Depth:		ft			Depth:	ft		Depth:	ft	
Tool / Packer:		***************************************			Annular Volume:	0.0 bbls		Annular Volume:	0 bbls	
Tool Depth:		ft			Excess:			Excess:		
Displacement:		aldd			Total Slurry:	12.7 bbls		Total Slurry:	50.0 bbls	
			STAGE	TOTAL	Total Sacks:	50 sx		Total Sacks:	200 sx	
TIME	RATE	PSI	BBLs	BBLs	REMARKS					
12:30 AM			┝╌┤		on location job and safet	<u> </u>				
12:40 AM				-	spot trucks and rig up					
			 	-	turbolizers 3,6,9,12,15,	18,31,35				
1:35 AM			 		start casing in the hole					
4:20 AM					on bottom and circulatin					
4.20 AIII					On bottom and circulation	я				
5:00 AM	2.0		12.7	12.7	plug rat hole 30 sacks p	olun mouse hole 20 sac	ks	· · · · · · · · · · · · · · · · · · ·		
					ping tax inside	3				
5:15 AM				-	start cement down hole				· · · · · · · · · · · · · · · · · · ·	
	4.5	300.0	12.0	12.0	mix 50 sacks scavenger					
	6.5	270.0	50.0		mix 200 sacks tail					
5:30 AM					cement in					
					wash pump and lines an	d release the plug				
5:35 AM					start displacement			· · · · · · · · · · · · · · · · · · ·		
	6.0	170.0	20.0							
	6.0	170.0	40.0				·			
	6.0	170.0	60.0							
	6.0	450.0 600.0	70.0 80.0							
	6.0	850.0	90.0			·				
	5.0	826.0	100.0							
	3.0	800.0	105.0	44,451154						
6:00 AM		1,000.0		***************************************	plug down,,,,,,,1000 to 15	500 psi				
					float did hold	4				
									· · · · · · · · · · · · · · · · · · ·	
		CREW			UNIT			SUMMARY		
Cementer:		M Brungardt			916	Averag	e Rate	Average Pressure	Total Fluid	
Pump Operator:		A Clifton			179/521	4.9	bpm	467 psi	755 bbls	
	uik #1:	K Ju	lian		182/534					
В	ulk #2:									

ftv: 15-2021/01/25 mplv: 339-2022/10/05

Shelby Resources (JIB Account) Ledger Listing

01/01/2022 thru 12/31/2022

		0 1/ 0 1/ 2022 11 11 12 12/ 0 1/ 2022			
Date	Reference	Jrnl Description	Invoice#	Amount	Quantity



03/15/2023 04:11 pm Company:1SHEL

Shelby Resources (JIB Account) Ledger Listing

01/01/2022 thru 12/31/2022

01/01/2022 tilld 12/01/2022							
Date	Reference	Jrnl Description	Invoice#	Amount	Quantity		
9308-2105	Cementing & S	ervices - L & M Unit # 1-33 <continued></continued>					
9308-2105	17,249.00	YTD Total		17,249.00 *			

Grand Total= 33,792.00 #Detail: 2, #Accounts:0

33,792.00

Page 9

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Laura Kelly, Governor

Susan K. Duffy, Chair Dwight D. Keen, Commissioner Andrew J. French, Commissioner

March 16, 2023

Trey Mallon Shelby Resources LLC 3700 QUEBEC STREET SUITE 100 PMB 376 DENVER, CO 80207-1639

Re: ACO-1 API 15-151-22555-00-00 L & M UNIT 1-33 SW/4 Sec.33-28S-14W Pratt County, Kansas

Dear Trey Mallon:

K.A.R. 82-3-107 provides for all completion information to be filed within 120 days of the spud date. Subsection(e)(2) of that regulation states "All rights to confidentiality shall be lost if the filings are not timely."

The above referenced well was spudded on 10/14/2022 and the ACO-1 was received on March 15, 2023 (not within the 120 days timely requirement).

Therefore, your request for confidential treatment of data contained within the ACO-1 filing cannot be granted at this time.

If you should have any questions, please do not hesitate to contact me at (316)337-6200.

Sincerely,

Production Department