## KOLAR Document ID: 1721930

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recovery: KCC District No.:	API No.:		Permit No.:
Operator License No.: Name:		 c Twp	S. R East West
Address 1:			
Address 2:		Feet from	East / West Line of Section
City: State: Zip:+	Lease:		Well No.:
Contact Person: Phone: ( )			
Well Construction Details: New well Existing well with change	ges to construction 🔲 Existing we	Il with no change	s to construcion
Maximum Authorized Injection Pressure:psi Max	ximum Injection Rate:	bbl/d	
Conductor Surface Intern	mediate Production	Liner	Tubing
Size:			Size:
Set at:			Set at:
Sacks of Cement:			Туре:
Cement Top:			
Cement Bottom:			
Packer Type:		_ Set at:	
DV Tool Port Collar Depth of: feet with	sacks of cement TD (and p	lug back):	feet depth
			_ Perf. or Open Hole:
Is there a Chemical Sealant or a Mechanical Casing patch in the annula			
	MIT Peas	son:	Date Acquired:
MIT Type:			
Time in Minute(s):			
Pressures: Set up 1			
Set up 2			
·			
Tested: Casing or Casing - Tubing Annulus System			. to load annulus:
Test Date: Using:			Company's Equipment
The zone tested for this well is between feet and	feet.		
The test results were verified by operator's representative:			
Name:	Title:	Phone: (	()
· · · · · · · · · · · · · · · · · · ·			
KCC Office Use Only     State Agent:	Title:		Witness: Yes No
KCC Office Use Only State Agent:   The results were: Remarks:			
The results were: Remarks:			
The results were: Remarks:			
The results were: Remarks: Satisfactory Not Satisfactory			

Form U-7 August 2019 Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720

Susan K. Duffy, Chair Dwight D. Keen, Commissioner Andrew J. French, Commissioner



Phone: 620-902-6450 http://kcc.ks.gov/

Laura Kelly, Governor

## FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

07/18/2023

LICENSE 33215 Taylor, Robert W. dba Taylor Oil Co. PO BOX 894 EL DORADO, KS 67042-0894

Re: API No. 15-073-22049-00-02 Permit No. D30160.0 HIGBEE 3 17-28S-11E Greenwood County, KS

Operator:

On 07/17/2023, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

1) repair and retest the well to show mechanical integrity,

2) plug the well, or

3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

## Failure to comply with K.A.R. 82-3-407(c) by 10/15/2023 shall be punishable by a \$1, 000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Duane Sims KCC District #3