KOLAR Document ID: 1644531

Confidentiality Requested:

Yes No

#### Kansas Corporation Commission Oil & Gas Conservation Division

Form ACO-1
January 2018
Form must be Typed
Form must be Signed
All blanks must be Filled

## WELL COMPLETION FORM WELL HISTORY - DESCRIPTION OF WELL & LEASE

OPERATOR: License #	API No.:			
Name:	Spot Description:			
Address 1:	SecTwpS. R East _ West			
Address 2:	Feet from North / South Line of Section			
City: State: Zip:+	Feet from East / West Line of Section			
Contact Person:	Footages Calculated from Nearest Outside Section Corner:			
Phone: ()	□NE □NW □SE □SW			
CONTRACTOR: License #	GPS Location: Lat:, Long:			
Name:	(e.g. xx.xxxxxx) (e.gxxx.xxxxxx)			
Wellsite Geologist:	Datum: NAD27 NAD83 WGS84			
Purchaser:	County:			
Designate Type of Completion:	Lease Name: Well #:			
New Well Re-Entry Workover	Field Name:			
	Producing Formation:			
☐ Oil ☐ WSW ☐ SWD	Elevation: Ground: Kelly Bushing:			
☐ Gas ☐ DH ☐ EOR	Total Vertical Depth: Plug Back Total Depth:			
☐ OG ☐ GSW	Amount of Surface Pipe Set and Cemented at: Feet			
CM (Coal Bed Methane)	Multiple Stage Cementing Collar Used? Yes No			
Cathodic Other (Core, Expl., etc.):				
If Workover/Re-entry: Old Well Info as follows:	If yes, show depth set: Feet			
Operator:	If Alternate II completion, cement circulated from:			
Well Name:	feet depth to: sx cmt.			
Original Comp. Date: Original Total Depth:				
☐ Deepening ☐ Re-perf. ☐ Conv. to EOR ☐ Conv. to SWD	Drilling Fluid Management Plan			
☐ Plug Back ☐ Liner ☐ Conv. to GSW ☐ Conv. to Producer	(Data must be collected from the Reserve Pit)			
Commingled Permit #:	Chloride content:ppm Fluid volume:bbls			
Dual Completion Permit #:	Dewatering method used:			
SWD Permit #:	Location of fluid disposal if hauled offsite:			
☐ EOR Permit #:	Location of fluid disposal if fladica offsite.			
GSW Permit #:	Operator Name:			
_	Lease Name: License #:			
Spud Date or Date Reached TD Completion Date or	QuarterSecTwpS. R East West			
Recompletion Date Recompletion Date	County: Permit #:			

#### **AFFIDAVIT**

I am the affiant and I hereby certify that all requirements of the statutes, rules and regulations promulgated to regulate the oil and gas industry have been fully complied with and the statements herein are complete and correct to the best of my knowledge.

**Submitted Electronically** 

KCC Office Use ONLY						
Confidentiality Requested						
Date:						
Confidential Release Date:						
Wireline Log Received Drill Stem Tests Received						
Geologist Report / Mud Logs Received						
UIC Distribution						
ALT I II Approved by: Date:						

KOLAR Document ID: 1644531

#### Page Two

Operator Name: _				Lease Name:			Well #:	
Sec Twp.	S. R.	E	ast West	County:				
	flowing and shu	ut-in pressures, v	vhether shut-in pre	ssure reached st	atic level, hydrosta	tic pressures, bot		val tested, time tool erature, fluid recovery,
Final Radioactivity files must be subm						iled to kcc-well-lo	gs@kcc.ks.gov	v. Digital electronic log
Drill Stem Tests Ta			Yes No			on (Top), Depth ar		Sample
Samples Sent to 0	Geological Surv	/ey	Yes No	Na	me		Тор	Datum
Cores Taken Electric Log Run Geologist Report / List All E. Logs Ru	_		Yes No Yes No Yes No					
		B	CASING eport all strings set-c		New Used	ion, etc.		
Purpose of Strir		Hole illed	Size Casing Set (In O.D.)	Weight Lbs. / Ft.	Setting Depth	Type of Cement	# Sacks Used	Type and Percent Additives
			ADDITIONAL	CEMENTING / SO	UEEZE RECORD			
Purpose:		epth T Bottom	ype of Cement	# Sacks Used Type and Percent Additives				
Perforate Protect Casi Plug Back T								
Plug Off Zor								
Did you perform a     Does the volume     Was the hydraulic	of the total base f	fluid of the hydrauli		_	=	No (If No, sk	ip questions 2 an ip question 3) out Page Three	,
Date of first Product Injection:	tion/Injection or R	esumed Production	Producing Meth	nod:	Gas Lift 0	Other (Explain)		
Estimated Production Per 24 Hours	on	Oil Bbls.					Gas-Oil Ratio	Gravity
DISPOS	SITION OF GAS:		N	METHOD OF COMP	LETION:			DN INTERVAL: Bottom
	Sold Used	I on Lease	Open Hole			mmingled mit ACO-4)	Тор	BOROTT
,	,			B.11 B1				
Shots Per Foot	Perforation Top	Perforation Bottom	Bridge Plug Type	Bridge Plug Set At	Acid,	Fracture, Shot, Cer (Amount and Kind	menting Squeeze I of Material Used)	Record
TUBING RECORD:	: Size:	Set	Δ+-	Packer At:				
TODING RECORD:	. 3126.		n.	i donei Al.				

Form	ACO1 - Well Completion			
Operator	Shelby Resources LLC			
Well Name	VANWINKLE #1-1			
Doc ID	1644531			

#### Casing

Purpose Of String	Size Hole Drilled	Size Casing Set	Weight	Setting Depth	Type Of Cement		Type and Percent Additives
Surface	12.25	8.625	23	777	60/40 Poz	350	4%cc/2%g el

Shelby Resouces LLC

1-18S-14W Barton,KS



#### DRILL STEM TEST REPORT

Prepared For: Shelby Resouces LLC

3700 Quebec St Suite 100 PMB 376 Denver CO 80207

ATTN: Jeremy Schwartz

#### Van Winkle #1-1

#### 1-18S-14W Barton,KS

Start Date: 2022.04.15 @ 02:11:44 End Date: 2022.04.15 @ 09:43:04 Job Ticket #: 68932 DST #: 1

Trilobite Testing, Inc PO Box 362 Hays, KS 67601

ph: 785-625-4778 fax: 785-625-5620



Shelby Resouces LLC

1-18S-14W Barton,KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68932

Tester:

Unit No:

DST#: 1

ATTN: Jeremy Schwartz Test Start: 2022.04.15 @ 02:11:44

#### **GENERAL INFORMATION:**

Formation: LKC A - F

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Initial)

Time Tool Opened: 04:08:54
Time Test Ended: 09:43:04

Interval: 3099.00 ft (KB) To 3170.00 ft (KB) (TVD)

Total Depth: 3170.00 ft (KB) (TVD)

Hole Diameter: 7.88 inches Hole Condition: Poor

Reference Bevations: 1840.00 ft (KB)

Eric Burgess

80

e Elevations: 1840.00 ft (KB) 1832.00 ft (CF)

KB to GR/CF: 8.00 ft

Serial #: 8369 Outside

Press@RunDepth: 53.53 psig @ 3106.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.04.15
 End Date:
 2022.04.15
 Last Calib.:
 2022.04.15

 Start Time:
 02:11:45
 End Time:
 09:43:04
 Time On Btm:
 2022.04.15 @ 04:08:04


Time Off Btm: 2022.04.15 @ 07:34:44

TEST COMMENT: IF:Fair Building Blow built to 5" in bucket (15)

ISI:No Blow Back (45)

FF:Weak Building Blow built to .25" in bucket (45)

FSI:No Blow Back (90)



Р	RESSUR	RE SI	JMMA	RY

Time	Pressure	Temp	Annotation
(Min.)	(psig)	(deg F)	
0	1480.58	92.05	Initial Hydro-static
1	52.76	92.10	Open To Flow (1)
20	51.56	93.31	Shut-In(1)
64	730.82	93.85	End Shut-In(1)
65	54.39	93.51	Open To Flow (2)
113	53.53	94.51	Shut-In(2)
205	729.81	96.93	End Shut-In(2)
207	1457.24	97.33	Final Hydro-static

#### Recovery

Length (ft)	Description	Volume (bbl)
63.00	M 100%M	0.61
		·

#### Gas Rates

	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)
--	----------------	-----------------	------------------

Trilobite Testing, Inc Ref. No: 68932 Printed: 2022.04.19 @ 16:21:33



Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68932

DST#: 1

ATTN: Jeremy Schwartz

Test Start: 2022.04.15 @ 02:11:44

#### **GENERAL INFORMATION:**

Formation: LKC A-F

Deviated: Test Type: Conventional Bottom Hole (Initial) No Whipstock: ft (KB)

Time Tool Opened: 04:08:54 Time Test Ended: 09:43:04

Unit No: 80

Tester: Eric Burgess

1840.00 ft (KB)

3099.00 ft (KB) To 3170.00 ft (KB) (TVD)

Reference Bevations:

1832.00 ft (CF)

Total Depth: 3170.00 ft (KB) (TVD) Hole Diameter: 7.88 inches Hole Condition: Poor

KB to GR/CF: 8.00 ft

Serial #: 8846 Press@RunDepth: Outside

psig @

3106.00 ft (KB)

2022.04.15

Capacity: Last Calib.:

8000.00 psig

Start Date:

2022.04.15

End Date:

Time On Btm:

1899.12.30

Start Time:

Interval:

02:11:14

End Time:

09:42:33


Time Off Btm:

TEST COMMENT: IF:Fair Building Blow built to 5" in bucket (15)

ISI:No Blow Back (45)

FF:Weak Building Blow built to .25" in bucket (45)

FSI:No Blow Back (90)



#### PRESSURE SUMMARY

1	Time	Pressure	Temp	Annotation
-	(Min.)	(psig)	(deg F)	
-	(17111.)	(psig)	(deg i )	
-				
-				
-				
-				
.				
5				
-				
-				
-				
-				
-				
-				
-				

#### Recovery

Length (ft)	Description	Volume (bbl)
63.00	M 100%M	0.61

#### Gas Rates

Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Ref. No: 68932 Trilobite Testing, Inc Printed: 2022.04.19 @ 16:21:34



**TOOL DIAGRAM** 

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Van Winkle #1-1

Denver CO 80207

Job Ticket: 68932 DST#: 1

ATTN: Jeremy Schwartz

Test Start: 2022.04.15 @ 02:11:44

**Tool Information** 

Drill Collar:

Drill Pipe: Length: 3062.00 ft Diameter: Heavy Wt. Pipe: Length: 0.00 ft Diameter:

Length:

3.80 inches Volume: 42.95 bbl 0.00 inches Volume: 0.00 bbl 2.25 inches Volume: 0.15 bbl

Total Volume:

43.10 bbl

Tool Weight: 2000.00 lb Weight set on Packer: 24000.00 lb Weight to Pull Loose: 40000.00 lb

Drill Pipe Above KB: 24.00 ft

Tool Chased 12.00 ft

Depth to Top Packer: 3099.00 ft
Depth to Bottom Packer: ft

String Weight: Initial 42000.00 lb

Interval between Packers: 71.00 ft

Final 42000.00 lb

Tool Length: 102.00 ft Number of Packers: 2

2 Diameter: 6.75 inches

30.00 ft Diameter:

Tool Comments:

Tool Description	Length (ft)	Serial No.	Position	Depth (ft)	Accum. Lengths	
Change Over Sub	1.00			3069.00		
Shut In Tool	5.00			3074.00		
Hydraulic tool	5.00			3079.00		
EM TOOL	3.00			3082.00		
Jars	5.00			3087.00		
Safety Joint	3.00			3090.00		
Packer	4.00			3094.00	31.00	Bottom Of Top Packer
Packer	5.00			3099.00		
Stubb	1.00			3100.00		
Perforations	5.00			3105.00		
Change Over Sub	1.00			3106.00		
Recorder	0.00	8369	Outside	3106.00		
Recorder	0.00	8846	Outside	3106.00		
Blank Spacing	31.00			3137.00		
Change Over Sub	1.00			3138.00		
Perforations	29.00			3167.00		
Bullnose	3.00			3170.00	71.00	Bottom Packers & Anchor

Total Tool Length: 102.00

Trilobite Testing, Inc Ref. No: 68932 Printed: 2022.04.19 @ 16:21:35



**FLUID SUMMARY** 

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68932

DST#: 1

ATTN: Jeremy Schwartz

Test Start: 2022.04.15 @ 02:11:44

#### **Mud and Cushion Information**

Mud Type:Gel ChemCushion Type:Oil API:deg APIMud Weight:10.00 lb/galCushion Length:ftWater Salinity:ppm

Viscosity: 28.00 sec/qt Cushion Volume: bbl

Water Loss: in<sup>3</sup> Gas Cushion Type:

Resistivity: ohm.m Gas Cushion Pressure: psig

Salinity: 48000.00 ppm Filter Cake: 0.20 inches

#### **Recovery Information**

#### Recovery Table

Length ft	Description	Volume bbl
63.00	M 100%M	0.610


Total Length: 63.00 ft Total Volume: 0.610 bbl


Num Fluid Samples: 0 Num Gas Bombs: 0 Serial #:

Laboratory Name: Laboratory Location:

Recovery Comments:

Trilobite Testing, Inc Ref. No: 68932 Printed: 2022.04.19 @ 16:21:35







Prepared For: Shelby Resouces LLC

3700 Quebec St Suite 100 PMB 376 Denver CO 80207

ATTN: Jeremy Schwartz

#### Van Winkle #1-1

#### 1-18S-14W Barton,KS

Start Date: 2022.04.16 @ 00:35:00 End Date: 2022.04.16 @ 05:54:00 Job Ticket #: 68933 DST #: 2

Trilobite Testing, Inc PO Box 362 Hays, KS 67601

ph: 785-625-4778 fax: 785-625-5620



Shelby Resouces LLC

ATTN: Jeremy Schwartz

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68933

DST#: 2

Test Start: 2022.04.16 @ 00:35:00

#### **GENERAL INFORMATION:**

Formation: LKC H-K

Deviated: No Whipstock: ft (KB)

Outside

Time Tool Opened: 02:38:20 Time Test Ended: 05:54:00

3222.00 ft (KB) To 3305.00 ft (KB) (TVD)

Total Depth: 3305.00 ft (KB) (TVD)

Hole Diameter: 7.88 inches Hole Condition: Test Type: Conventional Bottom Hole (Reset)

Tester: Unit No: 80

Eric Burgess

Reference Bevations:

1840.00 ft (KB)

1832.00 ft (CF) KB to GR/CF: 8.00 ft

Serial #: 8369

Interval:

Press@RunDepth: 63.17 psig @

Start Date: 2022.04.16 Start Time: 00:35:01

3229.00 ft (KB) End Date:

End Time:

Capacity: Last Calib.: 2022.04.16

05:54:00

8000.00 psig

Time On Btm:


2022.04.16 2022.04.16 @ 02:37:40

Time Off Btm:

2022.04.16 @ 03:59:40

TEST COMMENT: IF:Blow Died Flushed tool per geo and shut in tool (15)

ISI:No Blow Back (45) FF:No Blow pulled tool



Time	Pressure	Temp	Annotation
(Min.)	(psig)	(deg F)	
0	1589.03	95.35	Initial Hydro-static
1	63.49	95.13	Open To Flow (1)
9	63.17	95.32	Shut-In(1)
54	514.33	96.42	End Shut-In(1)
54	64.33	96.21	Open To Flow (2)
82	1531.90	99.18	Final Hydro-static

PRESSURE SUMMARY

#### Recovery

Length (ft)	Description	Volume (bbl)			
75.00	M 100%M	0.78			
* Recovery from multiple tests					

Gas Rates Choke (inches) Pressure (psig) Gas Rate (Mcf/d)

Ref. No: 68933 Printed: 2022.04.19 @ 16:21:04 Trilobite Testing, Inc



Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68933

DST#: 2

ATTN: Jeremy Schwartz

Test Start: 2022.04.16 @ 00:35:00

GENERAL INFORMATION:

Formation: LKC H-K

Deviated: No Whipstock: ft (KB)

Time Tool Opened: 02:38:20 Time Test Ended: 05:54:00

Interval:

3222.00 ft (KB) To 3305.00 ft (KB) (TVD)

Total Depth: 3305.00 ft (KB) (TVD)

Hole Diameter: 7.88 inches Hole Condition:

Unit No: 80

Reference Bevations: 1840.00 ft (KB)

Eric Burgess

Test Type: Conventional Bottom Hole (Reset)

1832.00 ft (CF)

8000.00 psig

KB to GR/CF: 8.00 ft

Serial #: 8846 Outside

Press@RunDepth: psig @ 3229.00 ft (KB)

Start Date: 2022.04.16 End Date: 2022.04.16 Last Calib.: 1899.12.30

 Start Time:
 00:35:52
 End Time:
 05:55:51
 Time On Btm:

Time Off Btm:

Capacity:

Tester:

TEST COMMENT: IF:Blow Died Flushed tool per geo and shut in tool (15)

ISI:No Blow Back (45) FF:No Blow pulled tool

				PI	RESSUR	E SUMMARY	
			Time (Min.)	Pressure (psig)	Temp (deg F)	Annotation	
Recovery				Gas	Rates		
Length (ft)	Description	Volume (bbl)			Choke (in	ches) Pressure (psig)	Gas Rate (Mcf/d)
75.00	M 100%M	0.78					·

# Length (ft) Description Volume (bbl) 75.00 M 100%M 0.78

\* Recovery from multiple tests

Trilobite Testing, Inc Ref. No: 68933 Printed: 2022.04.19 @ 16:21:05



**TOOL DIAGRAM** 

DST#: 2

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Van Winkle #1-1

Denver CO 80207

ATTN: Jeremy Schwartz

Job Ticket: 68933

String Weight: Initial 44000.00 lb

Final 44000.00 lb

Test Start: 2022.04.16 @ 00:35:00

**Tool Information** 

Drill Pipe: Length: 3188.00 ft Diameter: 3.80 inches Volume: 44.72 bbl Tool Weight: 2000.00 lb 0.00 inches Volume: 0.00 bbl Heavy Wt. Pipe: Length: 0.00 ft Diameter: Weight set on Packer: 24000.00 lb Drill Collar: Length: 30.00 ft Diameter: 2.25 inches Volume: 0.15 bbl Weight to Pull Loose: 40000.00 lb Total Volume: 44.87 bbl Tool Chased 25.00 ft

Drill Pipe Above KB: 27.00 ft
Depth to Top Packer: 3222.00 ft

Depth to Bottom Packer: ft Interval betw een Packers: 83.00 ft Tool Length: 114.00 ft

Number of Packers: 2 Diameter: 6.75 inches

Tool Comments:

Tool Description	Length (ft)	Serial No.	Position	Depth (ft)	Accum. Lengths	
Change Over Sub	1.00			3192.00		
Shut In Tool	5.00			3197.00		
Hydraulic tool	5.00			3202.00		
EM TOOL	3.00			3205.00		
Jars	5.00			3210.00		
Safety Joint	3.00			3213.00		
Packer	4.00			3217.00	31.00	Bottom Of Top Packer
Packer	5.00			3222.00		
Stubb	1.00			3223.00		
Perforations	5.00			3228.00		
Change Over Sub	1.00			3229.00		
Recorder	0.00	8369	Outside	3229.00		
Recorder	0.00	8846	Outside	3229.00		
Blank Spacing	63.00			3292.00		
Change Over Sub	1.00			3293.00		
Perforations	9.00			3302.00		
Bullnose	3.00			3305.00	83.00	Bottom Packers & Anchor

Total Tool Length: 114.00

Trilobite Testing, Inc Ref. No: 68933 Printed: 2022.04.19 @ 16:21:06



**FLUID SUMMARY** 

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68933

DST#: 2

ATTN: Jeremy Schwartz

Test Start: 2022.04.16 @ 00:35:00

#### **Mud and Cushion Information**

Mud Type:Gel ChemCushion Type:Oil API:deg APIMud Weight:9.00 lb/galCushion Length:ftWater Salinity:ppm

Viscosity: 59.00 sec/qt Cushion Volume: bbl

Water Loss: 5.79 in<sup>3</sup> Gas Cushion Type:

Resistivity: ohm.m Gas Cushion Pressure: psig

Salinity: 7500.00 ppm Filter Cake: 0.20 inches

#### **Recovery Information**

#### Recovery Table

Length ft	Description	Volume bbl
75.00	M 100%M	0.779

Total Length: 75.00 ft Total Volume: 0.779 bbl


Num Fluid Samples: 0 Num Gas Bombs: 0


Laboratory Name: Laboratory Location:

Recovery Comments:

Serial #:

Trilobite Testing, Inc Ref. No: 68933 Printed: 2022.04.19 @ 16:21:06







Prepared For: Shelby Resouces LLC

3700 Quebec St Suite 100 PMB 376 Denver CO 80207

ATTN: Jeremy Schwartz

#### Van Winkle #1-1

#### 1-18S-14W Barton, KS

Start Date: 2022.04.16 @ 21:52:26 End Date: 2022.04.17 @ 05:36:46 Job Ticket #: 68934 DST #: 3

Trilobite Testing, Inc
PO Box 362 Hays, KS 67601

ph: 785-625-4778 fax: 785-625-5620



Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

over CO 80207 Job

Job Ticket: 68934

DST#: 3

ATTN: Jeremy Schwartz

Test Start: 2022.04.16 @ 21:52:26

#### **GENERAL INFORMATION:**

Formation: Arbuckle

Deviated: No Whipstock: ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 00:10:26 Time Test Ended: 05:36:46 Tester: Eric Burgess
Unit No: 80

Reference Bevations:

Last Calib.:

36:46 Unit No:

1840.00 ft (KB)

Total Depth: 3354.00 ft (KB) (TVD)
Hole Diameter: 7.88 inches Hole Condition: Fair

1832.00 ft (CF) KB to GR/CF: 8.00 ft

Tole Danielei. 7.00 inches note Condition. Fail

Outside

Serial #: 8369

Press@RunDepth:

Interval:

117.11 psig @ 3300.00 ft (KB)

3298.00 ft (KB) To 3354.00 ft (KB) (TVD)

Capacity: 8000.00 psig

Start Date: 2022.04.16 End Date:

2022.04.17 05:36:46 2022.04.16 2022.04.17 @ 00:09:36

Start Time: 21:52:27 End Time:


Time On Btm: 2022.04.17 @ 00:09:36 Time Off Btm: 2022.04.17 @ 03:17:05

TEST COMMENT: IF:Fair Building Blow built to 5.25" in bucket (15)

ISI:No Blow Back (45)

FF:Fair Building Blow built 9" in bucket (60)

FSI:No Blow Back (60)



PRESSURE SUMMARY
------------------

Time	Pressure	Temp	Annotation
(Min.)	(psig)	(deg F)	
0	1605.34	93.18	Initial Hydro-static
1	43.85	94.20	Open To Flow (1)
16	60.31	98.85	Shut-In(1)
61	1147.19	98.77	End Shut-In(1)
62	61.77	98.72	Open To Flow (2)
121	117.11	108.45	Shut-In(2)
186	1145.42	105.56	End Shut-In(2)
188	1602.31	105.49	Final Hydro-static

#### Recovery

Length (ft)	Description	escription Volume (bbl)			
63.00	MCW 15%M 85%W	0.61			
63.00 MCW 5%M 95%W 63.00 WCM 55%M 45%W		0.88			
		0.88			
31.00	WCM 65%M 35%W	0.43			
* Recovery from multiple tests					

#### Gas Rates

Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)
----------------	-----------------	------------------

Trilobite Testing, Inc Ref. No: 68934 Printed: 2022.04.19 @ 16:20:32



Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68934

DST#: 3

ATTN: Jeremy Schwartz Test Start: 2022.04.16 @ 21:52:26

2022.04.17

05:37:37

#### **GENERAL INFORMATION:**

Formation: **Arbuckle** 

Deviated: No Whipstock: ft (KB)

Time Tool Opened: 00:10:26 Time Test Ended: 05:36:46

Interval:

3298.00 ft (KB) To 3354.00 ft (KB) (TVD)

Total Depth: 3354.00 ft (KB) (TVD)

Hole Diameter: 7.88 inches Hole Condition: Fair Test Type: Conventional Bottom Hole (Reset)

Eric Burgess

80

Unit No:

Reference Bevations:

1840.00 ft (KB)

1832.00 ft (CF)

KB to GR/CF: 8.00 ft

Serial #: 8846 Outside

Press@RunDepth: 3300.00 ft (KB) psig @

Start Date: 2022.04.16 End Date:

Start Time: 21:52:58 End Time:

Capacity: Last Calib.:

Tester:

8000.00 psig

1899.12.30


Time On Btm: Time Off Btm:

TEST COMMENT: IF:Fair Building Blow built to 5.25" in bucket (15)

ISI:No Blow Back (45)

FF:Fair Building Blow built 9" in bucket (60)

FSI:No Blow Back (60)



-	Time	Pressure	Temp	Annotation
				Alliotation
	(Min.)	(psig)	(deg F)	
,				
ì				
,				

#### Recovery

Length (ft)	Description	Volume (bbl)
63.00	MCW 15%M 85%W	0.61
63.00	MCW 5%M 95%W	0.88
63.00	WCM 55%M 45%W	0.88
31.00	WCM 65%M 35%W	0.43
* Recovery from mult	inle teete	

#### Gas Rates

	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)	
--	----------------	-----------------	------------------	--

Ref. No: 68934 Printed: 2022.04.19 @ 16:20:33 Trilobite Testing, Inc



**TOOL DIAGRAM** 

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Van Winkle #1-1

Denver CO 80207

ATTN: Jeremy Schwartz

Job Ticket: 68934 **DST#: 3** 

String Weight: Initial 44000.00 lb

Final 44000.00 lb

Test Start: 2022.04.16 @ 21:52:26

**Tool Information** 

Drill Pipe: Length: 3251.00 ft Diameter: 3.80 inches Volume: 45.60 bbl Tool Weight: 2000.00 lb 0.00 inches Volume: 0.00 bbl Heavy Wt. Pipe: Length: 0.00 ft Diameter: Weight set on Packer: 24000.00 lb Drill Collar: Length: 30.00 ft Diameter: 2.25 inches Volume: 0.15 bbl Weight to Pull Loose: 24000.00 lb Total Volume: 45.75 bbl Tool Chased 4.00 ft

Drill Pipe Above KB: 14.00 ft
Depth to Top Packer: 3298.00 ft

Depth to Bottom Packer: ft
Interval betw een Packers: 56.00 ft
Tool Length: 87.00 ft

Number of Packers: 2 Diameter: 6.75 inches

Tool Comments:

Tool Description	Length (ft)	Serial No.	Position	Depth (ft)	Accum. Lengths	
Change Over Sub	1.00			3268.00		
Shut In Tool	5.00			3273.00		
Hydraulic tool	5.00			3278.00		
EM TOOL	3.00			3281.00		
Jars	5.00			3286.00		
Safety Joint	3.00			3289.00		
Packer	4.00			3293.00	31.00	Bottom Of Top Packer
Packer	5.00			3298.00		
Stubb	1.00			3299.00		
Change Over Sub	1.00			3300.00		
Recorder	0.00	8369	Outside	3300.00		
Recorder	0.00	8846	Outside	3300.00		
Blank Spacing	31.00			3331.00		
Change Over Sub	1.00			3332.00		
Perforations	19.00			3351.00		
Bullnose	3.00			3354.00	56.00	Bottom Packers & Anchor
T.4.1 T1140						

Total Tool Length: 87.00

Trilobite Testing, Inc Ref. No: 68934 Printed: 2022.04.19 @ 16:20:33



**FLUID SUMMARY** 

Shelby Resouces LLC

1-18S-14W Barton, KS

3700 Quebec St Suite 100 PMB 376

Denver CO 80207

Van Winkle #1-1

Job Ticket: 68934

DST#: 3

ATTN: Jeremy Schwartz

Test Start: 2022.04.16 @ 21:52:26

#### **Mud and Cushion Information**

Mud Type: Gel Chem Cushion Type: Oil API: deg API

Mud Weight: 9.00 lb/gal Cushion Length: ft Water Salinity: 25000 ppm

Viscosity: 50.00 sec/qt Cushion Volume: bbl

Water Loss: 6.79 in<sup>3</sup> Gas Cushion Type:

Resistivity: ohm.m Gas Cushion Pressure: psig

Salinity: 9800.00 ppm Filter Cake: 0.20 inches

#### **Recovery Information**

#### Recovery Table

Length ft	Description	Volume bbl
63.00	MCW 15%M 85%W	0.610
63.00	MCW 5%M 95%W	0.884
63.00	WCM 55%M 45%W	0.884
31.00	WCM 65%M 35%W	0.435


Total Length: 220.00 ft Total Volume: 2.813 bbl


Num Fluid Samples: 0 Num Gas Bombs: 0 Serial #:

Laboratory Name: Laboratory Location:

Recovery Comments:

Trilobite Testing, Inc Ref. No: 68934 Printed: 2022.04.19 @ 16:20:33







# RILOBITE ESTING INC.

### **Test Ticket**

NO.

68932

all should	rkway • Hays, Ransas 07001	
Well Name & No. Shells Resour	cestte ww Winkle Tosi No. 1	Date 4/14/ 22
company_3he (by Kexalicans (1	Elevation	0
Address 3200 Quebec ST Suite	(D) PMB376 Derver, CO. 803	0 7
Co. Rep / Gen Jorg M. C. L.	Rig 813Cover	4
Location: SecTwp/85	Rge. 14W Co. Borton	State _KS
Interval Tested 30 99 - 31%		
Anchor Length 71	Drill Pipe Run	Mud Wt. 9,7
Top Packer Depth 3891	Drill Collars Run 30	Vis
Bottom Packer Depth 3895	Wt. Pipe Run	WL
Total Depth3100	(19)	System LCM <u>O</u>
Blow Description IF Fair Building	Slaw built to S"in Bucket (15)	
IST: An Plan Buc	ck (45)	
FF: Weak Buildir	g Blow built to . 25" in Bucket	(45)
FSI: NOBION Back		
Rec_63 Feet of M	%gas	%oil %water (c) %mud
Rec Feet of	%gas	%oil %water %mu
RecFeet of	%gas	%oil %water %mu
Rec Feet of	%gas	%oil %water %mu
Rec Feet of	%gas	%oil %water %mi
Rec Total 63 BHT 97	Gravity API RW	@F Chloridespr
(A) Initial Hydrostatic 1481	1800	
(B) First Initial Flow 53	300	T-Started <u>C 211</u>
(C) First Final Flow 52	Safety Joint	T-Open <u>0 4 / 4</u>
(D) Initial Shut-In 731	Circ Sub	T-Pulled <u>0735</u>
(E) Second Initial Flow 54	☐ Hourly Standby	T-Out <u>0993</u>
F) Second Final Flow 54	Mileage 112 168	Comments
776	D Sampler	
C)		
10 5 - 11 11 11 - 12 12		
H) Final Hydrostatic 1457	Straddle	EM Tool
Tij i mar tiyorostado	Straddle  Shale Packer	
nitial Open (5	Straddle Shale Packer Extra Packer	EM Tool  Ruined Shale Packer  Ruined Packer
nitial Open 15	Straddle  Shale Packer	EM Tool  Ruined Shale Packer  Ruined Packer  Extra Copies
nitial Open 15 nitial Shut-In 45 Final Flow 45	Straddle Shale Packer Extra Packer	EM Tool Ruined Shale Packer Ruined Packer Extra Copies Sub Total
nitial Open 15	□ Straddle           □ Shale Packer           □ Extra Packer           □ Extra Recorder           □ Day Standby           □ Accessibility	EM Tool Ruined Shale Packer Ruined Packer Extra Copies Sub Total
nitial Open 15 nitial Shut-In 45 Final Flow 45	□ Straddle           □ Shale Packer           □ Extra Packer           □ Extra Recorder           □ Day Standby	EM Tool  Ruined Shale Packer  Ruined Packer  Extra Copies  Sub Total



## **Test Ticket**

68933 NO.

1515 Commerce Parkv	vay • Hays, Kansas 67601				i de
Well Name & No. Van Winkle 1-1			2	ate 4/15/2	2
Company Stelly Resources CLC		Elevation 12	340	KB_103_2	GL
Address 3000 Out CTS. In ho	ANR 336 Derver	100.000	2		The state of the s
Co. Rep/Geo. Jereny Schworte		Hig _UISACC		Ve	<del></del> i
Location: Sec. Twp 185	Rge Y WC	o. Borba		State	
nterval Tested 3222 - 3355	Zone Tested Longi	My H-K		08	
unchor Length83'	Drill Pipe Run			ud Wt. 8.8	*****
op Packer Depth 3214	Drill Collars Run	30		s <u>59</u>	
Bottom Packer Depth_3218	Wt. Pipe Run	9	W	5.8	NOT
otal Depth 3305	Chlorides 7500	ррі	n System LO	см <u>2</u>	All and a second
Blow Description IF: Blow died Flu	ished tool Per Geo a	Nd Shut	IN (15)		
ISI: NO BLOW BO	ck (45)		1. 1. 1.		
FF: No Blow Pul	•	in the second	. /	·	
FSI:					1 1
tec75 Feet ofM		%gas	%oil	%water	<u>/∞/ %mud</u>
Rec Feet of		%gas	%oil	%water	%mud
RecFeet of		%gas	%oil	%water	%mud
Rec Feet of		%gas	%oil	%water	%mud
Rec Feet of		%gas	%oil	%water	%mud
Rec Total BHT	Gravity AP	RW		Chlorides	
A) Initial Hydrostatic 1589	1800	1		ation <u>2345</u>	
B) First Initial Flow 63	Jars300		T-Started	10035	
C) First Final Flow 63	Safety Joint			0230	11
D) Initial Shut-In 5/4	Circ Sub	77		040	
E) Second Initial Flow 64					i in parts
F) Second Final Flow	<b>7</b> 110 1		Comme	nts	
					The second second
(G) Final Shut-In	Gampler		-	<b>Tool</b> -350	-
Tij i mai riyorostano	☐ Shale Packer			ned Shale Packe	T-16 T-18 15 TF
nitial Open 15	4 4 4 5 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4				
11/				ned Packer	
nitial Shut-In 75 Final Flow CO			A STATE OF THE STA	ra Copies tal350	
87	Day Standby	4	Sub to	1010	
Final Shut-In	Accessibility 2268		The state of the s	ST Disc't	
	Sub Total 2208	· · · · · · · · · · · · · · · · · · ·	02	DISCI	
Approved By		Representative			



# RILOBITE ESTING INC.

515 Commerce Partural - Have Kenses 6760

## **Test Ticket**

NO. 68934

4/10 MACK						
Well Name & No. Van Winkle 1-1		Test No	3	_Date 4/16/	22	-
Company Shelly Rossins 5 1/C		Elevation	1840	KB_103/	-	_GL
Address 3200 Quelos ST Sillo 100	PMB 376	Derver, S	0.80%		-	
Co. Rep / Gen ) Orani Schi Lyts		Ria UIS	covery			0
Location: Sec Twp185	Rge. 14W	_co. Bart	<i>N</i>	State_K	5	
Interval Tested 3298 - 3354	Zone Tested A					
Anchor Length 56	Drill Pipe Run	3251		Mud Wt. 9,1		
Top Packer Depth 3290	Drill Collars Rur	30		VIs SO		
Bottom Packer Depth_3294	Wt. Pipe Run			WL 6.8		
Total Depth3354	Chlorides	1800	ppm System	LCM		
Blow Description IF- Fair Building Bo	Law built to 5	5.25" in bu	Ket (15)			
ISI -NO Blow Back 14	(5)					
FF: Fair Build in Bla		Bucket (1	(a)	**		ret.
FST: NO BLOW BOCK (	(60)					7
Rec_31 Feet of WCM	1 2 2	%gas	%oil	35 %water	65	%mud
Rec 63 Feet of WCA	de C	%gas	%oil	45 %water	55	%mud
Rec_63 Feet of MCW		%gas	%oil	95 %water	5	%mud
Rec_63 Feet of MCL/		%gas	%oil	35 %water	15	%muc
Rec Feet of		%gas	%oil	%water		%muc
Rec Total BHT			6_@_41	F Chlorides <u>25</u>	000	ppn
(A) Initial Hydrostatic 1605	Test180	0		Location 202	3	
(B) First Initial Flow 44	Jars 30	0	T-Sta	2152		<u> </u>
(C) First Final Flow 60	Safety Joint _		T-Op	en_6014		
(D) Initial Shut-In 1147	☐ Circ Sub		T-Pu	illed <u>035</u>		
(E) Second Initial Flow 62	☐ Hourly Standt		T-O	ut 0576		
(F) Second Final Flow	Mileage 1	100	Con	nments		
(G) Final Shut-In					3	
(G) Filial Stidt-III			_	0	1 6	
(H) Final Hydrostatic1602			_	EM Tool		-
	☐ Shale Packer			Ruined Shale Pag	ker	
Initial Open	☐ Extra Packer			Ruined Packer		
Initial Shut-In 45	☐ Extra Record	er		Extra Copies		Saje (
Final Flow 60	☐ Day Standby		Su	b Total0		
Final Shut-In	☐ Accessibility	N. C.	То	2268		
	Sub Total2	268	MI	P/DST Disc't		
Approved By		Our Represent	ative Db		N.	
Trilobite Testing Inc. shall not be liable for damaged of any kind of the propert equipment, or its statements or opinion concerning the results of any test, to	ty or personnel of the one for			r sustained directly or ind	ranth throu	oh the use

No. 2996 Home Office P.O. Box 32 Russell, KS 67665 Phone 785-483-1071 Cell 785-324-1041 County On Location Range State Sec. Twp 18 Location Well No. Owner To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed. Type Job Charge To no 1 esuces Hole Size T.D. Depth Street Depth State Tbg. Size City The above was done to satisfaction and supervision of owner agent or contractor. Tool Depth Cement Amount Ordered 350 60/40 40/60 20/6 (60) Cement Left in Csq. Shoe Joint Displace Meas Line EQUIPMENT Common Cementer \* Poz. Mix Helpe Pumptrk Gel. Driver Calcium JOB SERVICES & REMARKS Hulls iculate Salt Remarks: Rat Hole Flowseal Kol-Seal Mouse Hole Mud CLR 48 Centralizers CFL-117 or CD110 CAF 38 Baskets D/V or Port Collar Sand Handling Mileage FLOAT EQUIPMENT Guide Shoe Centralizer Baskets AFU Inserts Float Shoe Latch Down Pumptrk Charge Mileage Tax

Signature

Discount Total Charge

## QUALITY OILWELL CEMENTING, INC. Federal Tax I.D.# 20-2886107

Date 4-17-22 Sec.	Twp. Range	Bacton	KState S	On Location	9:30 Pm
12001	winkle.	Location Box	rd - 15.	14E, NI	nto
Lease	Well No. 1 -	Owner	5		Maria State (III resign
Contractor Discovery	#2	To Quality	Oilwell Cementing, I	nc. nt cementing equipmen	at and turnich
Type Job Plag	and the late of th			wher or contractor to d	
Hole Size 778	T.D. 3354	Charge To	Shelbu	Resources	
Csg.	Depth	Street	0.1609	suid to ment and or ge	Williams work Vist.
Tbg. Size 48" D.P	Depth 777	City		State	halle annument
Tool	Depth	11	vas done to satisfaction	and supervision of owne	r agent or contractor.
Cement Left in Csg.	Shoe Joint	Cement Ar	mount Ordered 2	05 60140 4	% Gel
Meas Line	Displace 420	1/4#	Flo.seal	- YTLIAUD JURINA	U.D. Branch
EQUIF	PMENT	Common	05 123		HE SHETTLE
Pumptrk 16 No. Cementer T	Sovid	Poz. Mix	123 82	I Call time by all	was at the W
Bulktrk 19 No. Driver D.	SUCY	Gel.	7	NA HOLLONG	AREA TELE
BUHKIRK PIUNO. Driver R	cko	Calcium		AND DESCRIPTION OF THE PARTY OF	CONTRACTOR -
,	S & REMARKS	Hulls			
Remarks:	700	Salt	CT LILLO,	Aude la Tax	
Rat Hole 7777'-	- 50 5X	Flowseal	50#		
Mouse Hole 5001 -	100 2X	Kol-Seal			
Centralizers 40' -	10 SX	Mud CLR	18		Mill Demign
Baskets 30 - R	Cathole	CFL-117 o	r CD110 CAF 38	The second second	
D/V or Port Collar /5 - W	nousehole	Sand			A S D In &
		Handling	2/2		
Cement die	Circul	ate Mileage			
			FLOAT EQUIP	MENT	
		Guide Sho	· Dry }	yould star	
District of realist Laborator in	A SECTION AND ADDRESS.	Centralizer			TILGING A
and the last last the same	on industrial state of	Baskets			a distributible
notice of the later of	ALC: NO.	AFU Insert	s	177	Server State of
THE SECRETARY ROOM	OTTO BELLEVIOLE	Float Shoe			m subjects
POYTHIGHT DESCRIPTION	Marine Comment	Latch Dow	n	- moderate	Harris Harris
A STREET AND A STREET AND A STREET				a re-based frame	
	THE RESERVE	THE REST	The Designation	specialists without a	
one to the same and to address of	The second second	Pumptrk C	harge Pluc	?	a residence (A)
		Mileage /	6 1 -	7	munt to lends de-
			1 1	Tax	This pres 700
711	(i) to nompleon may	-	hanks	Discount	
X Signature	MESTE deal on myles of	/	Paris of School	Total Charge	



Scale 1:240 Imperial

Well Name: Van Winkle #1-1

Surface Location: 2310' FSL \_1434' FWL, Sec. 1-T18s-R14w

**Bottom Location:** 

API: 15-009-26341-00-00

License Number: 31725

Spud Date: 4/11/2022 Time: 2:15 PM

Region: **Barton County** 

Drilling Completed: 4/17/2022 Time: 12:30 PM

Surface Coordinates:

**Bottom Hole Coordinates:** 

Ground Elevation: 1832.00ft K.B. Elevation: 1840.00ft

Logged Interval: 2650.00ft 3354.00ft To:

Total Depth: 3354.00ft Formation: Lansing

Drilling Fluid Type: Chemical/Fresh Water Gel

#### **OPERATOR**

Shelby Resources, LLC Company:

3700 Quebec St. Unit 100 PMB 376 Address:

Denver, CO 80207

Contact Geologist: Jeff Zoller / Jeremy Schwartz Contact Phone Nbr: 620-786-0807 / 203-671-6034

> Well Name: Van Winkle #1-1

Location: 2310' FSL \_1434' FWL, Sec. 1-T18s-R14w

API: 15-009-26341-00-00

Pool: Field: Boyd

USA State: Kansas Country:

#### **LOGGED BY**



Mile High Exploration, LLC Company: 14645 Sterling Road Address:

Colorado Springs, CO 80921

Phone Nbr: 203-671-6034

Logged By: Geologist Name: Jeremy Schwartz

#### **NOTES**

Three DST's were conducted during the drilling of this well.

Due to negative drill stem tests across all zones of interest it was determined by all parties involved to plug and abandon the well. No E-logs were run and the well was P&A in accordance with KCC approval. The dry samples were saved and will be available for furthur review at the Kansas Geological Society Well Sample Library, located in Wichita, KS.

Respectfully Submitted, Jeremy Schwartz Geologist

#### **CONTRACTOR**

Contractor: Discovery Drilling

Rig #:

Rig Type: mud rotary Spud Date: 4/11/2022 Time: 2:15 PM TD Date: 4/17/2022 Time: 12:30 PM

Rig Release: Time:

#### **ELEVATIONS**

K.B. Elevation: 1840.00ft Ground Elevation: 1832.00ft


K.B. to Ground: 8.00ft


Shelby Resources, LLC


<u>DATE</u>	<u>DEPTH</u>	<u>ACTIVITY</u>
Thursday, April 14, 2022	2700'	Geologist Jeremy Schwartz on location @ 1130hrs, 2700', drlg ahead through Topeka,
37 97		Heebner, Toronto, Douglas, Brown Lime, Lansing, CFS @ 3147', resume drlg, CFS @ 3170',
	3170'	Conduct short trip, CTCH 90min, drop survey, strap out for DST #1 in Lansing A-F
Friday, April 15, 2022	3352'	Successful test, resume drlg ahead through Lansing G, Muncie Creek, H, CFS @ 3252',
	33051	resume drlg, CFS @ 3283, resume drlg, CFS @ 3305', OOH for DST #2 in the Lansing H-k
Saturday, April 16, 2022		Successful test, rig cannot get past surface casing while tripping back in hole,
	33541	mill out guide shoe and trip in hole, resume drlg, CFS @ 3354', show in Arbuckle
		CTCH 90min, trip out for DST #3 in the Arbuckle
Sunday, April 17, 2022	3354'	Successful test, TD @ 3354'.
	1	Geologist Jeremy Schwartz off location @ 1600hrs.


					4															
ય :		15-009-26	341-00-00	13	l															
LG CONTRACTOR:		Discoven	y Drilling		1															
i#:		Ž	2	33	1															
GHOUSE #:		785-63	5-1412		1															
OLPUSHER:		Travis S	Schmidt	- 33	1															
LL #:		785-34	2-8522																	
				- 13		Oil	- P&A										•			
						L.D. Di	illing, Inc				Shelby Re	sources, LL	Ċ			Shelby Res	ource	s, LLC		-
							/inkle #1				Benton Wi	rth Unit #2	-1			Schlessige	Cattl	e#1-2		-
		Van Win	ıkle #1-1			Sec. 1 5	E-SW-SW				Sec. 1 NW	-SW-NW-N	E			Sec. 2 N/	2-SE-S	E-NE		-
	КВ		1840		КВ		1848			КВ		1839			КВ		1	342		_
	LOG	TOPS	SAMPI	LE TOPS	COM	. CARD	LOG	SIV	IPL.	COME	. CARD	LOG	SN	/IPL.	COMP	CARD	L	)G	_ 5N	Λſ
FORMATION	DEPTH	DATUM	DEPTH	DATUM	DEPTH	DATUM	CORR.	ω	RR.	DEPTH	DATUM	CORR.	CC	RR.	DEPTH	DATUM	CO	RR.	CC	)F
Anhydrite Top					789	1059				780	1059				789	1053				T
Base					813	1035				805	1034				812	1030			2	T
Topeka			2801	-961	2799	-951		2	10	2795	-956		-	5	2793	-951			2	I
Heebner			3018	-1178	3020	-1172		· · ·	6	3005	-1166		-	12	3011	-1169			*	I
Toronto			3032	-1192	3031	-1183		-2	9	3018	-1179		-	13	3022	-1180			8	I
Douglas			3042	-1202	3041	-1193		-	9	3029	-1190		-	12	3033	-1191			1	1
Brown Lime			3096	-1256	3096	-1248		22	8	3084	-1245		2	11	3086	-1244			1	I
Lansing			3106	-1266	3105	-1257		-	9	3093	-1254		-	12	3098	-1256			1	I
Lansing G Porosity			3174	-1334	3182	-1334		+	0	3161	-1322		-	12	3166	-1324			1	I
Muncie Creek			3227	-1387	3228	-1380		-	7	3218	-1379		-	8	3220	-1378			1	
Lansing H			3232	-1392	3234	-1386		2	6	3225	-1386		-	6	3226	-1384			1	1
Stark			3282	-1442	3284	-1436		- 1	6	3272	-1433		-	9	3276	-1434			<del>-</del> -	
BKC			3300	-1460	3302	-1454		2	6	3294	-1455		2	5	3295	-1453			2	1
Arbuckle			3331	-1491	3322	-1474		-	17	3341	-1502		+	11	3306	-1464			*	1
RTD			3354	-1514	3330	-1482		- 2	32						3420	-1578			+	1
LTD		Ü Ü			3333	-1485									3419	-1577				1

CLIENT: WELL NAME:











Shelby Resouces LLC

1-18S-14W Barton Co Ks

Job Ticket: 68932

Tester:

3700 Quebec St Suite 100 PMB 376

MB 376 Van Winkle 1-1

Denver Co 80207

ACCOUNTS AND THE STATE OF THE S

ATTN: Jeremy Schwartz

Test Start: 2022.04.15 @ 02:11:44

Eric Burgess

DST#: 1

#### GENERAL INFORMATION:

Formation: Lansing A-F

Deviated: No Whipstock: 0.00 ft (KB) Test Type: Conventional Bottom Hole (Initial)

Time Tool Opened: 04:08:54

Time Test Ended: 09:43:04 Unit No: 80

Interval: 3099.00 ft (KB) To 3170.00 ft (KB) (TVD) Reference Elevations: 1840.00 ft (KB)

 Total Depth:
 3170.00 ft (KB) (TVD)
 1832.00 ft (CF)

 Hole Diameter:
 7.88 inchesHole Condition:
 Poor
 KB to GR/CF:
 8.00 ft

Serial #: 8369 Outside

Press@RunDepth: 53.53 psig @ 3106.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.04.15
 End Date:
 2022.04.15
 Last Calib.:
 2022.04.15

 Start Time:
 02:11:45
 End Time:
 09:43:04
 Time On Btm:
 2022.04.15 @ 04:08:04


 Time Off Btm:
 2022.04.15 @ 07:34:44

TEST COMMENT: IF:Fair Building Blow built to 5" in bucket (15)

ISI:No Blow Back (45)

FF:Weak Building Blow built to .25" in bucket (45)

FSI:No Blow Back (90)



63.00	M 100%M	0.61

The same terminal and the first of the first	y as remaining of the second	The second secon
		8

Trilobite Testing, Inc Ref. No: 68932 Printed: 2022.04.15 @ 11:13:37



Shelby Resouces LLC

1-18S-14W Barton Co Ks

3700 Quebec St Suite 100 PMB 376

700 Quebec 3i Suite 100 FMD 370

Van Winkle 1-1
Job Ticket: 68933

Denver Co 80207

Job Ticket: 68933 DST#2

ATTN: Jeremy Schwartz

Test Start: 2022.04.16 @ 00:35:00

#### GENERAL INFORMATION:

Formation: Lansing H-K

Deviated: No Whipstock: 0.00 ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 02:38:20 Tester: Eric Burgess

Time Test Ended: 05:54:00 Unit No: 80

Interval: 3222.00 ft (KB) To 3305.00 ft (KB) (TVD)

Reference Elevations: 1840.00 ft (KB) 1832.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: KB to GR/CF: 8.00 ft

Serial #: 8369 Outside

Total Depth:

Press@RunDepth: 63.17 psig @ 3229.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.04.16
 End Date:
 2022.04.16
 Last Calib.:
 2022.04.16


 Start Time:
 00:35:01
 End Time:
 05:54:00
 Time On Btm:
 2022.04.16 @ 02:37:40

Time Off Btm: 2022.04.16 @ 03:59:40

TEST COMMENT: IF:Blow Died Flushed tool per geo and shut in tool (15)

ISI:No Blow Back (45) FF:No Blow pulled tool

3305.00 ft (KB) (TVD)



PRESSURE SUMMARY					
Time (Min.)	Pressure (psig)	Temp (deg F)	Annotation		
(14111.)	1589.03	95.35	Initial Hydro-static		
1	63.49	95.13	Open To Flow (1)		
9	63.17	95.32	Shut-In(1)		
54	514.33	96.42	End Shut-In(1)		
54	64.33	96.21	Open To Flow (2)		
82	1531.90	99.18	Final Hydro-static		
	1				

# Recovery Length (ft) Description Volume (bbl) 75.00 M 100%M 0.78

\* Recovery from multiple tests

Choke (inches) Pressure (psig) Gas Rate (Mcf/t	100 00000000000000000000000000000000000						
	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)				
	Chore (Inches)	Tressure (parg)	Gas IVale (INICI/U)				
		Chole (inches)	Choke (inches) Pressure (psig)				

Gas Rates

Trilobite Testing, Inc Ref. No: 68933 Printed: 2022.04.16 @ 07:45:19



Shelby Resouces LLC

1-18S-14W Barton Co Ks

3700 Quebec St Suite 100 PMB 376

Van Winkle 1-1

Denver Co 80207

Job Ticket: 68934 DST#3

ATTN: Jeremy Schwartz Test Start: 2022.04.16 @ 21:52:26

#### GENERAL INFORMATION:

Formation: Arbuckle

Deviated: No Whipstock: 0.00 ft (KB) Test Type: Conventional Bottom Hole (Reset)

Time Tool Opened: 00:10:26 Tester: Eric Burgess

Time Test Ended: 05:36:46 Unit No: 80

Interval: 3298.00 ft (KB) To 3354.00 ft (KB) (TVD) Reference Elevations: 1840.00 ft (KB)

Total Depth: 3354.00 ft (KB) (TVD) 1832.00 ft (CF)

Hole Diameter: 7.88 inchesHole Condition: Fair KB to GR/CF: 8.00 ft

Serial #: 8369 Outside

Press@RunDepth: 117.11 psig @ 3300.00 ft (KB) Capacity: 8000.00 psig

 Start Date:
 2022.04.16
 End Date:
 2022.04.17
 Last Calib.:
 2022.04.17

 Start Time:
 21:52:27
 End Time:
 05:36:46
 Time On Btm:
 2022.04.17 @ 00:09:36


Time Off Btm: 2022.04.17 @ 03:17:05

TEST COMMENT: IF:Fair Building Blow built to 5.25" in bucket (15)

ISI:No Blow Back (45)

FF:Fair Building Blow built 9" in bucket (60)

FSI:No Blow Back (60)



#### Recovery

Description	Volume (bbl)
MCW 15%M 85%W	0.61
MCW 5%M 95%W	0.88
WCM 55%M 45%W	0.88
WCM 65%M 35%W	0.43
	MCW 15%M 85%W MCW 5%M 95%W WCM 55%M 45%W

#### Gas Rates

	Choke (inches)	Pressure (psig)	Gas Rate (Mcf/d)
--	----------------	-----------------	------------------

Trilobite Testing, Inc Ref. No: 68934 Printed: 2022.04.17 @ 07:32:24