## KOLAR Document ID: 1783879

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION CASING MECHANICAL INTEGRITY TEST

Disposal: Enhanced Recove	rv: KCC District N	0.:	API No.:		Permit No.:	
Operator License No.: Name:						
Address 1:						ine of Section
Address 2:				Feet from	East / West L	ine of Section
City: State: Zip:+			Lease:		Well No	o.:
Contact Person: Phone: ( )			County:			
-						
Well Construction Details:	ew well Existing we	ell with changes to con	struction Existing	well with no chang	es to construcion	
Maximum Authorized Injection Pre	essure:	_ psi Maximum Inje	ection Rate:	bbl/d		
Conductor	Surface	Intermediate	Production	Liner		Tubing
Size:					Size: _	
Set at:					Set at:	
Sacks of Cement:					Туре:	
Cement Top:					-	
Cement Bottom:					-	
Packer Type:				Set at:		
DV Tool Port Collar D	epth of: f	eet with sac	cks of cement TD (and	d plug back):		feet depth
Zone of Injection Formation:		Top Feet:	Bottom F	eet:	Perf. or Open Hole:	
Is there a Chemical Sealant or a N			Yes No			
	AD27 NAD83		MITR	eason:	Date Acquired:	
Time in Minute(s):						
Pressures: Set up 1						
Set up 2						
Set up 3						
Tested: Casing or Casing - Tubing Annulus System Pressure du Test Date: Using:					Is. to load annulus:	
	-				Compa	ny s Equipment
The zone tested for this well is bet		and ieei.				
The test results were verified by op	· ·					
Name:		Title:		Phone	: ()	
KCC Office Use Only Sta	ate Agent:		Title:		Witness:	Yes No
The results were: Re	emarks:					
Satisfactory						
Not Satisfactory						
Next MIT:						

Form U-7 August 2019 Conservation Division District Office No. 3 137 E. 21st Street Chanute, KS 66720



Phone: 620-902-6450 http://kcc.ks.gov/

Andrew J. French, Chairperson Dwight D. Keen, Commissioner Annie Kuether, Commissioner Laura Kelly, Governor

## FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

LICENSE 35503 Midstates Energy Operating, LLC 5571 HALIFAX AVENUE FT MYERS, FL 33912-4403

Re: API No. 15-045-20429-00-01 Permit No. E25140.1 WISEMAN 5 10-14S-20E Douglas County, KS

Operator:

On 06/25/2024, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

1) repair and retest the well to show mechanical integrity,

2) plug the well, or

3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

## Failure to comply with K.A.R. 82-3-407(c) by 09/23/2024 shall be punishable by a \$1, 000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Duane Sims KCC District #3