WATER WELL RECORD (WWC-5)

| VATER WELL I | RECORD (W | WC-5) | | | KOLAR D | OC ID | WELL ID | |
|---|---------------------|---------|---------------------------------|----------------------|-----------------|---|-------------------------|---------|
| OCATION OF WATER | WELL | | | Or | iginal Recor | d Correction | Change in V | Nell Us |
| Latitude | Longitude | | Section | Township | Range | E W Fraction | 1/4 1/4 | 1, |
| Datum | Elevation | | County | - | | VV | | |
| ATER WELL OWNER | | W | ELL WATER USE | | | NEAREST SOURCE OF | POTENTIAL CONTA | MINATIO |
| Jame | | | | | | Source: | | |
| | | | | | | Distance | Direction | |
| Business | | | MPLETION | | | from well: | from well: | |
| Address | | | | d well: | ft. | Source | | |
| | | | Pepth(s) groundwa | | | description: | | |
| 7 11 1 | | | 1) ft.; (2 | | | Source: | | |
| Vell location | | | 3) ft.; (4) | | | Distance from well: | Direction from well: | |
| at owner's | | S | tatic water level in | well: ft. | | Source | | |
| address | | | measured below | | | description: | | |
| NSTRUCTION | | | on (mm/dd/yy) | | | No potential sour | ce of contamination | 1 |
| orehole interval: | Borehole dia | meter: | measured above on (mm/dd/yy) | | | within 100 feet. | | |
| romto1 | | | | | | PERMIT & ID NUMBE | RS (AS REQUIRED) | |
| romtof | | _ - | stimated yield: | | houre | DWR Application No | · · | |
| | | | valer lever was: | ft. after pumping | I . | KDHE / EPA Project | | |
| asing height above la | · | | ump installed? | | gpiii | Site Name: | | |
| If casing height is lo has a variance beer | | s No | ump mstancu: | ies no | | KDHE UIC Class V I | | |
| | ired for monitoring | | Vater well disinfec | ted? Yes No | | County Permit: Ye | • | |
| or environmental | remediation wells | | ate disinfected (n | nm/dd/yy): | | Lease Name & Well # | | |
| asing type: | | | quifer, if known: | | | # of boreholes: | | |
| ank casing interval: | | _*" _ | - | | | | | |
| lank casing diameter: | | | THOLOGIC LOG | LITUOLOGY INT | FRVALC | | | |
| | lbo/ft | | ROM TO | LITHOLOGY INTI | EKVALS | | | |
| | auge no.: | | | | | | | |
| lank casing interval: | | | | | | | | |
| lank casing diameter: | | | | | | | | |
| Casing joints: | | | | | | | | |
| Weight: | lbs/ft. | | | | | | | |
| Wall thickness or g | | | | | | | | |
| rout interval: | | | | | | | | |
| Grout material: | | | | | | | | |
| rout interval: | | | | | | | | |
| Grout material: | | cc | OMMENTS | | | | | |
| | | | | | | | | |
| creen / perforation ma | aterial: | | | | | | | |
| creen / perforation op | penings: | co | ONTRACTOR'S O | R LANDOWNERS CE | RTIFICATION | | | |
| creen / perforation int | | | his water well w | vas constructed | reconstru | cted pursuant to | the stated water v | well |
| Fromft. to _ | ft. | | | | eted on | . I certify th | | |
| Slot size | unit | | | • | | vell record was compl | | |
| From ft. to _ | ft. | | • | · · | | ven record was compr | | |
| Slot size | unit | | | | | under the au | | |
| ravel pack intervals: | | | | | | | • | _ |
| | ed: Gravel size _ | in - | | | | d and certified by the | electronic signatui | e of th |
| From ft. to | | | | n at its submittal:_ | | | += 00 6 | |
| | ed: Gravel size | in Se | nd one copy to WA | | | for your records. Fee of | | ucted w |
| From ft. to | ft. | | Bureau o | f Water, Geology Sec | tion, 1000 SW J | EALTH AND ENVIRON ackson St., Suite 420, To A. 82a-1212 v2022c | | , |

| Form | WWC5.2 - Water Well Record |
|------------|----------------------------|
| Doc ID | 1835137 |
| Well Owner | Vicki Gruen |
| Contractor | Burton Well Drlg., Inc. |

Lithology

| From | То | Lithology Intervals |
|------|-----|--|
| 0 | 20 | topsoil,medium,clayey,light,ta n,dry,loose,not cemented,no staining |
| 20 | 26 | sandstone,unweathered,claye y,light,tan,hard,medium bedded |
| 26 | 32 | sand,fine to coarse,clayey,light,tan,dry,loo se,not cemented,no staining |
| 32 | 56 | sandstone,unweathered,sand y,light,tan,hard,medium bedded |
| 56 | 59 | clay,medium,sandy,light,tan,dr y,loose,not cemented,no staining |
| 59 | 67 | sand,fine to coarse,clayey,light,tan,dry,loo se,not cemented,no staining |
| 67 | 70 | limestone,unweathered,sandy ,light,tan,hard,medium bedded |
| 70 | 144 | sandstone,unweathered,sand y,light,tan,hard,medium bedded |
| 144 | 154 | sand,fine,sandy,light,tan,dry,lo ose,not cemented,no staining |
| 154 | 155 | limestone,unweathered,light,t an,hard,medium bedded |
| 155 | 163 | sand,fine,clayey,light,tan,wet,l oose,not cemented,no staining |

| Form | WWC5.2 - Water Well Record |
|------------|----------------------------|
| Doc ID | 1835137 |
| Well Owner | Vicki Gruen |
| Contractor | Burton Well Drlg., Inc. |

Lithology

| From | То | Lithology Intervals |
|------|-----|---|
| 163 | 180 | sand & gravel,fine to coarse,gravelly,light,tan,wet,l oose,not cemented,no staining |
| 180 | 204 | sand,medium to coarse,gravelly,light,tan,wet,l oose,not cemented,no staining |