WATER WELL RECORD (WWC5.2)

Constructed

KOLAR DOC ID 1972002 WELL ID

LOCATION OF WATER WELL

County	Hamilton	Section	18	Township	26	Range	42 ☐E ☑W	Fraction	SW ¼ NW ¼ SW ¼
Latitude	37.785677	Longitude	-101.960954	Datum	WGS84	Elevation	3472		

WATER WELL LOCATION

☑ at owner's address

WATER WELL OWNER

Name	Ron Fox
Business	
Address	3391 SW CR E Burlington KS 66839

PERMIT & ID NUMBERS (AS REQUIRED)

DWR Application No.:

KDHE / EPA Project Code:

Site Name:

KDHE UIC Class V Form Completed: ☐ Yes ☐ No

County/Local Permit Required? ☐ Yes ☐ No

Permit Obtained? ✓ Yes ☐ No Permit ID: 26-0618

Oil/Gas Lease Name & Well #:

CONSTRUCTION

Casing: Height above land surface: 18 in.

Is casing height less than 12 inches? ☐ Yes ☑ No

Blank Casing type: ThermalPlastic

1st interval: 0 ft. to 390 ft.; Diameter 5 in.

Casing Joint: : Splines Weight: lbs/ft

Wall thickness or gauge no.: SDR17

2nd interval: ft. to ft.; Diameter in.

Casing Joint: : Weight: lbs/ft

Wall thickness or gauge no.:

3rd interval: ft. to ft.; Diameter in.

Casing Joint: : Weight: lbs/ft

Wall thickness or gauge no.:

Screen / Perforation material: PVC

Specify if other:

Screen / Perforation openings: Saw cut

1st interval 390 ft. to 490 ft. Slot Size .032 inches

2nd interval ft. to ft. Slot Size

3rd interval ft. to ft. Slot Size

WELL WATER USE

Domestic Household

Additional info if required:

# of Boreholes # of Dewatering Wells

COMPLETION

Depth of completed well: 490 ft.

Depth(s) groundwater encountered: ☐ Dry Well

(1) ft.; (2) ft.; (3) ft.;

Static water level in well: 322 ft.

Date measured: 07/06/2026

Measured from: ✓ Top of Casing or ☐ Ground Surface

Measured: ☐ Above or ☑ Below Land Surface

Estimated yield: 25 gpm

Pump Test Date: Water level was:

ft. after hours pumping gpm

ft. after hours pumping gpm

Pump Information:

Pump Installed? ☐ Yes ☑ No Date:

Pump Type: Horsepower: Volts:

Drop Pipe Diameter: in. Drop Pipe Length: ft.

Water well disinfected? ✓ Yes ☐ No

Date disinfected (mm/dd/yy): 07/06/2026

CONSTRUCTION

Borehole interval:

from 0 to 625 ft.

from to ft.

from to ft..

Borehole diameter:

10 in.

in.

in.

Grout:

1st Interval: 0 ft. to 125 ft. Grout material: Bentonite

2nd Interval: ft. to ft. Grout material:

3rd Interval: ft. to ft. Grout material:

Gravel pack: Not Used

1st Interval: 125 ft. to 490 ft. Gravel Size: 1/16" ☐

2nd Interval: ft. to ft. Gravel Size: ☐

3rd Interval: ft. to ft. Gravel Size: ☐

DESIGNATED PERSON	Trevor Nash	WELL COMPLETION DATE	07/06/2026
CONTRACTOR BUSINESS NAME	Nash Water Well Service, LLC		

KANSAS DEPARTMENT OF HEALTH AND ENVIRONMENT
Bureau of Water, Geology Section, 1000 SW Jackson St., Suite 420, Topeka KS 66612-1367

WATER WELL RECORD (WWC-5) Constructed KOLAR DOC ID 1972002 WELL ID

LOCATION OF WATER WELL

County	Hamilton	Section	18	Township	26	Range	42 ☐E ☑W	Fraction	SW ¼ NW ¼ SW ¼
Latitude	37.785677	Longitude	-101.960954	Datum	WGS84	Elevation	3472		
Well Owner	Ron Fox	Well Owner Business							

NEAREST SOURCE OF POTENTIAL CONTAMINATION or ✓ No potential source of contamination within 100 ft.

Source:	Source:
Distance from well (ft): Direction from well:	Distance from well (ft): Direction from well:
Source description:	Source description:
Required information for local entity? ☐ Yes ☐ No	Required information for local entity? ☐ Yes ☐ No

LITHOLOGIC LOG **AQUIFER, if known**

FROM	TO	LITHOLOGY
0	6	topsoil
6	17	clay,brown
17	80	clay,sandy,tan,fine
80	140	clay,sandy,tan,gray/yellow w/ thin streaks fine
140	160	clay,sandy,tan,gray/yellow w/ thin streaks fine
160	200	clay,sandy,tan,fine streaks
200	255	clay,sandy,tan,fine course streaks
255	280	other,sandy,tannish,lost circulation w/ fine
280	300	other,sandy,tannish,lost circulation w/ fine
300	360	other,unknown,clayey,brownish,Tan sand w/gray/blue and soap stone
360	400	other,unknown,Gray/tan fine sand
400	460	sandstone,unknown,clayey,grayish,gray,gray
460	520	sandstone,unknown,clayey,grayish,gray,tan w/ blue and tan
520	540	other,unknown,Tan sand and lost circulation and got bit stuck in hole
540	620	sandstone,unknown,tan
620	625	other,unknown,Lost Circulation

COMMENTS

Due to loss circulation was unable to get cuttings out. Borehole collapsed from 490' to 625'.

This water well was constructed ☐ reconstructed pursuant to the stated water well contractor's license and was completed on 07/06/2026. I certify that this record is true to the best of my knowledge and belief. This water well rcord was completed on 09/29/2026 under the business name of Nash Water Well Service, LLC, KS Water Well Contractor's License No. 846 under the authority of the designated person as defined in K.A.R. 28-30-2(j) and signed and certified by the electronic signature of the designated person at its submittal: Trevor Nash. Send one copy to the water well owner and the contractor should retain one copy.