

23-25-6E

COMPANY **UNCLE SAM OIL CO.**

23 25 6E  
 NW NW NE

NAME **Arthur Clayton**

1

DEPTH **2900' ?**

DATE **8-4-17**

Butler



20	10"	1476'
15 1/2"	120'	1647'
12 1/2"	615'	2370'
13	5	

ELEVATION **1403**

Dry

soil	8	slate	1590
lime yellow	102	lime	1615
slate	140	sand	1650
red rock	170	hole full of water	1530'
lime	180	slate	1715
slate	195	lime	1745
red rock	200	slate	1830
slate	260	lime	1900
lime	280	slate	1945
slate	290	lime	2010
lime	310	slate lime	2140
slate	335	lime	2200
lime	365	sand little oil	2208
slate	390	lime	2235
lime	405	slate	2295
slate	465	lime	2335
lime	480	slate	2375
slate	495	lime	2395
lime	505	slate	2415
slate	525	lime	2430
lime	540	slate	2490
slate	570	lime	2505
lime	580	slate	2515 <del>XXX</del>
sand HFW	595	lime	2525
red rock	600	slate	2530
clay	645	lime	2535
slate	675	slate	2570
lime	695	lime	2590
slate	765	sand	2595
2 bailers of wtr.	720'	slate	2625
lime	770	lime	2635
slate	830	slate	2655
lime	860 ?	lime	2665
slate	870	slate	2772
lime	880	sand shell	2775 oil showing
mud	900	slate	2810
slate	905	shell	2815
lime	918	slate	2820
slate	950	sand	2837
lime	975	lime	2900 ? salt water
slate	1020	Total Depth	
lime	1040		
slate	1070		
lime	1115		
slate	1120		
lime	1160		
slate	1180		
lime	1200		
slate	1210		
lime	1230		
slate	1235		
lime	1275		
slate	1300		
lime	1370		
slate	1395		
lime	1405		
slate	1470		
lime	1550		