

Company Excelsior Brick Co.

Farm Welch

No. 1

35-28-14 E
Sec. 35 T. 28 R. 14 E
Loc. W $\frac{1}{2}$ SE $\frac{1}{4}$
County

Total Depth 1110

Comm. 6/21/27

Comp. 7/8/27

Shot or Treated

Contractor

Issued

Casing

20 in.

10 in

15 1/2

8 1/4

12 1/2

6 5/8

13 3/8

5 3/16

260 M Gas
Rock Press 385#

Elevation

Production

Figures Indicate Bottom of Formation

Soil	22
Shale	109
Lime	147
Shale	220
Lime and shale	250 3/4
Sand	295
Lime	300
Shale	310
Big Lime	420
Shale	465
Lime	493
Shale	510
Lime	542
Shale dark	552
Lime	559
Shale, dark	595
Shale	600
Lime	607
Shale, light	617
Lime	632
Shale, light	670
Sand	700
Shale	725
Lime	765
Shale	786
Oswego Lime	805
Shale, black	812
Lime	825
Shale	828
Lime	830
Shale	835
Lime	845
Shale	890
Lime	905
Shale, light	915
Shale, sandy	966
Sandy	973
Shale	983
Shale, sandy	1060
Shale, light	1070
Shale, black	1094
Lime, Miss	1110 gas from 1106-1110