

14-31-21E

Sec. 14 T. 31 R. 21E  
Loc. SW Cor. E $\frac{1}{2}$   
County Crawford

Company Hess-Miller

Farm Parsons

No. 1

Total Depth 281


Comm. 5/7/58

Comp. 5/9/58

Shot or Treated

Contractor Carroll

Issued



Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production Dry - plugged

6 $\frac{1}{4}$ " 42

Figures Indicate Bottom of Formation

- 13 Soil Clay
- Fresh water 12'
- 27 Sand Squirrel
- 108 Shale, gray, water 37' fresh
- 112 Lime 2'
- 114 Shale, dark
- 115 Shale, white
- 155 Shale, dark gray
- 167 Shale, white
- 172 Shale, dark gray
- 173 Lime
- 181 Shale, light gray
- 187 Sand, dry
- 212 Shale, broken
- 217 Shale, black
- 270 Shale, light gray
- 276 Sand, broken - dry
- 281 Shale, white