

Company - LUCKY EIGHT OIL CO.
Farm - Piper No. 2.

SEC. 13 T. 29 R. 3 E
NEc SE NW ??

Total Depth. 2951

Comm.

Comp.

County.


Butler

KANSAS

Shot or Treated.

Contractor.

Issued.



CASING:

Elevation. _____

Production.

Figures Indicate Bottom of Formations.

clay	30	shale	1600
gravel	40	lime	1680
slate	60	slate	1845
lime	85	lime gas	1865
slate	100	lime sdy	1874
lime sdy	150	lime	1980
slate	162	slate	1990
lime	167	lime	2065
slate	187	slate	2190
lime	190	lime	2220
slate	220	showing oil 2220' of	
lime	240	15 Bbls.	
slate	250	lime sdy	2225
red rock	260	lime	2228
slate	310	sand	2230
lime	315	lime	2290
slate	395	lime sdy	2300
lime	410	lime	2320
shale	430	slate	2323
lime	440	lime	2350
shells	510	slate	2354
lime	530	lime	2360
slate	580	sand	2370
shells & slate	605	lime	2400
slate	645	shale	2495
lime	655	lime brkn	2500
slate	675	lime	2505
red rock	688	slate	2530
slate	690	lime	2550
red rock	700	slate	2565
slate shells	750	shells	2595
slate	780	slate	2610
lime	790	lime	2615
slate	810	slate	2657
lime	820	lime	2670
slate	840	shale	2780?
shells	850	lime sdy	2728
slate	900	lime	2735
lime	920	lime sdy	2854
shells & slate	989	shale	2865
lime	999	lime	2866
slate	1090	shale	2931
lime	1140	lime	2932
slate	1220	sand	2951
lime	1300	400' wtr @ 2951	
slate	1310	Total Depth	
lime	1350		
slate	1370	Cased off gas sand	1910
lime	1385		
slate	1425		
lime	1460		
slate	1470		
shells	1500		
lime	1520		
slate	1540		
lime sdy	1550		
gas & little wtr	1566		
lime	1595		

1267