


Company - G. A. BISANGO
Farm Reamer

No. 1

SEC. 22 T. 26 R. 14E
CE/2 NE SE

Total Depth. 1300
Comm. 5-2-45 Comp. 6-8-45?
Shot or Treated.
Contractor. Bisango
Issued. 2-25-50

County. Woodson
KANSAS



CASING:

none

Elevation. _____

Production. 15 bbls.

Figures Indicate Bottom of Formations.

| | |
|-----------------|------|
| soil | 3 |
| clay | 15 |
| shale | 35 |
| lime | 41 |
| shale | 191 |
| lime | 240 |
| shale | 246 |
| lime | 296 |
| shale | 302 |
| lime | 342 |
| shale | 345 |
| lime | 375 |
| shale | 395 |
| water 415 | |
| lime | 456 |
| shale | 490 |
| lime | 496 |
| shale | 535 |
| lime | 615 |
| lime sdy | 630 |
| shale | 806 |
| lime | 812 |
| shale | 816 |
| lime | 819 |
| shale | 823 |
| lime | 826 |
| shale | 836 |
| lime | 846 |
| shale | 896 |
| sand | 904 |
| shale wtr | 940 |
| sand | 950 |
| shale | 955 |
| shale | 992 |
| lime | 1010 |
| shale | 1019 |
| lime | 1021 |
| shale | 1025 |
| shale | 1040 |
| lime | 1042 |
| shale sdy | 1047 |
| sand | 1080 |
| shale | 1145 |
| lime shells | 1146 |
| shale | 1234 |
| sand, shale-OIL | 1238 |
| sand OIL | 1258 |
| sand ? | 1300 |
| Total depth | |