

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY.
412 Union National Bank Bldg, Wichita, Kansas

Plotted
95-186


THE PALMER OIL CORP.
C. Ruder No. 2.

SEC. 8 T. 15 R. 18W.
NEc SE

Plotted Texas CO.
County Ellis.

Total Depth. 3596
Comm. 6- 8-36 Comp. 10-31-36
Shot or Treated.
Contractor. The Palmer Oil Corp.
Issued. 11-14-36

NOV 14 1936



CASING.

15 1/2" 30'10"
10" 1113'9"
65/8" 3549'5"

Elevation.

Production. DRY.

Figures Indicate Bottom of Formations.

surface	35		
shale and shells sand	245	red rock	3581
sand and shale	620	very small rainbow	3589-91
water sand	815	quartzite lime	3585
shale and shells	870	sdv lime	3592
sand shells and shale	990	lime shell	3593
red rock	1090	lime	3594
red rock and shale	1115	sdv lime	3596
lime	1130	water 3594-96	1200'
lime broken	1195	Total Depth.	Plugged and abd.
shale and shells	1300		
broken lime	1357		
shale and shells	1530		
salt	1835		
broken lime	1860		
lime	2051		
lime broken	2155		
lime hard	2310		
lime	2400		
broken lime shale	2457		
lime	2590		
lime and shale	2693		
lime broken	2779		
lime	2855		
lime broken	2880		
lime hard	2920		
lime broken	2935		
lime hard	3050		
lime	3089		
lime hard	3180		
shale and shells	3200		
lime hard	3242		
lime broken	3280		
lime hard	3307		
broken lime	3335		
lime hard	3365		
broken lime	3370		
lime hard	3410		
shale	3415		
lime hard	3490		
broken lime	3552		
shale and lime	3562		
sand light	3572		
sand shale light soft	3578		