

Russell


KANSAS

Form 51—5M—11-38—Palace

Section 29 Township 14 Range 13-W

Well No. #5 Rogg

Company Sinclair Prairie



KANSAS


Russell

Sec. 29 Twp. 14 R. 13-WWell No. #5 Rogg FarmSinclair-Prairie Company

(Hall)

990 Ft. from N. Line Ft. from S. Line Ft. from E. Line660 Ft. from W. Line

Elev. 1759



1939	REPORT
6/21	Rotary.
6/29	10" - 158' Drig. 2296'
7/6	Drig. 3125'
7/13	Gorham 3161' 7" - 3161'
	Sat. 3161-64' T.D. RUST.
7/20	98 shots. 2000 acid.
	Pump 35 oil 14 hrs.
	3000 acid. Testing.
7/26	Gorham 3161'
	7" - 3161'
	T.D. 3164'
	98 shots 2920-33'
	8000 acid.
	Pump 946 oil, 10% water for potential.
	COMPLETED

Russell KANSAS

Map No. _____ Sec. 29 Twp. 14 R. 13W

Well No. 5 Rogg

Sinclair Prairie Company

Contractor

FIRST REPORT

SECTION PLAT

990 C S L NW SE
Ft. from N. Line

____ Ft. from S. Line

____ Ft. from E. Line

660 Ft. from W. Line

		o	

HALL POOL

Location _____

Rig up _____

Drilling and Remarks:

Rotary

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUN 21

19

C. J. LEWIS

Scout

Map No. 72 Sec. 29 Twp. 14 R. 13WWell No. 5 RoggSinclair Prairie

Company

Contractor

COMPLETED

C S L NW SE

990 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

660 Ft. from W. Line

SECTION PLAT

HALL POOL

Location _____

Rig up _____

Drilling and Remarks:

*Gorham 3161**7" C 3161**98 Shots. 2920-33**2000 acil**Pump 946 oil**10% Water P&F.*

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3164

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUL 26 1939 19

S. J. LEWIS

Scout