

Map No. 1 Kansas Sec. 23 Twp. 29 R. 6Well No. 1 Leuchman FarmN.B. Garden Company

NORTH

250 Ft. from N. Line

Ft. from S. Line

Ft. from E. Line

250 Ft. from W. Line

WEST

EAST

SOUTH

1926

Date

REPORT

1/8	Location
1/4	Rigging up
1/20	
1/27	Bldg rig
3/4	Rigging up
2/10	Spudg 100'
2/17	Drlg 735'
2/24	S. D. 1010
3/5	Dlg 1505'
3/10	W. R. 10" 1675'
3/18	Slg 1940
3/25	Sandy lime 2135-40
	sho oil Run 8" 2275'
4/1	Top lime 2835 Dlg 2860
4/7	Dlg 2875'
4/14	" 3140
4/21	Abandoned 3280

11 KANSAS 23 Bother Co 29 R. 6
 Map No. Sec. Twp. R.
 Well No. 1 Deichman
 H. B. Sanders Company

Contractor

FIRST REPORTS

SECTION PLAT

250 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

250 Ft. from W. Line

0			

Location ✓ _____

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JAN 8 1926

192

CHAS. L. SHERWOOD

Scout

Map No. *K11* **KANSAS** Sec. *23* Twp. *29* R. *6*

Well No. *1* *Deichman*
H. B. Sander Company

Contractor

COMPLETED

SECTION PLAT

250

Ft. from N. Line

Ft. from S. Line

Ft. from E. Line

250

Ft. from W. Line

ABANDONED

0			

Location

Rig up

Drilling and Remarks:

*50y lino 2135-40**show oil**zap lino 2835**water 3253-63**DQW*
3280

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth *3280*

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole ☒Abandoned ☒

Date

APR 21 1926

CHAS. L. SHERWOOD

192

Scout