

36-10-22E Plotted

Company

Sec. 36 T. 10 R. 22 E

Farm Myers

No. 1

Loc. Sec SW $\frac{1}{4}$

County Leavenworth

Total Depth 597'


Comm.

Comp.

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16

Elevation

Production Abd

Figures Indicate Bottom of Formation

surface	4
lime	14
shale	18
lime	22
shale	42
lime	57
shale	60
sand	65
shale	85
lime	90
shale	94
lime	104
shale	114
lime	154
shale	156
lime	158
shale	162
lime	163
shale	173
lime	193
shale	208
lime	225
shale	260
lime	262
shale	266
lime	269
shale	271
lime	281
shale	284
lime	304
shale	310
lime	325
shale	328
lime	331
shale	341
lime BKC	349
shale	364
sandy shale	369
shale	459
red rock	463
lime	466
shale	468
sand broken	473
shale	503

lime BFS 507
 shale 587
 sand Sq 597 T. D.

HFW@ 590

Hole plugged and abandoned