

P
12/10/21

6-27-6E

OKLAHOMA PETROLEUM ✓
Hoover #1,
NW Corner SW $\frac{1}{4}$ SW $\frac{1}{4}$ 6-27-6E,
Butler County, Kansas.

<u>Formation</u>	<u>Top</u>	<u>Bottom</u>	
Soil	0	10	
Lime	10	80	
Shale	80	110	
Lime	110	160	
Shale	160	330	
Lime	330	270	
Slate	270	400	
Lime	400	480	
Shale	480	530	
Lime	530	545	
Shale	545	625	
Lime	625	655	
Shale	655	735	
Lime	735	745	
Shale	745	790	
Lime	790	820	
Shale	820	940	Water at 940
Lime	940	1000	
Slate	1000	1030	
Lime	1030	1190	
Shale	1190	1220	
Lime	1220	1290	
Slate	1290	1350	
Lime	1350	1440	
Slate	1440	1520	
Lime	1520	1540	
Shale	1540	1610	
Lime	1610	1640	
Shale	1640	1705	
Lime	1705	1745	
Lime	1745	1750	
Slate	1750	1790	
Lime	1790	1975	
Slate	1975	2115	
Lime	2115	2160	
Lime	2160	2300	Water.
Slate and shale	2300	2500	
Lime	2500	2509	
Slate	2509	2700	
Lime	2700	2715	
Slate	2715	2734	
Top of Sand	2734	2766	
Water sand	2766	2776	Hole full of water at 2766'

ABANDONED AT

2776'

1340
-1436
D