



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED

NOV 09 2010

Test Ticket

NO. 04109715024

Well Name & No. Geyer #1-26 BY: _____ Test No. 1 Date 11-6-10
 Company Phillips Exploration Co. Elevation 2378 KB 2374 GL
 Address 1601 Sagebrush Wichita, KS 67230
 Co. Rep / Geo. Tm Phillips Rig Murphy 16
 Location: Sec. 26 Twp. 10S Rge. 24W Co. Graham State KS

Interval Tested 3734-3790 Zone Tested LRC "A,B,C"
 Anchor Length 56' Drill Pipe Run 3742 Mud Wt. 90
 Top Packer Depth 3729 Drill Collars Run 0 Vis 64
 Bottom Packer Depth 3734 Wt. Pipe Run 0 WL 7.6
 Total Depth 3790 Chlorides 2800 ppm System LCM 2#

Blow Description WF- Weak building blow. Buttr to 3 inches.

EST- No Return.

FF- Weak building blow. Buttr to 2.5 inches.

FST- No Return.

Rec	Feet of	%gas	%oil	%water	%mud
<u>60</u>	<u>Mud</u>			<u>100</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 60 BHT 110 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1865

(B) First Initial Flow 32

(C) First Final Flow 45

(D) Initial Shut-In 610

(E) Second Initial Flow 46

(F) Second Final Flow 58

(G) Final Shut-In 600

(H) Final Hydrostatic 1869

Initial Open 30

Initial Shut-In 4.5

Final Flow 30

Final Shut-In 45

☒ Test 1125

☐ Jars

☒ Safety Joint 75

☐ Circ Sub

☒ Hourly Standby XZ 200

☒ Mileage 50XZ 125

☐ Sampler

☐ Straddle

☐ Shale Packer

☐ Extra Packer

☐ Extra Recorder

☐ Day Standby

☐ Accessibility

Sub Total 1525

T-On Location 0745

T-Started 1145

T-Open 1444

T-Pulled 1715

T-Out 1900

Comments

☐ Ruined Shale Packer

☐ Ruined Packer

☐ Extra Copies

Sub Total 0

Total 1525

MP/DST Disc't

Approved By _____

Our Representative

D. Rash

Trilobite Testing Inc. shall not be liable for damaged or any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



**TRILOBITE
TESTING INC.**

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
NOV 09 2010

Test Ticket

NO. 041098

BY:

Well Name & No. Geyer #1-26 Test No. Z Date 11-7-10
Company Phillips Exploration Co. Elevation 2378 KB 2374 GL
Address 1601 Sagebrush Wichita, KS 67230
Co. Rep / Geo. Jim Phillips Rig Murphy 16
Location: Sec. 26 Twp. 10S Rge. 24W Co. Graham State KS

Interval Tested 3890 - 3950 Zone Tested LKC "T, J, + K"
Anchor Length 60' Drill Pipe Run 3898 Mud Wt. 9.2
Top Packer Depth 3885 Drill Collars Run 0 Vis 65
Bottom Packer Depth 3890 Wt. Pipe Run 0 WL 7.8
Total Depth 3950 Chlorides 3000 ppm System LCM 2#

Blow Description IF - Weak building blow. Built to 1 1/4 inches.
IST - Blowback @ 18 minutes. Surging surface blow.
FF - Weak building blow. Built to 1 1/4 inches.
FST - Blowback @ 22 minutes. Surging surface blow.

Rec	Feet of	%gas	%oil	%water	%mud
<u>15</u>	<u>USOCM</u>	<u>5</u>		<u>95</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 15 BHT 109 Gravity 1125 API RW 0 @ 0 °F Chlorides 0 ppm

(A) Initial Hydrostatic <u>2006</u>	☒ Test <u>1125</u>	T-On Location <u>0745</u>
(B) First Initial Flow <u>29</u>	☐ Jars	T-Started <u>1000</u>
(C) First Final Flow <u>31</u>	☒ Safety Joint <u>75</u>	T-Open <u>1245</u>
(D) Initial Shut-In <u>112</u>	☐ Circ Sub	T-Pulled <u>1545</u>
(E) Second Initial Flow <u>32</u>	☐ Hourly Standby	T-Out <u>1730</u>
(F) Second Final Flow <u>32</u>	☒ Mileage <u>50X2 125</u>	Comments
(G) Final Shut-In <u>76</u>	☐ Sampler	
(H) Final Hydrostatic <u>1970</u>	☐ Straddle	

Initial Open <u>30</u>	☐ Shale Packer	☐ Ruined Shale Packer
Initial Shut-In <u>45</u>	☐ Extra Packer	☐ Ruined Packer
Final Flow <u>4.5</u>	☐ Extra Recorder	Extra Copies
Final Shut-In <u>60</u>	☐ Day Standby	Sub Total <u>0</u>
	☐ Accessibility	Total <u>1325</u>
	Sub Total <u>1325</u>	MP/DST Disc't

Approved By _____ Our Representative D. Rash

TriLOBITE Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.