



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 43529 15915

Well Name & No. Koblitz #8 Test No. 1 Date 6-21-11
 Company Robinowitz Oil Company Elevation 2167 KB 2160 GL
 Address 4200 E. Skelly Drive, Suite 620, Tulsa, OK, 74135
 Co. Rep / Geo. Brad Hutchison Rig Royal #2
 Location: Sec. 22 Twp. 12s Rge. 18w Co. Ellis State KS

Interval Tested 3630 - 3662 Zone Tested Arbuckle
 Anchor Length 32' Drill Pipe Run 3613 Mud Wt. 9.2
 Top Packer Depth 3625 Drill Collars Run 0 Vis 49
 Bottom Packer Depth 3630 Wt. Pipe Run 0 WL 9.6
 Total Depth 3662 Chlorides 5,000 ppm System LCM 1#

Blow Description IFP - Strong, BOB in 3 1/2 min.

ISI - Blowback Built to 3/4"

FFP - Strong, BOB in 4 min.

FSI - Blowback Built to 1/2"

Rec	Feet of	%gas	%oil	%water	%mud
<u>645</u>	<u>Free Oil</u>	<u>5</u>	<u>95</u>		
<u>90</u>	<u>Mud Cut Oil</u>		<u>75</u>		<u>25</u>

Rec Total 735 BHT 113° Gravity 27 API RW @ °F Chlorides ppm

(A) Initial Hydrostatic 1808
 (B) First Initial Flow 43
 (C) First Final Flow 191
 (D) Initial Shut-In 1134
 (E) Second Initial Flow 197
 (F) Second Final Flow 320
 (G) Final Shut-In 1133
 (H) Final Hydrostatic 1650

☒ Test 1125
☐ Jars
☐ Safety Joint
☐ Circ Sub
☐ Hourly Standby
☒ Mileage 25 RT 35
☐ Sampler
☐ Straddle
☐ Shale Packer
☐ Extra Packer
☐ Extra Recorder
☐ Day Standby
☐ Accessibility
 Sub Total 1160

T-On Location 15:36
 T-Started 17:53
 T-Open 19:09
 T-Pulled 21:09
 T-Out 23:21
 Comments

☐ Ruined Shale Packer
☐ Ruined Packer
☐ Extra Copies
 Sub Total 0
 Total 1160
 MP/DST Disc't

Initial Open 20
 Initial Shut-In 40
 Final Flow 20
 Final Shut-In 40

Approved By _____

Our Representative Jason McJannet

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.