



**TRILOBITE
TESTING INC.**

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
DEC 15 2011

Test Ticket

NO. 46334 16739

Well Name & No. Nelson Ranch 6-16 Test No. 1 Date 12-13-11
 Company Pelican Hill Elevation 2211 KB 2200 GL
 Address 1401 N El Camino Real suite 207, San Clemente CA, 92672-5932
 Co. Rep / Geo. Chris Bean Rig Integrity #7
 Location: Sec. 16 Twp. 11S Rge. 21 W Co. Trego State KS

Interval Tested 3826-3856 Zone Tested Arbuckle
 Anchor Length 30' Drill Pipe Run 3815 Mud Wt. 9.4
 Top Packer Depth 3821 Drill Collars Run — Vis 62
 Bottom Packer Depth 3826 Wt. Pipe Run — WL 5.8
 Total Depth 3856 Chlorides 2100 ppm System LCM —

Blow Description IF - Surface blow, died in 9 Min.
ISI - No blow back
FF -
FSI -

Rec	Feet of	%gas	%oil	%water	%mud
<u>1'</u>	<u>OCM</u>	<u>20</u>		<u>80</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 1' BHT 1030 Gravity — API RW — @ — °F Chlorides — ppm

(A) Initial Hydrostatic	<u>1922</u>	☒ Test	<u>1125</u>	T-On Location	<u>3:00 pm</u>
(B) First Initial Flow	<u>14</u>	☐ Jars		T-Started	<u>10:30 pm 5:24pm</u>
(C) First Final Flow	<u>16</u>	☒ Safety Joint	<u>75</u>	T-Open	<u>7:50 pm</u>
(D) Initial Shut-In	<u>453</u>	☐ Circ Sub		T-Pulled	<u>8:20 pm</u>
(E) Second Initial Flow		☐ Hourly Standby		T-Out	<u>11:18 pm</u>
(F) Second Final Flow		☒ Mileage	<u>35 X2 700ft 98</u>	Comments	
(G) Final Shut-In		☐ Sampler			
(H) Final Hydrostatic	<u>1810</u>	☐ Straddle		☐ Ruined Shale Packer	

Initial Open 15
 Initial Shut-In 15 Pull
 Final Flow —
 Final Shut-In —

☐ Shale Packer
☐ Extra Packer
☐ Extra Recorder
☐ Day Standby
☐ Accessibility

Sub Total 1298

☐ Ruined Packer
☐ Extra Copies
 Sub Total 0
 Total 1298
 MP/DST Disc't —

Approved By — Our Representative Cody Bloedorn
 Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.