



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
NOV 15 2011

Test Ticket

NO. 44873 116608

Well Name & No. Nelson 5-1L Test No. 1 Date 11-12-11
 Company Relican Hill Oil & Gas Inc Elevation 2243 KB 2233 GL
 Address 1401 N EL CAMINO Real Suite 207 SAN CLEMENTE CA 92672-5932
 Co. Rep / Geo. Marc Downing Rig INTEGRITY #7
 Location: Sec. 1L Twp. 11 S Rge. 21 W Co. Trego State KS

Interval Tested 3838-3880 Zone Tested ARBUCKLE
 Anchor Length 42'-Anchor 48'-Tail Drill Pipe Run 3782 Mud Wt. 9.4
 Top Packer Depth 3833 Drill Collars Run 59 Vis 45
 Bottom Packer Depth 3838 Wt. Pipe Run 0 WL 8.8
 Total Depth 3928 Chlorides 5500 ppm System LCM 0

Blow Description FP-Fair Blow Built to 5 1/2 IN
ISI-Weak Surface Blow Back DIED OUT IN 10 min
ISI GOOD BLOW BOB IN 5 1/4 min
FP-Weak Blow Built to 3 IN

Rec	Feet of	%gas	%oil	%water	%mud
<u>12L</u>	<u>OCm</u>	<u>15</u>	<u>85</u>	<u>85</u>	<u>85</u>
<u>31</u>	<u>40cm</u>	<u>40</u>	<u>60</u>	<u>60</u>	<u>60</u>
<u>12L</u>	<u>MCO</u>	<u>65</u>	<u>35</u>	<u>35</u>	<u>35</u>
<u>252</u>	<u>Como</u>	<u>10</u>	<u>80</u>	<u>10</u>	<u>10</u>
<u>12L-GIP</u>					

Rec Total 535 BHT 117 Gravity 31 API RW @ °F Chlorides ppm

(A) Initial Hydrostatic 1949
 (B) First Initial Flow 63
 (C) First Final Flow 81
 (D) Initial Shut-In 431
 (E) Second Initial Flow 87
 (F) Second Final Flow 233
 (G) Final Shut-In 427
 (H) Final Hydrostatic 1901

Initial Open 15
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 400

☒ Test 1125
☐ Jars
☐ Safety Joint
☐ Circ Sub
☐ Hourly Standby
☒ Mileage 68RT 95.20
☐ Sampler
☒ Straddle 600
☐ Shale Packer
☐ Extra Packer
☐ Extra Recorder
☐ Day Standby
☐ Accessibility
 Sub Total 1820.20

T-On Location 10:03
 T-Started 10:47
 T-Open 13:28
 T-Pulled 15:43
 T-Out 19:04
 Comments
☐ Ruined Shale Packer
☐ Ruined Packer
☐ Extra Copies
 Sub Total 0
 Total 1820.20
 MP/DST Disc't

Approved By _____

Our Representative Jeff Brown

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.