



# TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED  
JUN 10 2010

## Test Ticket

# No. 38599 14349

12/09

Well Name & No. Reitz #1 Test No. 1 Date 6-8-10  
 Company Staab Oil Co. Elevation 1789 KB 1794 GL  
 Address 1607 Hopewell Rd Hays KS 67601  
 Co. Rep / Geo. Randy Rig Shields  
 Location: Sec. 7 Twp. 13S Rge. 14W Co. Atchison State KS

Interval Tested 2998 - 3035 Zone Tested LRC-C-D  
 Anchor Length 37 Drill Pipe Run \_\_\_\_\_ Mud Wt. 9.1  
 Top Packer Depth 2993 Drill Collars Run \_\_\_\_\_ Vis 47  
 Bottom Packer Depth 2998 Wt. Pipe Run \_\_\_\_\_ WL 7.8  
 Total Depth 3035 Chlorides 5400 ppm System LCM 1  
 Blow Description IF - 7 1/2 in blow  
ISI - No blow  
FF - BOB in 9 min  
FSI - 3 1/2 in blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>120</u>	<u>SOWCM</u>		<u>5</u>	<u>45</u>	<u>50</u>
<u>60</u>	<u>GSMCO</u>	<u>40</u>	<u>50</u>	<u>5</u>	<u>5</u>
<u>60</u>	<u>EMCO</u>	<u>20</u>	<u>65</u>		<u>15</u>
<u>60</u>	<u>SOCM</u>		<u>5</u>		<u>95</u>
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 300 BHT 99 Gravity \_\_\_\_\_ API RW \_\_\_\_\_ @ \_\_\_\_\_ °F Chlorides 93000 ppm  
 (A) Initial Hydrostatic 1444  Test 1125 T-On Location 9:00  
 (B) First Initial Flow 17  Jars \_\_\_\_\_ T-Started 10:05  
 (C) First Final Flow 29  Safety Joint \_\_\_\_\_ T-Open 12:56  
 (D) Initial Shut-In 947  Circ Sub \_\_\_\_\_ T-Pulled 16:31  
 (E) Second Initial Flow 37  Hourly Standby \_\_\_\_\_ T-Out 18:30  
 (F) Second Final Flow 118  Mileage 30x2 x 2=150 Comments pick up tools  
 (G) Final Shut-In 915  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic 1428  Straddle \_\_\_\_\_  
 Shale Packer \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Extra Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Extra Recorder \_\_\_\_\_  Extra Copies \_\_\_\_\_  
 Day Standby \_\_\_\_\_ Sub Total 0  
 Accessibility \_\_\_\_\_ Total 1275  
 Sub Total 1275

Approved By \_\_\_\_\_ Our Representative [Signature]

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.