

Map No. Sec. Twp. R.

Well No. Farm


..... Company

..... Ft. from N. Line

..... Ft. from S. Line

..... Ft. from E. Line

..... Ft. from W. Line



1918 Elev. 1421

Date

REPORT

Gypsy Roads

5/24

abd T.O. 2630'

Butler
K14 KANSAS MAP NO. _____ SEC. 13 TWP. 25S 4E R. _____

WELL NO. 1 - Carlisle

Acas Co. COMPANY

CONTRACTOR

ABANDONED

SECTION PLAT

| | | | |
|--|--|--|--|
| | | | |
| | | | |
| | | | |
| | | | |

_____ FT. FROM N. LINE

_____ FT. FROM S. LINE

_____ FT. FROM E. LINE

_____ FT. FROM W. LINE

LOCATION _____

RIG UP _____

DRILLING AND REMARKS:

RECORD

CASED _____ IN., _____ FT.

SAND _____

GAS _____

OIL _____

TOTAL DEPTH 7630

PRODUCTION

1ST 24 HRS. NAT. _____

1ST 24 HRS. AFTER SHOT _____

GAS _____ CU. FT.

DRY HOLE _____

ABANDONED

DATE 5-24-18 192 _____ SCOUT