Home Office: Wichita, Kansas 67201
P. O. Box 1599 (316) 838-0601

Company K.R.M. Petroleum Corp. Lease & Well No. Price #1

Elevation - Formation - Effective Pay - Ft. Ticket No. 23077

Date 8-2-77 Sec. 6 Twp. 28S Range 20W County Kiowa State Kansas

Test Approved by J.C. Simmons Western Representative Bill Hager

Formation Test No. 4 O.K. - Misrun X Interval Tested From 4395' to 4440' Total Depth 4440'

Size Main Hole 7 7/8 Rat Hole - Conv. X B.T. - Damaged - Yes X No Conv. - B.T. X Damaged - Yes X

Top Packer Depth - Ft. Size 6 3/4 Bottom Packer Depth - Ft. Size 6 3/4

Straddle Yes Conv. X B.T. - Damaged X Yes - No Packer Depth - Ft. Size 6 3/4

Tool Size 5½OD Tool Joint Size 4½FH Anchor Length 45 Ft. Size 5½OD Surface Choke Size 3/4 In. Bottom Choke Size 3/4

RECORDERS Depth - Ft. Clock No. 4763 Depth - Ft. Clock No. 9726

Top Make Kuster Cap. 4150 No. 2604 Inside Outside Bottom Make Kuster Cap. 4150 No. 2606 Inside Outside

Below Straddle: Depth - Rec. No. 52 Clock No. 44 Inside Outside Depth - Ft. Rec. No. - Clock No. - Inside Outside

Time Set Packer M

Tool Open I.F.P. From M. to M Hr. Min. From (B) P.S.I. To (C) P.

Tool Closed I.C.I.P. From M. to M Hr. Min (D) P.

Tool Open F.F.P. From M. to M Hr. Min. From (E) P.S.I. To (F) P.

Tool Closed F.C.I.P. From M. to M Hr. Min. (G) P.

Initial Hydrostatic Pressure (A) P.S.I. Final Hydrostatic Pressure (H) P.S.I. Maximum Temp.

## INFORMATION

BLOW Misrun

Did Well Flow - Yes X No Recovery Total Ft. Misrun

Reversed Out - Yes X No Mud Type Premix Viscosity 49 Weight 9.3 Water Loss 9.9 cc. Chlorides 9000PPM

EXTRA EQUIPMENT: Type Circ. Sub Pin Safety Joint Yes Jars: Size 4½OD In. Make W.T.C. Ser. No. 408


Dual Packer Yes Did Packers Hold? - Did Tool Plug? - Where? -


DRILLING CONTRACTOR Xplor Drlg. Inc. Length Drill Pipe? - Ft. I.D. Drill Pipe 3 In. Tool Joint Size 4½FH


Length Weight Pipe - Ft. I.D. Weight Pipe - In. Tool Joint Size - In. Length Drill Collars 278 Ft. I.D. Drill Collars 2 1/4


Tool Joint Size 4½XH In. Length D.S.T. Tool 80 Ft.

Remarks: Could not get to testing depth, went to 2636'.


IKH# 23077
I


IKH# 23077
Below Straddle


IK# 23077
I


IK# 23077
Below Straddle