

Map No. _____ Sec. 13 Twp. 26 R. 4
 Well No. 19 Blair Farm _____
 _____ Empire Company

NORTH



SOUTH

Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD

PRODUCTION

Cased _____ in. _____ ft.

1st 24 hrs. Nat. _____

Sand _____

1st 24 hrs. after shot _____

Gas _____


Gas _____ cu. ft.

Oil _____

Dry Hole _____

Total Depth _____

Abandoned _____

Map No. _____ Sec. 13 Twp. 26 R. 4Well No. 19 Blair Farm _____Empire G. F. Co. Company __________
Contractor _____MW Quarter _____660 Ft. from N. Line_____
Ft. from S. Line_____
Ft. from E. Line200 Ft. from W. LineDate 1/19

REPORT

10/11Rig10/177367-7381' Gobbs.

COMPLETED

Map No. _____ Sec. 13 Twp. 26 R. 4

Well No. 19 Blair
Empire

Compan _____

Contractor _____

NORTH

WEST

EAST

FIRST REPORT

SOUTH

660 N

200 W

Location _____

Rig up ☒

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

7/2 1919

Pyle Scout

Map No. K14 Sec. 13 Twp. 26 R. 4Well No. 19 BlairEmpire Company

Contractor

SECTION PLAT

660 Ft. from N. Line

Ft. from S. Line

Ft. from E. Line

200 Ft. from W. Line

0			

Location

Rig up

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand 2367 - 2381

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. 90 bbls

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/27 1919

Pyle

Scout