

18-11-23E Plotted

Sec. 18 T. 11 R. 23E
 Loc. NEc NW $\frac{1}{4}$
 County Wyandotte

Company

Farm Bachnick

No. 1

Total Depth 578'


Comm.

Comp.

Shot or Treated

Contractor

Issued



Casing	
20 in.	10 in.
15 1/2	8 1/4
12 1/2	6 5/8 393'
13 3/8	5 3/16
	4 7/8 542'

Elevation

Production Dry and Abandoned

Figures Indicate Bottom of Formation

surface	33		
lime	43		Sand 417
shale	45		shale 429
sand	55	HFW	lime 435
lime	57		sand 449
shale	75		shale 457
lime	112		lime 460
shale	115		shale 470
lime	121		sand 474
shale	125		shale 480
lime	127		lime 484
shale	137		coal 488
lime	147		sandy shale 500
shale	156		lime 506
lime	164		shale 521
shale	175		lime 523
lime	177		shale 530
shale	180		lime 532
lime	182		shale 536
shale	185		lime 542
lime	189		shale 572
shale	191		sand 578 T.D. HFW
lime	195		
shale	198		
lime	213		
shale	219		
lime	238		
shale	240		
lime	243		
shale	246		
lime	254		
shale	296	SG	
sandy broken	364		
shale	384		
lime	386		
sand	389		
shale	393		
lime	398		
shale	400		
red rock	404		
lime	409		