

20-11-23E

Plotted

Bonner Springs Oil & Gas Co.

Sec. 20 T. 11 R. 23E

Farm Twist

No. 7

Loc. SWc NE

SW SE NE

Borden's map 9/9/30

County Wyndotte County

Total Depth


Comm.

Shot or Treated

Contractor

Issued

Comp. 1908



Casing

20 in.

15 1/2

12 1/2

13 3/8

10 in.

8 1/4

6 5/8

5 3/16

Elevation Above sea level 966.23

Production Well is still a good producer and is a very dry well.

Figures Indicate Bottom of Formation

soil	1	red rock	432
lime	31	sand	439
blue shale	41	shale lgt	444
lime	51	red rock	453
lime shells	66	sand little gas	473
shale lgt	69	shale lgt	490
lime	79	lime	495
shale lgt	82	shale lgt	505
lime	102	shale dk	513
shale lgt	107	lime	516
lime	151	slate blk wtr	518
shale dk	156	lime shells	546
lime	159	shale dk	555
slate blk	162	lime shells	562
lime dk	167	shale lgt	580
shale dk	170	gas sand	591
lime wh	195		
shale dk	200		
lime lgt	210		
shale lgt	225		
lime	230		
slate blk gas	233		
lime	243		
shale lgt	246		
lime	255		
shale dk	259		
lime	284		
slate blk wtr	289		
lime	310		
shale lgt	314		
red rock	317		
shale lgt	345		
lime	349		
shale lgt	379		
shale blue	404		
shale lgt	409		
sand wh	424		
shale blue	428		

9-10-30

This well is not producing now, tho Mr. Bohart reports it would produce if cleaned out.

J.L.B.