

23-12-23E

Company

Sec. 23 T. 2 R. 23
Loc. SW NW SW

Farm Kampmire

No. 2

Total Depth 522'

County Johnson


Comm.

Comp. 12-5-24

Shot or Treated

Contractor

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	
12 1-2	6 5-8	397'
13 3-8	5 3-16	

Elevation 856

Production

Figures Indicate Bottom of Formation

Surface	4'
Lime	10
Light shale	22
Lime	35
Dark shale	39
Blue shale	43
Lime	47
Blue shale	60
Lime	63
Dark shale	65
Lime Eatie	81
Dark shale	84
Lime	99
Black slate gas	105
Lime	125
Black slate	129
Lime	131
Black dirt	134
Lime <i>Hexha</i>	143
White shale	149
Dark gas <i>Knobtown</i>	205
Blue shale	270
Red rock	278
White shale	315
Lime	320
Dark shale	323
Lime	326
Dark shale	332
Lime	338
White sandy shale	343
Dark shale	354
Lime <i>FT Scott</i>	358
Sand gas	375
Black shale	385
White shale	405
Black slate	410
White shale	450
Dark shale	467
Sand gas <i>Squirrel</i>	522
77' of Anchor	
Cage at 484	