

Company

Sec. 25

T. 12

R. 23

25-12-23E

Loc.

C SW $\frac{1}{4}$ SW $\frac{1}{4}$

Farm

Rose

No.

6

Total Depth 511'

County

Johnson

Comm.


Comp.

Shot or Treated

Contractor

Earl Smith

Issued



Casing

20 in.

10 in.

15 1-2

8 1-4

Drive Pipe

25'

Elevation

12 1-2

6 5-8

290'

Production

13 3-8

5 3-16

Figures Indicate Bottom of Formation

Soil	4'
Yellow clay	9
Gravel	15
Shale blue	17
Lime	24
Shale white	27
Shale dark	32
Shale white	35
Lime	42
Shale blue	58
Lime	61
Shale blue	68
Lime sharp	95
Shale dark	100
Lime water	120
Slate black & gas	124
Lime	127
Shale blue	131
Lime	137
Shale white	147
Sand	152
Shale dark	162
Sand	240
Shale white	270
Red rock	275
Shale white	285
Red rock	289
Shale white	299
Sand gas little water	324
Lime	326

Shale dark	329
Lime	331
Shale light	338
Lime	342
Sand	349
Shale blue	362
Lime	366
Shale dark	370
Sand	380
Lime sandy	385
Red Rock	395
Shale white	398
Lime	400
Slate black	405
Shale light	409
Lime	411
Shale dark	420
Shale white	440
Shale light	462
Shale dark	477
Sand & gas	489
Shale dark	493
Sand	497
Shale dark	511

Figures Indicate Bottom of Formation