

Company

NE $\frac{1}{4}$ SW $\frac{1}{4}$ NE $\frac{1}{4}$

Sec. 26

T. 12

R. 23

Farm Herning

No. 3

County Johnson

Total Depth 520


Comm. 6-25-26

Comp. 6-28-26

Shot or Treated

Contractor Earl Smith

Issued



Casing

20 in.	10 in.	
15 1-2	8 1-4	Drive pipe 19'
12 1-2	6 5-8	450'
13 3-8	5 3-16	

Elevation

 Production Open Flow Test 1,500,000
 Rock Pressure 117 lbs.

Figures Indicate Bottom of Formation

Surface	12'	White shale	425
Shell lime	20	Dark shale	440
Black shale	23	Light shale	450
Gritty shale	28	Dark shale	477
Lime	40	Sand(gas)	520
Blue shale	60		
Lime	62	Cage at	497'
Blue shale	67	6 $\frac{1}{4}$ casing in hole	390
Eatie lime	95		
Black shale	100		
Lime	122		
Black shale(gas)	125		
Lime	127		
Dark shale	127		
Dark shale	129		
Lime	137		
White shale	159		
Blue shale	250		
Light shale	265		
Dark shale	270		
Red rock	272		
Lime	274		
Light shale	309		
Lime	313		
Dark shale	323		
Lime	329		
Light shale	341		
Dark shale	350		
Lime	354		
Black shale	359		
Lime	363		
Sandy shale	371		
Lime	373		
Red rock	385		
Black shale	390		
Blue shale	410		
Sand(gas)	417		