

31-12-25E  
 SEC SW SE  
 Davis - North Place El 918

14	Soil Clay	14
11	Lime	25
2	Shale	27 Water
2	Lime	29
14	Shale	43 Gray Muddy
12	Lime	55
10	Shale	65 Sandy
24	Lime	89
19	Shale	108
2	Lime	110
3	Shale	113 Sandy
28	Lime	141 (? Winterset)
7	B. Slate	148

2nd drilled to 125 only

3FL SW NW 6-13-25E  
 SEL SW NW 6-13-25E  
 Davis - West Place El 925?

6	Earth	6
14	Lime	20
15	Shale	35
11	Lime	46
10	Shale	56
17	Lime	73
18	Shale	91
4	Lime	95
29	Lime	124 )
1	Shale	125 ) Winterset
4	Lime	129 )
7	Slate	136 Water 151
19	Lime	155 B.F.
3	Slate	158 Salty Water
18	Lime	176 Hertha
36	Shale	212

No Knobtown  
 Near SW NE 6-13-25E 925  
 Davis No. 3 near Barn El 908?

29	Soil & Clay	29
9	Lime	38 (Bolders water)
24	Shale	62
6	Lime	68
9	Shale	77
11	Lime	88
24	Shale	112
2	Lime	114
1	Shale	115 B. Mole

CEL SW NE 6-13-25E  
 CEL SW NE NO #  
 Davis - North of barn in hollow  
 El 898

11	Earth	10
11	Lime	22 Broken & Shaley
10	Shale	32
2	Lime	34
2	Shale	36
7	Lime	43 Water 40'
6	Shale	49
16	Lime	65 Water @ 60
17	Shale	82 1' break at 60
2	Lime	84
2	Shale	86
3	Lime	89
1	Shale	90
10	Lime	100 )
20	Lime	120 ) Winterset
7	Dark Shale	127

Well drilled by Barton.  
 Depth 161 finished in black  
 slate - presumably below  
 Winterset. In S. 2 of SW 1/4 Sec.  
 31 T. 12 R 25 E - El in 952  
 and possibly H base could be  
 740-744. Either Barton or owner  
 Ralph T. Edger, 3469 E. 62nd  
 has log. Looks like might be  
 start of another structure  
 unless connection with one SE.

mud rock  
 Blue shale 45-47  
 Hard lime 74  
 Shale 84  
 lime 109  
 shale 114  
 lime 126  
 granitic rock 150.  
 5 Winterset 155

909  
 171  
 733