

Company Vaughn

Farm Vaughn

Total Depth 295'

Comm. 4-29-36

Shot or Treated

Contractor

Issued

No.

Comp. 5-6-36


Sec. ~~23~~ T. 12 R. 25E

Loc. 75th & Sunset Drive

~~CSL NW~~

NW SW

County Johnson



Elevation

← sunset Dr from 75 $\frac{1}{4}$ 79th
1055 $\pm$ 5

Production

Figures Indicate Bottom of Formation

Soil & clay-yellow soft	9'
Lightly lime-gray very hard	21
Shale soft gray	61
Lime hard	65 <i>Wyd</i>
Shale gray soft	135 <i>Lone</i>
Lime gray hard	152 <i>Fole</i>
Shale gray soft	160
Lime gray hard	163
Shale gray soft	168
Sandy lime-medium hard	170 ✓
Shale soft gray	175
Lime hard gray-	184
Shale dark soft	190
Shale gray soft	207
Lime gray hard	215
Shale gray soft	220
Lime gray bad	222
Shale gray soft	226
Lime gray hard	240 ✓
Shale gray soft	241
Lime hard gray	255
Shale & slate dark soft	260
Lime gray hard	281 ✓
Slate black soft	284 water salty
Lime gray hard	287
Shale dark soft	291 water stands 200'
Lime gray hard	295 T. D.