

10-13-23E

Company

Sec. 107 E 131 N 231

Loc. CSE NE1

Farm Hundley

No. 1

Total Depth


County Johnson

Comm. 2/13/26

Comp.

Shot or Treated

Contractor



CASINO

20 in.	10 in.	
15 1/2	8 1/4	15'
12 1/2	6 5/8	
13 3/4	5 3/16	

Elevation

Production

Figures Indicate Bottom of Formations.

surface	15	lime	542
lime	18	shale dk	550
shale wh	23	shale lgt	555
lime	42	lime	561
shale lgt	44	shale lgt	578
shale blk	48	lime	582
lime	57	shale dk	597
shale wh	63	lime some wtr	600
lime	90	shale wh	605
shale blue	105	red rock	612
lime	113	shale lgt	620
shale	115	SIM	
lime	118	slate blk	622
shale	121	shale dk	652
lime	128	shale lgt	682
shale	130	lime	684
lime	144	shale dk	691
shale	147	sand & gas	701
lime	155	shale dk	713
shale blue	202	sand oil	727
lime wh	212	shale dk	728
shale blue	240	Plugged	709
lime	256		
shale blk	264		
lime	290		
shale dk	293		
lime	295		
shale	298		
lime	320		
shale	323		
lime	342		
slate blk	344		
lime	346		
slate blk	351		
lime	359		
shale wh	470		
lime	472		
shale wh	537		