

Company

Farm P. A. Sexton

No. 1

Total Depth 644'

Comm. 6-28-24

Shot or Treated

Contractor Earl Smith

Issued


Comp.

Sec. 34 T. 13

R. 23E

Loc. 10 A. in NE¹₄

County Johnson



Casing

20 in.	10 in.
15 1-2	8 1-4
12 1-2	6 5-8
13 3-8	5 3-16

Elevation

Production

Figures Indicate Bottom of Formation

Surface	7'	Sandy shale	368 ✓
Lime	21	Blue shale	422
Dark shale	30	White shale	428
Dark rock	36 ✓	Sand	433
Light shale	46	White shale	453
Lime	52	Red rock	459 ✓
Blue shale	57	White shale	487
Lime	78	Blue shale	491
Blue shale	86	Lime	498
Lime Fatie	108	Dark shale	502
Light shale	118	Lime	506
Blue shale	148	White shale	512
Lime	156	Lime	518
Dark shale	166	Light shale	526
White shale	177	Dark shale	535
Lime	184	Lime	538
Blue shale	187	Black slate - water	544
Lime	197	Light shale	547
Blue shale	223	Lime	553 ✓
	225	Red rock	563 ✓
Dark shale	227	Dark shale	580
Lime	231	Light shale	595
Dark shale	235	L. sandy shale	620
Lime	247	Blue shale	644
Dark shale	250		
Lime	265		
Black slate	270		
Lime	272		
Black shale	275		
Lime	290		
Black slate	294		
Lime	296		
Dark shale	300		
Lime	309		
White shale	312		
Red rock	316		
White shale	326		
Blue shale	354		

Bottom of hole.