


0 v
24-14-19E

Location SE cor of SE 1/4



Sec. 24, T. 14, R. 19^E

Farm Pardue

No. 2
(or 1)

County Douglas

Company _____

Commenced _____ Completed _____

Elevation _____ T.D. 1235' I. P. Dry and abn.

PLOTTED LOG ONLY

Plotted *Chapman*
 24-14-19E
 Plotted.
 E.M.

Company

Sec. 24 T. 14 R. 19 E
 Loc. SEc SE

Farm Pardee

No. 1


Total Depth 1238

County Douglas

Comm.

Comp.

Shot or Treated



Contractor

Issued

Casing

20 in.

10 in.

15 1/2

8 1/4

Elevation

12 1/2

6 5/8

Production

13 3/8

5 3/16

Figures Indicate Bottom of Formation

soil and clay

18

lime

655

shale

1106

sand

21

shale

658

lime shells

1115

gravel

23

lime

660

shale light

1131

shale

50

shale light

680

blk shale

1161

lime

51

dark shale

790

shale white

1181

black shale

53

brkn sand

800

dk shale & lime

1200

red rock

55

dark shale

810

light shale

1204

white shab

90

light shale

820

sandy shale

1217

dark shale

102

dark shale

845

sand Slit wtr

1238

brkn lime

120

lime

865

Total Depth.

dark shale

145

shale

868

brkn lime

160

lime

873

lime

165

dark shale

876

shale

290

lime

878

lime

296

shale

880

shale

298

lime

883

lime

318

shale

885

shale

324

lime

892

lime

336

shale

900

shale white

338

dark shale

908

lime

374

lime

910

green sand

394

black shale

914

lime

425

dark shale

922

shale

465

lime

926

lime

497

shale

929

shale

505

lime

933

lime

526

shale white

972

dark shale

550

lime

973

lime

562

blue shale

980

dark shale

575

sand

988

lime

585

brkn sand

995

shale

586

shale

1023

lime

603

lime

1026

dark shale

610

shale

1039

lime

640

sand

1050

shale dark

642

lime

1052