

Company Hughes

Farm E.J. Selzer

Total Depth ?

Comm.

Shot or Treated

Contractor

Issued

Casing

20 in.	10 in
15 1/2	8 1/4
12 1/2	6 5/8
13 3/8	5 3/16


No.

20-14-21E
Sec. 20 T.14 R. 21E

Loc. SE SW SW

County Douglas

Comp. Not known, but between
1960 and 1966.



Elevation

Production

Figures Indicate Bottom of Formation

Surface	2	2
Sandstone	4	6
Shale	8	14 sdy
Shale	130	144
Lime	26	170
Shale	6	176
Lime	9	185
Shale	7	192
Lime	53	245
Shale	55	300
Lime	13	313
Shale	7	320
Lime	18	338
Shale	16	354
Lime	10	364
Shale	32	386
Lime	13	409
Shale	8	417
Lime	28	445 Winterset
Shale	5	450
Lime	25	475 Bethany Falls
Shale	6	481
Lime	3	484
Shale	4	488
Lime	10	498 <i>Herttha</i> slm
Shale	4	502
Sand	3	505 Knobtown
Shale	132	637
Lime	3	640
Shale	27	667
Lime	7	674
Shale	5	679

T.D. ?