Farm E. John Selzer

No. 2

Sec. 20 T. 14 R. 21E Loc. NENE SW County Douglas

Total Depth ?
Comm.
Shot or Treated
Contractor
Issued

Comp. Not known, but between 1960 and 1966.

0	

Casing

20 in. 10 in 15 1/2 8 1/4 12 1/2 6 5/8 13 3/8 5 3/16

Elevation

Production

Figures Indicate Bottom of Formation

Surface	2	2
Shale	8	10 sdy
Shale	128	138
Lime	26	164
Shale	7	171
Lime	9	180
Shale	6	186
Lime	57	243
Shale	48	291
Lime	14	305
Shale	9	314
Lime	18	332
Shale	16	348
Lime	10	358
Shale	30	388
Lime	8	396
Shale	5	401
Lime	1	402
Shale	10	412

This well was drilled to Squirrel sand (no shows) T.D. ?